

# Contents

<b>Preface</b>	page v
<b>1 INTRODUCTION</b>	
1.1 Examples and definitions	1
1.2 Where inspection?	4
1.3 Classification of inspection plans	5
1.4 Flow chart for acceptance inspection	8
<b>2 ACCEPTANCE SAMPLING: BASIC IDEAS</b>	
2.1 The OC-curve	12
2.2 The average run length	15
2.3 The process curve	16
2.4 Methods of choosing sampling plans	19
2.5 Defence sampling schemes	24
2.6 Decision theory schemes	26
2.7 A simple semi-economic scheme	28
2.8 Dodge and Romig's schemes	29
2.9 Other schemes	31
2.10 Discussion	32
2.11 Inspection by variables	34
<b>3 CONTROL CHARTS</b>	
3.1 Statistical quality control	44
3.2 Simple control charts for variables	45
3.3 Properties of the charts	52
3.4 The economic design of $\bar{x}$ -charts	58
3.5 Specifications for variables	62
3.6 Control charts for qualitative data	67
3.7 Other types of chart for variables	70
<b>4 CUMULATIVE SUM CHARTS</b>	
4.1 Introduction	73

<b>viii</b>	<b>CONTENTS</b>
4.2 Decision rules	81
4.3 Properties of the decision rules	88
4.4 Theory of the decision interval scheme	91
4.5 Use of nomogram to design decision interval schemes	97
4.6 The economic design of CUSUM control charts	100
4.7 Estimation from CUSUM charts	102
4.8 Other CUSUM charts	104
4.9 Conclusions	105
<b>5 CONTINUOUS SAMPLING PLANS</b>	
5.1 Basic description and aims	106
5.2 CSP-1 and the AOQL criterion	107
5.3 Theory of CSP-1	111
5.4 The AEDL criterion	112
5.5 Decision-theory approach to CSP-1	114
5.6 Modifications to CSP-1	116
5.7 Process trouble shooting	119
5.8 Adaptive control	120
5.9 Use of CUSUM techniques	123
<b>Papers and books for further reading</b>	126
<b>Appendix I. Theoretical models for industrial processes</b>	127
<b>Appendix II. Statistical tables</b>	129
<b>References</b>	137
<b>Index</b>	145