Contents

CHAPTER 1
Quality Improvement in the Modern Business Environment 1

Chapter Overview and Learning Objectives 1
1-1 The Meaning of Quality and Quality Improvement 2
1-1.1 Dimensions of Quality 2
1-1.2 Quality Engineering Terminology 6
1-2 A Brief History of Quality Control and Improvement 8
1-3 Statistical Methods for Quality Control and Improvement 11
1-4 Management Aspects of Quality Improvement 15
1-4.1 Quality Philosophy and Management Strategies 16
1-4.2 The Link Between Quality and Productivity 27
1-4.3 Quality Costs 28
1-4.4 Legal Aspects of Quality 33
1-4.5 Implementing Quality Improvement 35

PART I
Statistical Methods Useful in Quality Control and Improvement 39

CHAPTER 2
Modeling Process Quality 41

Chapter Overview and Learning Objectives 41
2-1 Describing Variation 42
2-1.1 The Stem-and-Leaf Plot 42
2-1.2 The Histogram 44
2-1.3 Numerical Summary of Data 47
2-1.4 The Box Plot 50
2-1.5 Probability Distributions 51

2-2 Important Discrete Distributions **55**
2-2.1 The Hypergeometric Distribution **55**
2-2.2 The Binomial Distribution **57**
2-2.3 The Poisson Distribution **58**
2-2.4 The Pascal and Related Distributions **59**
2-3 Important Continuous Distributions **61**
2-3.1 The Normal Distribution **61**
2-3.2 The Lognormal Distribution **66**
2-3.3 The Exponential Distribution **69**
2-3.4 The Gamma Distribution **70**
2-3.5 The Weibull Distribution **72**
2-4 Probability Plots **74**
2-4.1 Normal Probability Plots **74**
2-4.2 Other Probability Plots **76**
2-5 Some Useful Approximations **77**
2-5.1 The Binomial Approximation to the Hypergeometric **77**
2-5.2 The Poisson Approximation to the Binomial **78**
2-5.3 The Normal Approximation to the Binomial **78**
2-5.4 Comments on Approximations **79**

CHAPTER 3
Inferences about Process Quality **86**

Chapter Overview and Learning Objectives **86**
3-1 Statistics and Sampling Distributions **87**
3-1.1 Sampling from a Normal Distribution **88**
3-1.2 Sampling from a Bernoulli Distribution **92**
3-1.3 Sampling from a Poisson Distribution **92**
3-2 Point Estimation of Process Parameters **93**
3-3 Statistical Inference for a Single Sample **96**
3-3.1 Inference on the Mean of a Population, Variance Known **97**
3-3.2 The Use of *P*-Values for Hypothesis Testing **100**

3-3.3 Inference on the Mean of a Normal Distribution, Variance Unknown **101**
3-3.4 Inference on the Variance of a Normal Distribution **105**
3-3.5 Inference on a Population Proportion **107**
3-3.6 The Probability of Type II Error and Sample Size Decisions **109**
3-4 Statistical Inference for Two Samples **112**
3-4.1 Inference for a Difference in Means, Variances Known **113**
3-4.2 Inference for a Difference in Means of Two Normal Distributions, Variances Unknown **116**
3-4.3 Inference on the Variances of Two Normal Distributions **125**
3-4.4 Inference on Two Population Proportions **126**
3-5 What If There Are More Than Two Populations? The Analysis of Variance **128**
3-5.1 An Example **128**
3-5.2 The Analysis of Variance **130**
3-5.3 Checking Assumptions: Residual Analysis **137**

PART II
Basic Methods of Statistical Process Control and Capability Analysis **145**

CHAPTER 4
Methods and Philosophy of Statistical Process Control **147**

Chapter Overview and Learning Objectives **147**
4-1 Introduction **148**
4-2 Chance and Assignable Causes of Quality Variation **148**
4-3 Statistical Basis of the Control Chart **150**
4-3.1 Basic Principles 150
4-3.2 Choice of Control Limits **158**
4-3.3 Sample Size and Sampling Frequency **160**
4-3.4 Rational Subgroups **162**
4-3.5 Analysis of Patterns on Control Charts **164**
4-3.6 Discussion of Sensitizing Rules for Control Charts **166**
4-3.7 Phase I and Phase II of Control Chart Application **168**

4-4 The Rest of the "Magnificent Seven" **169**
4-5 Implementing SPC **175**
4-6 An Application of SPC **176**
4-7 Nonmanufacturing Applications of Statistical Process Control **183**

CHAPTER 5
Control Charts for Variables **194**

Chapter Overview and Learning Objectives **194**
5-1 Introduction **195**
5-2 Control Charts for $\bar{x}$ and R **196**
5-2.1 Statistical Basis of the Charts **196**
5-2.2 Development and Use of $\bar{x}$ and R Charts **200**
5-2.3 Charts Based on Standard Values **212**
5-2.4 Interpretation of $\bar{x}$ and R Charts **214**
5-2.5 The Effect of Nonnormality on $\bar{x}$ and R Charts **216**
5-2.6 The Operating-Characteristic Function **217**
5-2.7 The Average Run Length for the $\bar{x}$ Chart **220**
5-3 Control Charts for $\bar{x}$ and s **222**
5-3.1 Construction and Operation of $\bar{x}$ and s Charts **222**
5-3.2 The $\bar{x}$ and s Control Charts with Variable Sample Size **227**
5-3.3 The s^2 Control Chart **231**
5-4 The Shewhart Control Chart for Individual Measurements **231**
5-5 Summary of Procedures for $\bar{x}$, R, and s Charts **242**
5-6 Applications of Variables Control Charts **243**

CHAPTER 6
Control Charts for Attributes **265**

Chapter Overview and Learning Objectives **265**
6-1 Introduction **266**
6-2 The Control Chart for Fraction Nonconforming **266**
6-2.1 Development and Operation of the Control Chart **268**
6-2.2 Variable Sample Size **280**
6-2.3 Nonmanufacturing Applications **284**
6-2.4 The Operating-Characteristic Function and Average Run Length Calculations **286**
6-3 Control Charts for Nonconformities (Defects) **288**

6-3.1 Procedures with Constant Sample Size **289**
6-3.2 Procedures with Variable Sample Size **298**
6-3.3 Demerit Systems **300**
6-3.4 The Operating-Characteristic Function **302**
6-3.5 Dealing with Low Defect Levels **304**
6-3.6 Nonmanufacturing Applications **306**
6-4 Choice Between Attributes and Variables Control Charts **306**
6-5 Guidelines for Implementing Control Charts **311**

CHAPTER 7
Process and Measurement System Capability Analysis **326**

Chapter Overview and Learning Objectives **326**
7-1 Introduction **327**
7-2 Process Capability Analysis Using a Histogram or a Probability Plot **329**
7-2.1 Using the Histogram **329**
7-2.2 Probability Plotting **331**
7-3 Process Capability Ratios **333**
7-3.1 Use and Interpretation of C_p **333**
7-3.2 Process Capability Ratio for an Off-Center Process **338**
7-3.3 Normality and the Process Capability Ratio **339**
7-3.4 More about Process Centering **341**
7-3.5 Confidence Intervals and Tests on Process Capability Ratios **343**
7-4 Process Capability Analysis Using a Control Chart **349**
7-5 Process Capability Analysis Using Designed Experiments **351**
7-6 Gauge and Measurement System Capability Studies **352**
7-6.1 Basic Concepts of Gauge Capability **352**
7-6.2 The Analysis of Variance Method **358**
7-6.3 Confidence Intervals in Gauge R & R Studies **362**
7-6.4 False Defectives and Passed Defectives **364**
7-7 Setting Specification Limits on Discrete Components **367**
7-7.1 Linear Combinations **367**
7-7.2 Nonlinear Combinations **371**

7-8 Estimating the Natural Tolerance Limits of a Process **374**
7-8.1 Tolerance Limits Based on the Normal Distribution **374**
7-8.2 Nonparametric Tolerance Limits **375**

PART III
Other Statistical Process-Monitoring and Control Techniques **383**

CHAPTER 8
Cumulative Sum and Exponentially Weighted Moving Average Control Charts **385**

Chapter Overview and Learning Objectives **385**
8-1 The Cumulative Sum Control Chart **386**
8-1.1 Basic Principles: The Cusum Control Chart for Monitoring the Process Mean **386**
8-1.2 The Tabular or Algorithmic Cusum for Monitoring the Process Mean **390**
8-1.3 Recommendations for Cusum Design **395**
8-1.4 The Standardized Cusum **397**
8-1.5 Improving Cusum Responsiveness for Large Shifts **398**
8-1.6 The Fast Initial Response or Headstart Feature **398**
8-1.7 One-Sided Cusums **400**
8-1.8 A Cusum for Monitoring Process Variability **401**
8-1.9 Rational Subgroups **402**
8-1.10 Cusums for Other Sample Statistics **402**
8-1.11 The V-Mask Procedure **403**
8-2 The Exponentially Weighted Moving Average Control Chart **405**
8-2.1 The Exponentially Weighted Moving Average Control Chart for Monitoring the Process Mean **406**
8-2.2 Design of an EWMA Control Chart **411**
8-2.3 Robustness of the EWMA to Nonnormality **412**
8-2.4 Rational Subgroups **413**
8-2.5 Extensions of the EWMA **413**
8-3 The Moving Average Control Chart **417**

CHAPTER 9

Other Univariate Statistical Process Monitoring and Control Techniques **423**

Chapter Overview and Learning Objectives **423**
9-1 Statistical Process Control for Short Production Runs **424**
9-1.1 $\bar{x}$ and R Charts for Short Production Runs **425**
9-1.2 Attributes Control Charts for Short Production Runs **427**
9-1.3 Other Methods **428**
9-2 Modified and Acceptance Control Charts **429**
9-2.1 Modified Control Limits for the $\bar{x}$ Chart **429**
9-2.2 Acceptance Control Charts **433**
9-3 Control Charts for Multiple-Stream Processes **434**
9-3.1 Multiple-Stream Processes **434**
9-3.2 Group Control Charts **434**
9-3.3 Other Approaches **437**
9-4 SPC With Autocorrelated Process Data **438**
9-4.1 Sources and Effects of Autocorrelation in Process Data **438**
9-4.2 Model-Based Approaches **443**
9-4.3 A Model-Free Approach **452**
9-5 Adaptive Sampling Procedures **455**
9-6 Economic Design of Control Charts **457**
9-6.1 Designing a Control Chart **457**
9-6.2 Process Characteristics **458**
9-6.3 Cost Parameters **458**
9-6.4 Early Work and Semieconomic Designs **460**
9-6.5 An Economic Model of the $\bar{x}$ Control Chart **461**
9-6.6 Other Work **466**
9-7 Cuscore Charts **467**
9-8 The Changepoint Model for Process Monitoring **470**
9-9 Overview of Other Procedures **472**
9-9.1 Tool Wear **472**
9-9.2 Control Charts Based on Other Sample Statistics **473**
9-9.3 Fill Control Problems **474**
9-9.4 Precontrol **474**
9-9.5 Tolerance Interval Control Charts **476**
9-9.6 Monitoring Processes with Censored Data **476**
9-9.7 Nonparametric Control Charts **477**

CHAPTER 10
Multivariate Process Monitoring and Control **486**

Chapter Overview and Learning Objectives **486**
10-1 The Multivariate Quality-Control Problem **487**
10-2 Description of Multivariate Data **489**
10-2.1 The Multivariate Normal Distribution **489**
10-2.2 The Sample Mean Vector and Covariance Matrix **490**
10-3 The Hotelling T^2 Control Chart **491**
10-3.1 Subgrouped Data **491**
10-3.2 Individual Observations **500**
10-4 The Multivariate EWMA Control Chart **504**
10-5 Regression Adjustment **507**
10-6 Control Charts for Monitoring Variability **511**
10-7 Latent Structure Methods **513**
10-7.1 Principal Components **514**
10-7.2 Partial Least Squares **519**
10-8 Profile Monitoring **520**

CHAPTER 11
Engineering Process Control and SPC **526**

Chapter Overview and Learning Objectives **527**
11-1 Process Monitoring and Process Regulation **527**
11-2 Process Control by Feedback Adjustment **528**
11-2.1 A Simple Adjustment Scheme: Integral Control **528**
11-2.2 The Adjustment Chart **535**
11-2.3 Variations of the Adjustment Chart **536**
11-2.4 Other Types of Feedback Controllers **540**
11-3 Combining SPC and EPC **541**

PART IV
Process Design and Improvement with Designed Experiments **547**

CHAPTER 12
Factorial and Fractional Factorial Experiments for Process Design and Improvement **549**

Chapter Overview and Learning Objectives **549**
12-1 What is Experimental Design? **550**
12-2 Examples of Designed Experiments In Process Improvement **551**
12-3 Guidelines for Designing Experiments **555**
12-4 Factorial Experiments **557**

12-4.1 An Example **560**
12-4.2 Statistical Analysis **560**
12-4.3 Residual Analysis **566**
12-5 The 2^k Factorial Design **567**
12-5.1 The 2^2 Design **567**
12-5.2 The 2^k Design for $k \geq 3$ Factors **573**
12-5.3 A Single Replicate of the 2^k Design **585**
12-5.4 Addition of Center Points to the 2^k Design **589**
12-5.5 Blocking and Confounding in the 2^k Design **593**
12-6 Fractional Replication of the 2^k Design **595**
12-6.1 The One-Half Fraction of the 2^k Design **595**
12-6.2 Smaller Fractions: The 2^{k-p} Fractional Factorial Design **602**

CHAPTER 13
Process Optimization with Designed Experiments **611**

13-1 Response Surface Methods and Designs **612**
13-1.1 The Method of Steepest Ascent **614**
13-1.2 Analysis of a Second-Order Response Surface **616**
13-2 Process Robustness Studies **621**
13-2.1 Background **621**
13-2.2 The Response Surface Approach to Process Robustness Studies **624**
13-3 Evolutionary Operation **631**

PART V
Acceptance Sampling **643**

CHAPTER 14
Lot-by-Lot Acceptance Sampling for Attributes **645**

Chapter Overview and Learning Objectives **645**
14-1 The Acceptance-Sampling Problem **646**
14-1.1 Advantages and Disadvantages of Sampling **647**
14-1.2 Types of Sampling Plans **648**
14-1.3 Lot Formation **649**
14-1.4 Random Sampling **649**
14-1.5 Guidelines for Using Acceptance Sampling **650**
14-2 Single-Sampling Plans for Attributes **652**
14-2.1 Definition of a Single-Sampling Plan **652**
14-2.2 The OC Curve **652**

14-2.3 Designing a Single-Sampling Plan with a Specified OC Curve **657**
14-2.4 Rectifying Inspection **658**
14-3 Double, Multiple, and Sequential Sampling **662**
14-3.1 Double-Sampling Plans **662**
14-3.2 Multiple-Sampling Plans **668**
14-3.3 Sequential-Sampling Plans **669**
14-4 Military Standard 105E (ANSI/ASQC Z1.4, ISO 2859) **672**
14-4.1 Description of the Standard **672**
14-4.2 Procedure **674**
14-4.3 Discussion **679**
14-5 The Dodge–Romig Sampling Plans **681**
14-5.1 AOQL Plans **682**
14-5.2 LTPD Plans **685**
14-5.3 Estimation of Process Average **685**

CHAPTER 15
Other Acceptance-Sampling Techniques 688

15-1 Acceptance Sampling by Variables **689**
15-1.1 Advantages and Disadvantages of Variables Sampling **689**
15-1.2 Types of Sampling Plans Available **690**
15-1.3 Caution in the Use of Variables Sampling **691**
15-2 Designing a Variables Sampling Plan with a Specified OC Curve **692**
15-3 MIL STD 414 (ANSI/ASQC Z1.9) **694**
15-3.1 General Description of the Standard **694**
15-3.2 Use of the Tables **695**
15-3.3 Discussion of MIL STD 414 and ANSI/ASQC Z1.9 **698**
15-4 Other Variables Sampling Procedures **699**
15-4.1 Sampling by Variables to Give Assurance Regarding the Lot or Process Mean **699**
15-4.2 Sequential Sampling by Variables **700**
15-5 Chain Sampling **700**
15-6 Continuous Sampling **702**
15-6.1 CSP-1 **703**
15-6.2 Other Continuous-Sampling Plans **705**
15-7 Skip-Lot Sampling Plans **706**

Appendix **713**

I. Summary of Common Probability Distributions Often Used in Statistical Quality Control **715**
II. Cumulative Standard Normal Distribution **716**
III. Percentage Points of the χ^2 Distribution **718**
IV. Percentage Points of the t Distribution **719**
V. Percentage Points of the F Distribution **720**

VI. Factors for Constructing Variables Control Charts **725**
VII. Factors for Two-Sided Normal Tolerance Limits **726**
VIII. Factors for One-Sided Normal Tolerance Limits **727**

Bibliography **729**

Answers to Selected Exercises **713**

Index **743**