Contents

Acknowledgments **v**

1 Introduction **1**
1.1 Theme and Methodologies 2
1.2 Relations to Other Approaches 2
1.3 Organization and Overview 4

2 Stochastic Monotonicity, Convexity, and Submodularity **5**
2.1 Stochastic and Likelihood-Ratio Orderings 5
2.2 Stochastic Convexity 7
2.3 Stochastic Submodularity 11
2.4 Markov Chain Applications 14
2.5 Notes 16

3 Quality Control for Products with Warranty **19**
3.1 Warranty Cost Functions 20
3.2 K-Submodularity 23
3.3 Conditional Distribution for Defectives 26
3.4 Optimal Policy 27
3.5 The Individual Warranty Model 31
3.6 Examples and Extensions 34
3.7 Notes 35

4 Process Control in Batch Production **37**
4.1 Machine Revision 38
4.2 MDP Formulation 42
4.2.1 MDP Essentials 42
4.2.2 The MDP Problem 44
4.3 Discounted-Cost Model 45
4.3.1 Optimality Equations 45
4.3.2 Structural Properties 47
4.3.3 Optimal Policies 51
4.4 Average-Cost Model 56
4.5 A Special Case: No Inspection Cost 57
4.6 Notes 62

5 Coordinated Production-Inspection in a Tandem System **65**
5.1 A Two-Stage Tandem Queue 66
5.1.1 Problem Statement 66
5.1.2 The SMDP Formulation 67
5.2 Stationary Optimal Policies 72
5.3 Structure of the Optimal Policy 79
5.4 Notes 86

6 Sequential Inspection Under Capacity Constraints **89**
6.1 Capacity Constraints 90
6.2 Optimality of the Threshold Policy 93
6.3 Further Characterization of the Optimal Policy 100
6.4 An Application in Semiconductor Manufacturing 104
6.5 Notes 106

7 Coordination of Interstage Inspections **109**
7.1 Two-Stage Quality Control 110
7.2 Analysis of Stage 1 112
7.3 Optimal Policy at Stage 2 116
7.3.1 Priority Structure 116
7.3.2 Threshold Structure 120
7.4 A Special Case: Constant Defective Rates 125
7.5 Optimal Policy at Stage 1 127
7.6 General Cost Functions 132
7.7 Notes 136

8 Optimal Inspection in an Assembly System **139**
8.1 A Two-Component Assembly Model 140
8.2 Dynamic Programming Formulation 143
8.3 One Component with a Constant Defective Rate 145
8.4 A Heuristic Policy 154
8.5 Notes 156

9 Coordinated Replenishment and Rework with Unreliable Supply Sources **159**
9.1 The Inspection/Rework Model 160
9.2 Properties of the Cost Function 162
9.3 Optimal Solution to the Inspection Problem 166
9.4 Optimal Replenishment Quantities 171
9.5 Optimal Replenishment over an Infinite Horizon 177
9.6 A Random Yield Model with Multiple Sources 184
9.7 Notes 187

10 Inventory Control with Substitution **189**
10.1 Model Description 189
10.2 The Optimal Substitution Policy 191
10.3 Formulation of the Replenishment Decision 194
10.4 Concavity and Submodularity 197
10.5 The Optimal Order Quantities 200
10.6 Upper and Lower Bounds 202
10.7 Notes 204

References **207**

Index **216**