

Contents

Foreword	xv
Preface	xvii
Acknowledgments	xix
1 Introduction	1
1.1 The Technology	1
1.2 Packaging Failure	3
1.3 Approach and Methodology	4
1.4 Packaging Hierarchy	5
1.5 Failure Detection	6
1.6 Analysis	7
1.7 Modes and Mechanisms	8
1.8 Physics of failure and statistical models	9
1.9 Prevention	10
1.10 The Future	10
1.11 Suggested Readings	11
2 Electronics Packaging	12
2.1 Introduction	12
2.2 Packaging Nomenclature	13
2.3 Package Function	13
2.4 Plated-Through-Hole and Surface Mount Technology	15
2.5 Chip Level Packaging	15
2.5.1 Wire Bond or Ribbon Bond Packaging	16
2.5.2 Flip Chip Packaging	18
2.5.3 Tape Automated Bonding (TAB) Packaging	20
2.5.4 Ball Grid Array (BGA) Packaging	21
2.5.5 Chip Scale Packages (CSPs)	21
2.6 Printed Circuit Board Assembly	21
2.6.1 Printed Circuit Trace	26

2.6.2	Solder Mask	28
2.6.3	Preserving Printed Circuit Board (PCB) Solderability	28
2.6.4	PCB Materials	29
2.6.5	Flexible Circuits	29
2.6.6	Molded Circuits	30
2.7	Connectors, Cables, and Sockets	31
2.7.1	Introduction	31
2.7.2	Connector Types and Classifications	34
2.7.3	Connectors and PCB Assembly	34
2.7.3.1	Flux Contamination of Contacts	35
2.7.3.2	Conformal Coating Contamination	36
2.7.3.3	Dust and Debris Accumulation in Open Slots	36
2.7.3.4	Insertion Stresses on SMT Connector Solder Joints	36
2.7.3.5	Contact Metallurgy	36
2.7.3.6	Polarization for Alignment and Mating of Contacts	37
2.7.4	Sockets	37
2.7.4.1	Socket or Solder Attachment	39
2.7.4.2	Production vs. Test Sockets	40
2.7.5	Flat or Ribbon Cable Connectors	41
2.7.6	Optical Connectors	41
2.7.7	Elastomeric Connectors	43
2.8	Box Level Package	45
2.9	Cost of Failures	45
2.10	Summary	47
2.11	Suggested Readings	47
2.12	References	48
3	Why Failures Occur	51
3.1	Introduction	51
3.2	Stress vs. Strength	52
3.3	Poor Design Practices	53
3.3.1	Component Spacing	54
3.3.2	Clearance Between Component and PCB	54
3.3.3	Orientation (Components)	54
3.3.4	Stress Concentration (Trace Entry to Pad)	55
3.3.5	Stress Relief	55
3.3.6	Pad Vias	55
3.3.7	Test Point Accessibility	55
3.3.8	Alignment Forces During Reflow	56
3.3.9	Tolerances Accumulation	57
3.3.10	Under Design	57
3.3.11	Bending (Lack of Stiffness)	57
3.3.12	Polarization for Blind Mating	57
3.4	Manufacturing Defects	58
3.4.1	Warping	59
3.4.2	Manufacturing Contaminants	60
3.5	Electrical Design Considerations	61
3.5.1	Physical Size of the Printed Wiring Board	61

3.5.2	Power and Ground System Impedance	61
3.5.3	Signal Return Paths	62
3.5.4	Localized and Distributed Capacitance	62
3.5.5	Signal Integrity: Signal Ringing, Overshoot, and Undershoot	63
3.5.6	Component Thermal Margin	64
3.6	Material Characteristics	65
3.6.1	Coefficient of Thermal Expansion (CTE) Mismatch	65
3.6.2	Moisture Absorption	66
3.6.3	Environmental Corrosion	67
3.6.4	Materials Incompatibility	67
3.6.5	Melting Point Hierarchy	68
3.6.6	Metal Migration	68
3.7	Summary	68
3.8	References	69
4	Failure Detection	70
4.1	Introduction	70
4.1.1	Analytical Modeling	70
4.1.2	Statistical Simulation	71
4.1.3	Environmental Stress Testing	71
4.2	Analytical Modeling	72
4.2.1	Finite Element Modeling	72
4.2.2	Tolerance Analysis	74
4.2.3	Stress Analysis	75
4.3	Simulation	75
4.3.1	Electrical Simulation	75
4.3.1.1	Key Simulation Parameters	76
4.3.1.2	Determining the Values for Key Parameters	76
4.3.1.3	Tools	77
4.3.2	Mechanical Simulation	78
4.4	Environmental Stress Tests	78
4.4.1	Accelerated Tests	79
4.4.2	STRIFE Testing	80
4.4.3	Thermal Cycling	81
4.4.4	Thermal Shock	82
4.4.5	Insulation Resistance	83
4.4.6	Highly Accelerated Stress Test (HAST)	83
4.4.7	Temperature, Humidity, and Bias	87
4.4.8	Vibration	88
4.4.9	Mechanical Shock (Drop Test)	88
4.4.10	Salt Fog Test	88
4.4.11	Torque Test	89
4.4.12	Dust Test	89
4.4.13	Flowing Gas Test	90
4.5	Test Methodology Innovations	93
4.6	Summary	93
4.7	Suggested Readings	94
4.8	References	94

5	Failure Analysis	96
5.1	Introduction	96
5.2	Visual Inspection	97
5.2.1	Optical Inspection	99
5.2.2	X-rays	100
5.2.3	Thermal Imaging/Infrared Microscopy	100
5.2.3.1	Localized Joule Heating	101
5.2.4	Acoustic Imaging	101
5.2.4.1	Scanning Laser Acoustic Microscopy (SLAM)	103
5.2.4.2	C-Mode Acoustic Microscopy	103
5.3	Decapsulation	105
5.3.1	Wet Decapsulation	106
5.3.2	The Plasma Technique (Dry Decapsulation)	106
5.4	Moiré Interferometry	107
5.5	Dye Penetrants	109
5.6	Metallurgical Analysis	110
5.6.1	Metallurgical Examination	111
5.7	Chemical Analysis	112
5.7.1	Volumetric Analysis	112
5.7.2	Gravimetric Analysis	112
5.8	Atomic Absorption Emission Spectroscopies	113
5.9	UV/Visible Spectroscopy	113
5.10	Infrared Spectroscopy	114
5.11	Thermoanalytical Methods	115
5.11.1	Differential Scanning Calorimetry	117
5.11.2	Thermomechanical Analyzer	117
5.11.3	Thermogravimetric Analysis	122
5.12	Chromatography	123
5.13	Electron Beam Analysis	124
5.13.1	Auger Electron Spectroscopy (AES)	125
5.13.2	X-ray/Photoelectron Spectroscopy (XPS/ESCA)	125
5.13.3	Secondary Ion Mass Spectrometry (SIMS)	127
5.13.4	Scanning Electron Microscopy (SEM)	128
5.14	Laser Induced Ionization Mass Spectrometry (LIMS)	132
5.15	Summary	133
5.16	Suggested Readings	133
5.17	References	133
6	Failure Modes and Mechanisms	136
6.1	Introduction	136
6.2	Failure Mode Types	137
6.2.1	Electrical Shorts	137
6.2.2	Electrical Opens	137
6.2.3	Intermittent Failures	138
6.3	Printed Circuit Board	138
6.3.1	Material-Related Defects	139
6.3.1.1	Prepreg Defects	139

6.3.1.2	Measling, Crazing, and Haloing	139
6.3.1.3	Blistering and Delamination	141
6.3.1.4	Summary	141
6.3.2	Signal/Power Plane Plating Surface Defects	141
6.3.2.1	Copper Etch Shorts	141
6.3.2.2	Copper Etch Opens	141
6.3.2.3	Mechanical Circuit Damage	142
6.3.2.4	Handling Defects of Plated Copper Surfaces	142
6.3.2.5	Particulate Contamination	143
6.3.2.6	Pits and Scratches	145
6.3.2.7	Reduced Conductor Spacing	145
6.3.2.8	Summary	145
6.3.3	Through-Hole Defects	150
6.3.3.1	Partially Drilled Holes	151
6.3.3.2	Epoxy Smear	155
6.3.3.3	Nailheading	156
6.3.3.4	Inner Plane Delamination	157
6.3.3.5	PTH Copper Grain Structure	158
6.3.3.6	PTH Copper Plating Defects	158
6.3.3.7	PTH Solderability	159
6.3.3.8	Pink Ring	164
6.3.3.9	Summary	169
6.3.4	Solder Mask Related Defects	170
6.3.5	PCB Defect Elimination	170
6.4	Components and Packages	172
6.4.1	Introduction	172
6.4.2	Insertion Mount (PIH) Components	173
6.4.3	Surface Mount Components	173
6.4.3.1	SMT Chip Tombstoning	175
6.4.3.2	Modeling of Tombstoning Failures	176
6.4.3.3	SMT Chip Skewing	176
6.4.3.4	SMT Chip Cracking	176
6.4.4	SMT Packages	178
6.4.4.1	Package Failures	178
6.4.4.2	Interconnect Failures	187
6.4.4.2.1	Bond Pad Corrosion	187
6.4.4.2.2	Wire Bond Fails	188
6.4.4.3	Encapsulation Defects	190
6.4.4.4	Leads Related Failures	191
6.4.4.5	Summary	193
6.5	Interconnection Failures	193
6.5.1	Solder Joint Voids	193
6.5.1.1	PTH Solder Joint Voids	195
6.5.1.2	Hole Fill	196
6.5.1.3	SMT Solder Joint Voids	196
6.5.1.4	SMT Void Formation	199
6.5.1.5	Voids in BGA Joints	200

6.5.1.6	Summary	201
6.5.2	Intermetallics	201
6.5.2.1	Introduction	201
6.5.2.2	Intermetallic Formation	203
6.5.2.2.1	Copper–Tin Intermetallics	203
6.5.2.2.2	Nickel–Tin Intermetallics	204
6.5.2.2.3	Gold–Tin Intermetallics	204
6.5.2.3	Effect on Solderability	205
6.5.2.4	Effect on Joint Strength	205
6.5.2.5	Summary	206
6.5.3	Thermal Ratcheting	206
6.5.4	Solder Balling	210
6.5.4.1	Solder Balling During Wave Solder	210
6.5.4.2	Solder Balling During SMT Reflow	210
6.5.4.3	Solder Webbing	213
6.5.4.4	Solder Ball Test	213
6.5.4.5	Summary	213
6.6	Lead-Free Solders	213
6.6.1	Introduction	213
6.6.2	Tin–Bismuth Solder	214
6.6.3	Lead Contamination of Tin–Bismuth Solder	215
6.6.4	Indium Solder Corrosion	215
6.6.5	Summary	218
6.7	Corrosion and Migration	218
6.7.1	Introduction	218
6.7.1.1	Factors Affecting Corrosion and Electromigration	219
6.7.2	Corrosion	220
6.7.2.1	Electrode Potentials and Galvanic Corrosion	220
6.7.2.2	Conditions for Corrosion	221
6.7.3	Electromigration	221
6.7.3.1	Conditions for Electromigration	222
6.7.3.2	Conductive Anodic Filament	225
6.7.3.3	Conditions for Conductive Anodic Filament formation	226
6.7.3.4	Measurement of Migration Propensity	226
6.7.4	Electromigration and Corrosion of Select Metals	228
6.7.4.1	Silver	228
6.7.4.2	Copper	230
6.7.4.3	Tin	230
6.7.4.4	Lead	230
6.7.4.5	Gold	231
6.7.5	Failure Analysis of Corrosion and Electromigration	231
6.7.6	Prevention of Corrosion and Electromigration Phenomena	232
6.7.7	Tin Whiskers	233
6.7.7.1	Introduction	233
6.7.7.2	Whisker Growth Mechanism	234
6.7.7.3	Whisker Prevention	234
6.7.7.4	Summary	236

6.8 Connector Failures and Mechanisms	236
6.8.1 Introduction	236
6.8.2 Mechanical Failures	238
6.8.2.1 Bent Pins and Contacts	238
6.8.2.2 Card Warpage	240
6.8.2.3 Handling and Shipping Damage	240
6.8.2.4 Tolerances and Interference	240
6.8.2.5 Contact Fabrication	242
6.8.2.6 Temperature-Induced Mechanisms	242
6.8.2.7 Summary	244
6.8.3 Contact Corrosion	244
6.8.3.1 Introduction	244
6.8.3.2 Gold Plating Wear	245
6.8.3.3 Manufacturing Contaminant Corrosion	245
6.8.3.4 Dust	247
6.8.3.5 Connector Housing	247
6.8.3.6 Summary	249
6.8.4 Fretting Corrosion	249
6.8.4.1 Introduction	249
6.8.4.2 Fretting Corrosion Variables	249
6.8.4.3 The Fretting Mechanism	251
6.8.4.4 Socket Device Walk Out	251
6.8.4.5 Summary	252
6.8.5 Frictional Polymerization on Palladium Plating	252
6.8.6 Contact Arcing Due to Hot Plugging	252
6.8.7 Summary	253
6.9 Solder Fatigue and Creep	253
6.10 Failures in Nonsemiconductor Components	256
6.10.1 Introduction	256
6.10.2 Resistors	257
6.10.3 Capacitors	258
6.10.4 Oscillators	260
6.10.5 Inductors	260
6.11 Electro Static Discharge (ESD) Failures	262
6.11.1 Introduction	262
6.11.2 ESD Failure Mechanisms	262
6.11.3 ESD Charge Generation	263
6.11.4 Prevention of Static Charge	266
6.11.4.1 Minimizing Charge Buildup	266
6.11.4.2 Draining of Charge	267
6.11.4.3 Neutralizing Static Charge	267
6.11.4.4 Shielding from Field and Discharge Effects	268
6.11.5 Summary	268
6.12 PCB Laminates and Hollow Glass Fibers	268
6.13 Radiation-Induced Failures	270
6.13.1 Damage Prevention	272
6.14 Summary	272

6.15 Suggested Readings	273
6.16 References	273
7 Failure Models	283
7.1 Introduction	283
7.1.1 Physics-of-Failure Models	284
7.1.2 Statistical Models	284
7.2 A Survey of Physical Models	285
7.2.1 Arrhenius Model	287
7.2.2 Eyring Model	287
7.2.3 Voltage/Field Effect Model	288
7.2.4 Current Model	288
7.2.5 Power Model	289
7.2.6 Temperature Cycling Models	289
7.2.7 Humidity Models	289
7.2.7.1 Lawson Model	290
7.2.7.2 Eyring Humidity Model	290
7.2.7.3 Peck and Zierdt Model	291
7.2.7.4 Reich and Hakim Model	292
7.2.7.5 Sbar and Kozakiewicz Model	292
7.2.7.6 Weick Model	292
7.2.7.7 Stroehle Model	293
7.2.7.8 Hallek	293
7.2.7.9 SIM–Lawson Model	293
7.2.8 Humidity Ingress and Package/Card Damage Models	294
7.2.8.1 Memis Model	294
7.2.8.2 Conductive Anodic Filament Model	294
7.2.9 Solder Joint Fatigue Models	295
7.2.9.1 Coffin–Manson Model	295
7.2.9.2 Hughes Model	296
7.2.9.3 Steinberg Model	297
7.2.9.4 Englemaier Models	297
7.2.9.4.1 Leadless Model	297
7.2.9.4.2 Leaded Model	298
7.3 Physics-of-Failure Based Models for Devices	299
7.3.1 Black’s Model	299
7.3.2 Fowler–Nordheim Model	299
7.3.3 Kidson Model	300
7.3.4 Kato and Niwa Model	300
7.4 Accelerated Factors and Transforms	301
7.4.1 Introduction	301
7.4.2 Temperature Acceleration	302
7.4.3 Mechanical Deflection Test	304
7.4.4 Vibration Acceleration	304
7.5 Summary	307
7.6 References	307

8 Failure Prevention	310
8.1 Introduction	310
8.2 Concurrent Engineering and DFM	311
8.3 DFM Examples	314
8.3.1 Discrete Component Orientation	314
8.3.2 Discrete Component Pad Geometry	314
8.3.3 Shadowing by Tall Components	316
8.4 Design for Assembly	317
8.4.1 DFA for Electronic Packaging Assembly	319
8.5 Design for Test	320
8.6 Design for Qualification	320
8.7 Design for Reliability	322
8.7.1 Stress on Solder Joints	323
8.7.2 Depanelling Stresses	323
8.7.3 Mother Board Mounting	323
8.7.4 Mechanical Damage	323
8.8 Continuous Improvement Through Defect Management	324
8.9 Summary	325
8.10 References	325
Appendices	327
Appendix A	327
Appendix B	336
Appendix C	338
Appendix D	348
Appendix E	359
About the Authors	361
Index	363