

---

# Contents

Foreword .....	ix
<b>1 Introduction .....</b>	<b>1</b>
1.1 General .....	1
1.2 What is surface metrology? .....	1
1.3 Usefulness of surfaces .....	2
1.4 Nature of surfaces .....	7
<b>2 Identification and separation of surface features .....</b>	<b>16</b>
2.1 Visualization .....	16
2.2 Profiles and roughness – understanding the measurement routine .....	16
2.3 Waviness .....	24
2.4 Implementing the concept of sampling length .....	26
2.5 The shape of the reference line .....	30
2.6 Other methods .....	38
2.7 Filtering and M system .....	40
2.8 Conclusions .....	47
<b>3 Profile and areal (3D) parameter characterization .....</b>	<b>48</b>
3.1 Specification .....	48
3.2 Classification of parameters for the profile .....	49
3.3 Random process analysis .....	71
3.4 Areal (3D) assessment .....	78
3.5 Space frequency functions .....	88
3.6 Comments on digital areal analysis .....	89
3.7 Two-dimensional filtering (areal filtering) .....	92
3.8 Fractal surfaces .....	93

3.9	Summary of characterization .....	94
<b>4</b>	<b>Surface metrology and manufacture .....</b>	<b>96</b>
4.1	Where and when to measure .....	96
4.2	The process and surface finish .....	97
4.3	Process control .....	127
4.4	Relationship between surface metrology and manufacture .....	130
4.5	Force and metrology loops .....	133
4.6	Unit events and autocorrelation .....	134
4.7	Use of the power spectrum .....	135
4.8	Application of space frequency functions .....	136
4.9	Conclusions .....	139
<b>5</b>	<b>Function and surface texture .....</b>	<b>141</b>
5.1	Generic approach .....	141
5.2	Some specific examples in tribology .....	146
5.3	Surface models .....	151
5.4	Summary of function .....	154
<b>6</b>	<b>Surface finish measurement – general .....</b>	<b>158</b>
6.1	Some quick ways of examining the surface .....	158
6.2	Surface finish instrumentation .....	163
6.3	Comments .....	165
<b>7</b>	<b>Stylus instruments .....</b>	<b>168</b>
7.1	The stylus .....	168
7.2	Reference .....	169
7.3	Use of skids .....	170
7.4	Pick-up systems .....	172
7.5	Stylus damage .....	172
7.6	Stylus instrument usage .....	173
<b>8</b>	<b>Optical methods .....</b>	<b>185</b>
8.1	Optical path length .....	186
8.2	Optical penetration .....	186
8.3	Resolution and depth of focus .....	186
8.4	Comparison between optical and stylus methods .....	188
8.5	Gloss meters .....	189
8.6	Total integrating sphere .....	190
8.7	Diffractometer .....	190
8.8	Interferometry .....	192
8.9	Optical followers .....	194
8.10	Heterodyne method .....	195
8.11	Other optical methods .....	197
8.12	Conclusions from the comparison of tactile and optical methods .....	199

<b>9</b>	<b>Scanning microscopes</b> .....	<b>202</b>
9.1	General .....	202
9.2	Scanning microscopes .....	204
9.3	Operation of the STM .....	205
9.4	The atomic force microscope .....	209
9.5	Scanning microscopes: conclusions .....	210
9.6	Instruments ‘horns of metrology’: conclusions .....	211
<b>10</b>	<b>Errors of form (excluding axes of rotation)</b> .....	<b>214</b>
10.1	General statement .....	214
10.2	Straightness and related topics .....	217
10.3	Measurement .....	217
10.4	Assessment and classification of straightness .....	225
10.5	Flatness .....	228
10.6	Conclusions .....	233
<b>11</b>	<b>Roundness and related subjects</b> .....	<b>235</b>
11.1	General .....	235
11.2	Direction of measurement .....	237
11.3	Display of roundness .....	238
11.4	Lobing .....	241
11.5	Methods of measuring roundness .....	242
11.6	Nature of the roundness signal .....	255
11.7	Assessment of roundness .....	263
11.8	Partial arc determination .....	270
11.9	Other parameters .....	272
11.10	Filtering for roundness .....	277
11.11	Harmonic problems .....	279
11.12	Alternatives to harmonic analysis .....	281
11.13	Non-roundness parameters .....	283
11.14	Conclusions .....	288
<b>12</b>	<b>Cylindricity, sphericity</b> .....	<b>290</b>
12.1	Cylindricity .....	290
12.2	Configurations for measurement .....	294
12.3	Some definitions of cylindrical parameters .....	299
12.4	Assessment .....	301
12.5	Other points on cylinders .....	301
12.6	Sphericity .....	302
12.7	Partial sphericity .....	304
12.8	Wankel – other shapes .....	307
<b>13</b>	<b>Metrology instrument design and operation for minimum error</b> .....	<b>309</b>
13.1	Introduction .....	309
13.2	Capability .....	310

13.3	Errors .....	311
13.4	Metrology instrument design and error reduction .....	311
13.5	Instrument usage .....	332
13.6	Elastic design – removal of hysteresis and friction errors .....	334
13.7	Workpiece cleaning and handling .....	339
13.8	Conclusions .....	340
<b>14</b>	<b>Calibration of instruments .....</b>	<b>342</b>
14.1	General .....	342
14.2	The stylus calibration .....	345
14.3	Height calibration .....	348
14.4	General height .....	351
14.5	Roundness calibration – for height .....	351
14.6	Filter calibration (type C standard) .....	353
14.7	Vibrating tables .....	355
14.8	Instrument comparisons .....	356
14.9	Chain of standards .....	357
14.10	Conclusions .....	359
<b>15</b>	<b>Sampling, numerical analysis, display .....</b>	<b>361</b>
15.1	General .....	361
15.2	Numerical model .....	362
15.3	Sampling criteria .....	363
15.4	Error of application .....	365
15.5	Representation on drawing .....	367
15.6	Sample guides .....	367
15.7	Philosophical background to standards in roughness .....	368
15.8	Concluding remarks .....	371
	Glossary .....	373
	Index .....	389