
CONTENTS

Chapter 1 Histograms and Empirical Distributions 1

1.1	Introduction	1
1.2	Empirical Distributions	2
1.3	Measures of Central Tendency	7
1.4	Measures of Variation	8
* 1.5	Computation of the Mean and Standard Deviation of the Data from the Frequency Table	9

Chapter 2 Random Variables and Probability Distributions 13

2.1	Introduction	13
2.2	Set of All Possible Outcomes of the Experiment—the Sample Space	14
2.3	Events	18
2.4	Random Variables	19
2.5	Probability	24
2.6	Cumulative Distribution Functions	27
2.7	Discrete Probability Distributions	33
2.8	Continuous Random Variables and Density Functions	37
2.9	Expectation	43
2.10	Moments	47
2.11	Some Properties of Functions of Random Variables	51
2.12	Bivariate Probability Distributions	52
2.13	Conditional Probability and Independent Events	57
2.14	Independent Random Variables and a Random Sample	60
2.15	Conditional Probability Distributions	64

Chapter 3 The Normal Distribution 75

3.1	Definitions	75
3.2	The Mean and Variance of the Normal Distribution	76
*3.2.1.	Evaluation of the Mean and Variance	78
3.3	Tables of the Normal Integral	79
3.4	Combinations of Normally Distributed Variables	82
3.5	The Standardized Normal Random Variable	84

3.6	The Distribution of the Sample Mean	84
3.7	Tolerances	86
* 3.8	Tolerances in "Complex Items"	93
3.9	The Central Limit Theorem	99
Chapter 4 Other Probability Distributions		106
4.1	Introduction	106
4.2	The Chi-Square Distribution	107
4.2.1.	The Chi-Square Random Variable	107
4.2.2	The Addition Theorem	110
4.2.3	The Distribution of the Sample Variance, S^2	111
4.3	The t Distribution	114
4.3.1	The t Random Variable	114
4.3.2	The Distribution of $(\bar{X} - \mu)\sqrt{n}/S$	117
4.3.3	The Distribution of the Difference Between Two Sample Means	118
4.4	The F Distribution	120
4.4.1	The F Random Variable	120
4.4.2	The Distribution of the Ratio of Two Sample Variances	122
4.5	The Binomial Distribution	123
4.5.1	The Binomial Random Variable	123
*4.5.2	Tables of the Binomial Probability Distribution	126
*4.5.3	The Normal Approximation to the Binomial	127
*4.5.4	The Arc Sine Transformation	128
*4.5.5	The Poisson Approximation to the Binomial	128
Chapter 5 Decision Making		134
5.1	Introduction	134
5.2	Decision Making Without Experimentation	134
5.2.1	Action Space	135
5.2.2	States of Nature	136
5.2.3	Loss Function	137
5.2.4	Criteria for Choosing Among Actions	138
5.2.5	Bayes Principle	139
5.2.6	Evaluation of the Loss Function for the Rockwell Hardness Example	141
5.2.7	Further Examples	145
5.3	Decision Making With Experimentation	148
5.3.1	Decision Procedures	148
5.3.2	Risk Function	150
5.3.3	Bayes Decision Procedures	152
5.3.4	Calculation of the Posterior Distribution	155
*5.3.4.1	Derivation of Posterior Distribution	158
5.3.5	Further Examples	158
5.3.6	Assessment of the Bayesian Approach	161
5.4	Significance Tests	163
5.4.1	The Operating Characteristic Curve	165
5.4.2	Comparison of the OC Curve with the Risk Function	167
5.4.3	Comparison of OC Curves	168
5.4.4	Tests of Hypotheses	172
5.4.5	One- and Two-Sided Procedures	174

Chapter 6 Tests of Hypotheses about a Single Parameter 183

6.1	Test of the Hypothesis that the Mean of a Normal Distribution Has a Specified Value when the Standard Deviation Is Known	183
6.1.1	Choice of an OC Curve	183
6.1.2	Tables and Charts for Determining Decision Rules	184
6.1.2.1	Tables and Charts for Two-Sided Procedures	185
6.1.2.2	Summary for Two-Sided Procedures Using Tables and Charts	188
6.1.2.3	Tables and Charts for One-Sided Procedures	189
6.1.2.4	Summary for One-Sided Procedures Using Tables and Charts	191
6.1.2.5	Tables and Charts for OC Curves	192
6.1.3	Analytical Determination of Decision Rules	192
6.1.3.1	Acceptance Regions and Sample Sizes	192
6.1.3.2	The OC Curve	196
6.1.4	Example	197
6.2.	Test of the Hypothesis that the Mean of a Normal Distribution Has a Specified Value when the Standard Deviation is Unknown	198
6.2.1	Choice of an OC Curve	198
6.2.2	Tables and Charts for Carrying Out t Tests	199
6.2.2.1	Tables and Charts for Two-Sided Procedures	200
6.2.2.2	Summary for Two-Sided Procedures	200
6.2.2.3	Tables and Charts for One-Sided Procedures	202
6.2.2.4	Summary for One-Sided Procedures	204
6.2.2.5	Tables and Charts for OC Curves	205
6.2.3.	Examples of t Tests	206
6.3	Test of the Hypothesis that the Standard Deviation of a Normal Distribution Has a Specified Value	207
6.3.1	Choice of an OC Curve	207
6.3.2	Charts and Tables to Design Tests of Dispersion	208
6.3.2.1	Tables and Charts for Two-Sided Procedures	208
6.3.2.2	Summary for Two-Sided Procedures Using Tables and Charts	209
6.3.2.3	Tables and Charts for One-Sided Procedures	210
6.3.2.4	Summary for One-Sided Procedures Using Tables and Charts	213
6.3.2.5	Tables and Charts for OC Curves	214
6.3.3	Analytical Treatment for Chi-Square Tests	215
6.3.4	Example	216

Chapter 7 Tests of Hypotheses about Two Parameters 225

7.1	Test of the Hypothesis that the Means of Two Normal Distributions Are Equal when Both Standard Deviations Are Known	225
7.1.1	Choice of an OC Curve	225
7.1.2	Tables and Charts for Determining Decision Rules	226
7.1.2.1	Tables and Charts for Two-Sided Procedures	226
7.1.2.2	Summary for Two-Sided Procedures Using Tables and Charts	228

	7.1.2.3	Summary for One-Sided Procedures Using Tables and Charts	229
	7.1.2.4	Tables and Charts for OC Curves	230
7.1.3		Analytical Determination of Decision Rules	230
	7.1.3.1.	Acceptance Regions and Sample Sizes	230
	7.1.3.2	The OC Curve	232
	7.1.4	Example	234
7.2		Test of the Hypothesis that the Means of Two Normal Distributions Are Equal, Assuming that the Standard Deviations Are Unknown but Equal	235
	7.2.1	Choice of an OC Curve	235
	7.2.2	Tables and Charts for Carrying out Two-Sample t Tests	235
	7.2.2.1	Tables and Charts for Two-Sided Procedures	236
	7.2.2.2	Summary for Two-Sided Procedures Using Tables and Charts	237
	7.2.2.3	Summary for One-Sided Procedures Using Tables and Charts	237
	7.2.2.4	Tables and Charts for OC Curves	238
	7.2.3	Example	239
7.3		Test of the Hypothesis that the Means of Two Normal Distributions Are Equal, Assuming that the Standard Deviations Are Unknown and Not Necessarily Equal	240
	7.3.1	Test Procedure	240
	7.3.2	Example	241
7.4		Test for Equality of Means when the Observations Are Paired	242
	7.4.1	Test Procedure	242
	7.4.2	Example	244
7.5		Non-parametric Tests	246
	7.5.1	The Sign Test	246
	7.5.2	The Wilcoxon Signed Rank Test	249
	7.5.3	Wilcoxon Test for Two Independent Samples	251
7.6		Test of the Hypothesis that the Standard Deviations of Two Normal Distributions Are Equal	254
	7.6.1	Choice of an OC Curve	254
	7.6.2	Charts and Tables for Carrying out F Tests	255
	7.6.2.1	Tables and Charts for Two-Sided Procedures	255
	7.6.2.2	Summary for Two-Sided Procedures Using Tables and Charts	256
	7.6.2.3	Tables and Charts for One-Sided Procedures	257
	7.6.2.4	Summary for One-Sided Procedures Using Tables and Charts	258
	7.6.2.5	Tables and Charts for OC Curves	258
	*7.6.3	Analytical Treatment for Tests	260
	7.6.4	Example	262
7.7		Cochran's Test for the Homogeneity of Variances	263
Chapter 8 Estimation			279
8.1		Introduction	279
8.2		Point Estimation	279
	8.2.1	Comparison of Estimators	280

8.2.2	Unbiased Estimators	283
8.2.3	Consistent Estimators	284
8.2.4	Efficient Unbiased Estimators	285
8.2.5	Estimation by the Method of Maximum Likelihood	286
8.2.6	Estimation by the Method of Moments	290
8.2.7	Estimation by the Method of Bayes	292
8.3	Confidence Interval Estimation	294
8.3.1	Confidence Interval for the Mean of a Normal Distribution when the Standard Deviation Is Known	295
8.3.2	Confidence Interval for the Mean of a Normal Distribution when the Standard Deviation Is Unknown	296
8.3.3	Confidence Interval for the Standard Deviation of a Normal Distribution	297
8.3.4	Confidence Interval for the Difference between the Means of Two Normal Distributions when the Standard Deviations Are Both Known	298
8.3.5	Confidence Interval for the Difference between the Means of Two Normal Distributions where the Standard Deviations Are Both Unknown but Equal	300
8.3.6	Confidence Interval for the Ratio of Standard Deviations of Two Normal Distributions	301
8.3.7	A Table of Point Estimates and Interval Estimates	302
8.3.8	Approximate Confidence Intervals	302
8.3.9	Simultaneous Confidence Intervals	304
8.3.10	Bayesian Intervals	308
8.4	Statistical Tolerance Limits	309
8.4.1	Statistical Tolerance Limits Based on the Normal Distribution	309
8.4.2	One-Sided Statistical Tolerance Limits Based on the Normal Distribution	310
8.4.3	Distribution-Free Tolerance Limits	310

Chapter 9 Fitting Straight Lines

325

9.1	Introduction	325
9.2	Types of Linear Relationships	328
9.3	Least Squares Estimators of the Slope and Intercept	331
9.3.1	Formulation of the Problem and Results	331
*9.3.2	Theory	333
9.4	Confidence Interval Estimators of the Slope and Intercept	336
9.4.1	Formulation of the Problem and Results	336
*9.4.2	Theory	337
9.5	Point Estimators and Confidence Interval Estimators of the Average Value of Y for a Given x	338
9.5.1	Formulation of the Problem and Results	338
*9.5.2	Theory	339
9.6	Point Estimators and Interval Estimators of the Independent Variable x Associated with an Observation on the Dependent Variable Y	340
9.7	Prediction Interval for a Future Observation on the Dependent Variable	342

	10.3.12	The OC Curve of the Analysis of Variance for the Mixed Effects Model, Two-Way Classification, One Observation per Cell	420
	10.3.13	Example Using the Mixed Effects Model	420
10.4		Two-Way Analysis of Variance, n Observations per Combination	421
	10.4.1	Description of the Various Models	421
	10.4.2	Computational Procedure, Two-Way Classification, n Observations per Combination	423
	10.4.3	Analysis of the Fixed Effects Model, Two-Way Classification, n Observations per Combination	424
	10.4.4	The OC Curve of the Analysis of Variance for the Fixed Effects Model, Two-Way Classification, n Observations per Cell	427
	10.4.5	Example Using the Fixed Effects Model, Two-Way Classification, Three Observations per Combination	428
	10.4.6	Analysis of the Random Effects Model, Two-Way Classification, n Observations per Combination	430
	10.4.7	The OC Curve of the Random Effects Model, Two-Way Classification, n Observations per Combination	431
	10.4.8	Example Using the Random Effects Model	432
	10.4.9	Analysis of the Mixed Effects Model, Two-Way Classification, n Observations per Cell	432
	10.4.10	The OC Curve of the Analysis of Variance for the Mixed Effects Model, Two-Way Classification, n Observations per Cell	434
	10.4.11	Example Using the Mixed Effects Model	434
10.5		Summary of Models and Tests	436
 Chapter 11 Some Further Techniques of Data Analysis			452
11.1		Introduction	452
11.2		Qualitative Techniques for Determining the Form of a Distribution	452
11.3		Quantitative Techniques for Determining the Form of a Distribution	454
	11.3.1	The Kolmogorov-Smirnov Test	454
	11.3.2	The Chi-Square Goodness of Fit Test	458
11.4		Chi-Square Tests	460
	11.4.1	The Hypothesis Completely Specifies the Theoretical Frequency	461
	11.4.2	Dichotomous Data	461
	11.4.3	Test of Independence in a Two-Way Table	463
	11.4.4	Computing Form for Test of Independence in a 2×2 Table	464
11.5		Comparison of Two Percentages	465
11.6		Confidence Intervals for Proportion	466
 Chapter 12 Statistical Quality Control: Control Charts			472
12.1		Introduction	472
12.2		An Overview of Control Charts	473

12.3	Control Chart for Variables: \bar{X} -Charts	474
12.3.1	Statistical Concepts	474
12.3.2	Estimate of \bar{X}'	475
12.3.3	Estimate of σ' by $\bar{\sigma}$	476
12.3.4	Estimate of σ' by \bar{R}	476
12.3.5.	Starting a Control Chart for \bar{X}	478
12.3.6	Relation between Natural Tolerance Limits and Specification Limits	479
12.3.7	Interpretation of Control Charts for \bar{X}	480
12.4	<i>R</i> Charts and σ Charts	481
12.4.1	Statistical Concepts	481
12.4.2	Setting up a Control Chart for <i>R</i> or σ	483
12.5	Example of \bar{X} and <i>R</i> Chart	483
12.6	Control Chart For Fraction Defective	485
12.6.1	Relation between Control Charts Based on Variables Data and Charts Based on Attributes Data	486
12.6.2	Statistical Theory	487
12.6.3	Starting the Control Chart	488
12.6.4	Continuing the <i>p</i> Chart	489
12.6.5	Example	489
12.7	Control Charts For Defects	489
12.7.1	Difference between a Defect and a Defective Item	490
12.7.2	Statistical Theory	490
12.7.3	Starting and Continuing the <i>c</i> Chart	491
12.7.4	Example	492
12.8	Further Developments on Control Charts	493
12.8.1	The Signed Sequential Rank Control Chart	493
12.8.2	The Cumulative Sum Control Chart	495

Chapter 13 Sampling Inspection by Attributes **503**

13.1	The Problem of Sampling Inspection	503
13.1.1	Introduction	503
13.1.2	Drawing the Sample	504
13.2	Lot-by-Lot Sampling Inspection by Attributes	505
13.2.1	Single Sampling Plans	505
13.2.1.1	Single Sampling	507
13.2.1.2	Choosing a Sampling Plan	508
13.2.1.3	Calculation of OC Curves for Single Sampling Plans	508
13.2.1.4	Example	508
13.2.2	Double Sampling Plans	508
13.2.2.1	Double Sampling	509
*13.2.2.2	OC Curves for Double Sampling Plans	509
*13.2.2.3	Example	510
13.2.3	Multiple Sampling Plans	511
13.2.4	Classification of Sampling Plans	511
13.2.4.1	Classification By AQL	512
13.2.4.2	Classification By LTPD	512
13.2.4.3	Classification By Point of Control	512
13.2.4.4	Classification By AOQL	512

13.2.5	Dodge-Romig Tables	513
13.2.5.1	Single Sampling Lot Tolerance Tables	514
13.2.5.2	Double Sampling Lot Tolerance Tables	514
13.2.5.3	Single Sampling AOQL Tables	518
13.2.5.4	Double Sampling AOQL Tables	518
13.2.6	Military Standard 105D	518
13.2.6.1	History	518
13.2.6.2	Classification of Defects	522
13.2.6.3	Acceptable Quality Levels	522
13.2.6.4	Normal, Tightened, and Reduced Inspection	523
13.2.6.5	Sampling Plans	525
13.2.6.6	Summary of the Procedure To Be Followed in the Selection of a Sampling Plan from MIL-STD-105D	527
13.2.7	Designing Your Own Attribute Plan	527
13.2.7.1	Computing the OC Curve of a Single Sampling Plan	527
13.2.7.2	Finding a Sampling Plan Whose OC Curve Passes through Two Points	537
13.2.7.3	Design of Item-by-Item Sequential Plans	537
13.2.8	A Bayesian Approach to Sampling Inspection	545
13.2.8.1	Economic Structure	545
13.2.8.2	A Decision Analysis Model	546
13.2.8.3	Bayes Procedures	547
13.3	Continuous Sampling Inspection	550
13.3.1	Introduction	550
13.3.2	Dodge Continuous Sampling Plans	551
13.3.3	Multi-Level Sampling Plans	552
13.3.4	The Dodge CSP-1 Plan without Control	556
13.3.5	Wald-Wolfowitz Continuous Sampling Plans	557
13.3.6	Girshick Continuous Sampling Plan	558
13.3.7	Plans Which Provide for Termination of Production	559
Chapter 14 Lot-by-Lot Sampling Inspection by Variables		565
14.1	Introduction	565
14.2	General Inspection Criteria	566
14.3	Estimates of the Percent Defective	568
14.3.1	Estimate of the Percent Defective when the Standard Deviation Is Unknown but Estimated by the Sample Standard Deviation	568
14.3.2	Estimate of the Percent Defective when the Standard Deviation Is Unknown but Estimated by the Average Range	569
14.3.3	Estimate of the Percent Defective when the Standard Deviation Is Known	571
14.4	Comparison of Variables Procedures with M and k	574
14.5	The Military Standard for Inspection by Variables, MIL-STD-414	575
14.5.1	Introduction	575
14.5.2	Section A — General Description of Sampling Plans	576
14.5.3	Section B — Variability Unknown, Standard Deviation Method	585

14.5.4	Section C — Variability Unknown, Range Method	585
14.5.5	Section D — Variability Known	590
14.5.6	Example Using MIL-STD-414	591

Appendix	599
-----------------	------------

Answers to Selected Problems	618
-------------------------------------	------------

Index	623
--------------	------------