

## CONTENTS

PREFACE	v
1. INTRODUCTION	1
1.1 What is Statistics?	1
1.2 Why Statistical Quality Control?	1
1.3 Aim of Book	3
1.4 Prerequisites	3
1.5 Suggestions to the Student	3
2. BRIEF REVIEW OF STATISTICAL BACKGROUND	5
2.1 Population and Sample	5
2.2 Parameter and Statistic	5
2.3 Notations	6
2.4 Probability Definitions and Laws	9
2.5 Distribution of Sample Statistics	12
2.6 Statistical Estimation	16
2.7 Testing Hypotheses	18
References	21
3. CONTROL CHARTS IN GENERAL	23
3.1 Introduction	23
3.2 Running Records of Performance	23
3.3 Random and Assignable Causes	26
3.4 The Control Chart for Interpreting Variations in Quality	29
3.5 Two Purposes of Control Charts	32
3.6 Economic Balance Between Two Errors	33
3.7 Meaning of a Process in Control and Potential Advantages	33
Problems	35
References	38
4. CONTROL CHARTS FOR MEASUREMENTS	39
4.1 Introduction	39
4.2 Control Charts for Averages, Ranges and Standard Deviations, from Given Standards	39
4.3 Control Charts for Averages, Ranges and Standard Deviations, Analyzing Past Data	49
4.4 Comparison of the Two Charts for Variability	53
4.5 Comparison of a Process with Specifications	54
4.6 Continuing the Charts	60
4.7 Illustrative Examples	61
4.8 Kinds of Assignable Causes	78
4.9 When to Set Standard Values - Process Capability	83
4.10 Use of Runs for Out of Controlness	85
4.11 Summary	86
Problems	89
References	96

5.	BACKGROUND OF CONTROL CHARTS FOR MEASUREMENTS	97
5.1	Introduction	97
5.2	The Empirical Approach to Sampling Distributions	97
5.3	Control Charts for Samples from Normal Populations of $x$ 's	98
	Problems	106
	References	106
6.	CONTROL CHARTS FOR ATTRIBUTES	107
6.1	Introduction	107
6.2	Control Charts for Defectives	108
6.3	Control Charts for Defects	128
6.4	General Comments on Control Charts for Attributes	138
6.5	A Method of Rating Product Quality	140
6.6	Summary	142
	Problems	144
	References	156
7.	MISCELLANEOUS TOPICS IN CONTROL CHARTS	157
7.1	Control Charts for Individual Measurements, Moving Ranges	157
7.2	Tool Wear and Other Gradual Process Changes	161
7.3	Charts for $\bar{x}$ and $s$ , Large Samples	168
7.4	Charts for $\bar{x}$ and $R$ or $s$ , with Varying Sample Size	169
7.5	Different Types of Samples	172
7.6	Relative Efficiency of Different Types of Charts	180
7.7	Artificial "Specifications" for Greater Efficiency in Attribute Charts	183
7.8	Summary Charts for $\bar{x}$ and $\bar{R}$	185
7.9	Variations of Control Charts	186
7.10	Summary	190
	Problems	190
	References	196
8.	APPLICATIONS OF CONTROL CHARTS	203
8.1	What Manufacturing Problem to Work On	203
8.2	Attacking an Industrial Problem	204
8.3	List of Typical Applications of Control Charts	207
8.4	Use in the Laboratory	211
8.5	The Quality Control Person	212
8.6	Bibliography on Applications	213
9.	ACCEPTANCE SAMPLING BY ATTRIBUTES	225
9.1	Why Acceptance Sampling?	225
9.2	Characteristics of Sampling Plans	226
9.3	Acceptance Criteria for Attribute Acceptance Plans	228
9.4	Operating Characteristic (OC) Curve, Defectives.	230
9.5	The Average Outgoing Quality Curve, AOQ Curve	239
9.6	The Average Sample Number Curve, ASN Curve	243
9.7	The Average Total Inspection Curve, ATI Curve	244
9.8	Characteristics of Double Sampling Plans	245
9.9	Further Notations on OC Curves	253
9.10	Characteristics for Defects Plans	255

9.11	Devising a Sampling Plan to Match Two Points on an OC Curve	257
9.12	Use of Control Chart Record with Acceptance Sampling	259
9.13	Summary - General Principles of Sampling Acceptance and Some Misconceptions	260
	Problems	269
	References	271
10.	SOME STANDARD PLANS FOR ATTRIBUTES	273
10.1	Introduction	273
10.2	The Dodge-Romig Sampling Inspection Tables	275
10.3	The ABC or Military Standard 105D Plan	281
10.4	What Next?	315
10.5	Summary	318
	Problems	319
	References	322
11.	ACCEPTANCE SAMPLING BY MEASUREMENTS	323
11.1	Potential Greater Efficiency by Variables than by Attributes	323
11.2	Dependence Upon Knowledge of Distribution of Individual $x$ 's	324
11.3	Use of Control Charts and Frequency Distributions for Past Data	324
11.4	Decision-Making on Lot Means, Known $\sigma$	325
11.5	Decision Making on Percent Beyond a Specification, Known $\sigma$	331
11.6	Decision Making on Percent Beyond a Specification, Unknown $\sigma$	332
11.7	Single Sampling for Variability	336
11.8	Military Standard 414 Plan	341
11.9	Checking a Process Setting and a Process Capability	345
11.10	Summary	347
	Problems	348
	References	350
12.	SEQUENTIAL ANALYSIS	353
12.1	Introduction	353
12.2	The General Approach	354
12.3	The Sequential Probability Ratio Test	355
12.4	Six Special Cases of Sequential Analysis Summarized	356
12.5	Some Examples	363
12.6	Use in Checking a Process Setting	369
12.7	A Sequential Test for Process Capability, Using Ranges	371
12.8	Use in the Laboratory	371
12.9	Two Derivations of Acceptance-Rejection Constants	372
12.10	Summary	375
	Problems	375
	References	379
13.	SOME OTHER SAMPLING PLANS	381
13.1	Sampling Inspection of Continuous Production	381
13.2	Chain Sampling Plans, ChSP-1	390

13.3	Skip-Lot Sampling Plan	392
13.4	Cusum Charts	395
13.5	Summary	399
	Problems	400
	References	401
14.	STATISTICS OF COMBINATIONS, TOLERANCES FOR MATING PARTS	403
14.1	Introduction	403
14.2	Statistics of Sums and Differences	404
14.3	Use of Distributions in Assemblies	408
14.4	Tolerancing Assemblies by Specifying Process Controls and Acceptance Sampling	417
14.5	Products, Quotients, and Other Functions	422
14.6	Summary	430
	Problems	431
	References	435
15.	SOME OTHER FREQUENCY DISTRIBUTIONS	437
15.1	Introduction	437
15.2	Moments of Distributions	437
15.3	Some Frequency Distribution Models	441
15.4	A Goodness of Fit Test for Frequency Data	454
15.5	Summary	460
	Problems	461
	References	463
	ANSWERS TO ODD-NUMBERED PROBLEMS	465
	APPENDIX	475
	GLOSSARY OF SYMBOLS	507
	AUTHOR INDEX	515
	SUBJECT INDEX	519