

# Contents

<b>1</b>	<b>Quality Assurance in the Modern Business Environment</b>	<b>1</b>
1-1	THE MEANING OF QUALITY	1
1-2	QUALITY ASSURANCE, TECHNOLOGY, AND PRODUCTIVITY	3
1-3	QUALITY COSTS	5
1-4	METHODS OF QUALITY ASSURANCE	11
1-5	THE RESPONSIBILITY FOR QUALITY	15
1-6	LEGAL ASPECTS	17
1-7	SUMMARY	19

<b>PART I</b>	<b>STATISTICAL METHODS USEFUL IN QUALITY ASSURANCE</b>	<b>21</b>
---------------	--	-----------

<b>2</b>	<b>Modeling Process Quality</b>	<b>23</b>
2-1	DESCRIBING VARIATION	23
2-1.1	The Frequency Distribution and Histogram	23
2-1.2	Numerical Summary of Data	26
2-1.3	Probability Distributions	28
2-2	IMPORTANT DISCRETE DISTRIBUTIONS	33
2-2.1	The Hypergeometric Distribution	33
2-2.2	The Binomial Distribution	34

2-2.3	The Poisson Distribution	36
2-2.4	The Pascal and Related Distributions	37
2-3	IMPORTANT CONTINUOUS DISTRIBUTIONS	38
2-3.1	The Normal Distribution	38
2-3.2	The Exponential Distribution	44
2-3.3	The Gamma Distribution	46
2-3.4	The Weibull Distribution	47
2-4	SOME USEFUL APPROXIMATIONS	49
2-4.1	The Binomial Approximation to the Hypergeometric	49
2-4.2	The Poisson Approximation to the Binomial	50
2-4.3	The Normal Approximation to the Binomial	50
2-4.4	Comments on Approximations	51
2-5	EXERCISES	52

**3 Inferences About Process Quality 57**

3-1	STATISTICS AND SAMPLING DISTRIBUTIONS	58
3-1.1	Sampling from a Normal Distribution	59
3-1.2	Sampling from a Bernoulli Distribution	62
3-1.3	Sampling from a Poisson Distribution	63
3-2	ESTIMATING PROCESS PARAMETERS	64
3-2.1	Point Estimation	65
3-2.2	Interval Estimation	66
3-3	HYPOTHESIS TESTING ON PROCESS PARAMETERS	75
3-3.1	Tests on Means, Variance Known	77
3-3.2	Tests on Means of Normal Distributions, Variance Unknown	79
3-3.3	Tests on Variances of Normal Distributions	83
3-3.4	Tests on Binomial Parameters	85
3-3.5	Tests on Poisson Parameters	87
3-3.6	The Probability of Type II Error	89
3-4	EXERCISES	92

<b>PART II</b>	<b>STATISTICAL PROCESS CONTROL</b>	<b>99</b>
<b>4</b>	<b>How the Control Chart Works</b>	<b>101</b>
4-1	CHANCE AND ASSIGNABLE CAUSES OF QUALITY VARIATION	101
4-2	STATISTICAL BASIS OF THE CONTROL CHART	102
4-2.1	Basic Principles	102
4-2.2	Choice of Control Limits	108
4-2.3	Sample Size and Sampling Frequency	110
4-3	RATIONAL SUBGROUPS	111
4-4	ANALYSIS OF PATTERNS ON CONTROL CHARTS	112
4-5	NONMANUFACTURING APPLICATIONS OF CONTROL CHARTS	115
4-6	EXERCISES	116
<b>5</b>	<b>Control Charts for Attributes</b>	<b>119</b>
5-1	INTRODUCTION	119
5-2	THE CONTROL CHART FOR FRACTION NONCONFORMING	119
5-2.1	Development and Operation of the Control Chart	121
5-2.2	Variable Sample Size	133
5-2.3	The Operating-Characteristic Function	139
5-3	CONTROL CHARTS FOR NONCONFORMITIES (DEFECTS)	141
5-3.1	Procedures with Constant Sample Size	142
5-3.2	Procedures with Variable Sample Size	153
5-3.3	Demerit Systems	155
5-3.4	The Operating-Characteristic Function	156
5-4	EXERCISES	158
<b>6</b>	<b>Control Charts for Variables</b>	<b>171</b>
6-1	INTRODUCTION	171
6-2	CONTROL CHARTS FOR $\bar{x}$ AND $R$	173
6-2.1	Statistical Basis of the Charts	173

6-2.2	Development and Use of $\bar{x}$ and $R$ Charts	176
6-2.3	Charts Based on Standard Values	188
6-2.4	Interpretation of $\bar{x}$ and $R$ Charts	189
6-2.5	The Effect of Nonnormality on $\bar{x}$ and $R$ Charts	192
6-2.6	The Operating- Characteristic Function	193
6-3	OTHER CONTROL CHARTS FOR VARIABLES	197
6-3.1	$\bar{x}$ and $S$ Control Charts	197
6-3.2	The $S^2$ Control Chart	199
6-3.3	Control Charts for Individual Units	200
6-3.4	Control Limits Based on a Small Number of Samples	202
6-4	CHOICE BETWEEN ATTRIBUTES AND VARIABLES CONTROL CHARTS	203
6-5	SUMMARY OF PROCEDURES FOR $\bar{x}$ , $R$ , AND $S$ CHARTS	205
6-6	GUIDELINES FOR IMPLEMENTING CONTROL CHART PROGRAMS	206
6-7	EXERCISES	209

<b>7</b>	<b>Other Statistical Process-Control Techniques</b>	<b>221</b>
7-1	MODIFIED CONTROL CHARTS	221
7-1.1	Basic Principles	221
7-1.2	Alternative Designs for the Modified Control Chart	224
7-2	THE CUMULATIVE-SUM CONTROL CHART	225
7-2.1	Basic Principles	225
7-2.2	Designing a Cumulative-Sum Control Chart	229
7-2.3	Related Procedures	230
7-3	CONTROL CHARTS BASED ON WEIGHTED AVERAGES	235
7-3.1	The Moving-Average Control Chart	235
7-3.2	The Geometric Moving-Average (GMA) Control Chart	239
7-4	PRE-CONTROL	243

7-5	METHODS FOR CONTROLLING SEVERAL RELATED QUALITY CHARACTERISTICS	245
7-6	STATISTICAL ALTERNATIVES TO CONTROL CHARTS	252
7-7	EVOLUTIONARY OPERATION	253
7-8	OVERVIEW OF OTHER PROCEDURES	260
7-9	EXERCISES	265
<b>8</b>	<b>Process-Capability Analysis</b>	<b>273</b>
8-1	INTRODUCTION	273
8-2	PROCESS-CAPABILITY ANALYSIS USING A HISTOGRAM OR A PROBABILITY PLOT	275
8-2.1	Using the Histogram	275
8-2.2	Probability Plotting	280
8-3	PROCESS-CAPABILITY ANALYSIS USING A CONTROL CHART	285
8-4	PROCESS-CAPABILITY ANALYSIS USING DESIGNED EXPERIMENTS	288
8-5	SETTING SPECIFICATION LIMITS ON DISCRETE COMPONENTS	293
8-5.1	Linear Combinations	293
8-5.2	Nonlinear Combinations	297
8-6	ESTIMATING THE NATURAL TOLERANCE LIMITS OF A PROCESS	300
8-6.1	Tolerance Limits Based on the Normal Distribution	300
8-6.2	Nonparametric Tolerance Limits	301
8-7	EXERCISES	302
<b>9</b>	<b>Economic Design of Control Charts</b>	<b>307</b>
9-1	INTRODUCTION	307
9-1.1	Process Characteristics	308
9-1.2	Cost Parameters	309
9-1.3	Early Work and Semieconomic Designs	310
9-2	ECONOMIC DESIGN OF THE $\bar{x}$ CONTROL CHART	312
9-2.1	Single Assignable-Cause Models	312
9-2.2	Multiple Assignable-Cause Models	324

9-2.3 Joint Economic Design of $\bar{x}$ and $R$ Control Charts	332
9-3 ECONOMIC DESIGN OF THE CONTROL CHART FOR FRACTION NONCONFORMING	333
9-4 ECONOMIC DESIGN OF OTHER CONTROL CHARTS	336
9-5 SUMMARY	338
APPENDIX 9A A COMPUTER PROGRAM FOR THE ECONOMIC DESIGN OF THE $\bar{x}$ CONTROL CHART	341
9-6 EXERCISES	343

## **PART III ACCEPTANCE SAMPLING 349**

### **10 Lot-By-Lot Acceptance Sampling for Attributes 351**

10-1 THE ACCEPTANCE-SAMPLING PROBLEM	351
10-1.1 Advantages and Disadvantages of Sampling	353
10-1.2 Types of Sampling Plans	354
10-1.3 Lot Formation	354
10-1.4 Random Sampling	355
10-1.5 Guidelines for Using Acceptance Sampling	356
10-2 SINGLE-SAMPLING PLANS FOR ATTRIBUTES	358
10-2.1 Definition of a Single-Sampling Plan	358
10-2.2 The OC Curve	359
10-2.3 Designing a Single-Sampling Plan with a Specified OC Curve	366
10-2.4 Rectifying Inspection	367
10-3 DOUBLE, MULTIPLE, AND SEQUENTIAL SAMPLING	373
10-3.1 Double-Sampling Plans	373
10-3.2 Multiple-Sampling Plans	382
10-3.3 Sequential-Sampling Plans	383
10-4 A LOT-SENSITIVE COMPLIANCE (LTPD) SAMPLING PLAN	387

10-5	MILITARY STANDARD 105D (ANSI / ASQC Z1.4)	389
10-5.1	Description of the Standard	389
10-5.2	Procedure	392
10-5.3	Discussion	408
10-6	DODGE-ROMIG SAMPLING PLANS	413
10-6.1	LTPD Plans	414
10-6.2	AOQL Plans	420
10-6.3	Estimation of Process Average	426
10-7	EXERCISES	426
<b>11</b>	<b>Acceptance Sampling by Variables</b>	<b>431</b>
11-1	INTRODUCTION TO VARIABLES SAMPLING	431
11-1.1	Advantages and Disadvantages of Variables Sampling	431
11-1.2	Types of Sampling Plans Available	432
11-1.3	Caution in the Use of Variables Sampling	434
11-2	DESIGNING A VARIABLES SAMPLING PLAN WITH A SPECIFIED OC CURVE	435
11-3	MIL STD 414 (ANSI / ASQC Z1.9)	439
11-3.1	General Description of the Standard	439
11-3.2	Use of the Tables	440
11-3.3	Discussion of MIL STD 414 and ANSI/ASQC Z1.9	453
11-4	OTHER VARIABLES SAMPLING PROCEDURES	455
11-4.1	Sampling by Variables to Give Assurance Regarding the Lot or Process Mean	455
11-4.2	Sequential Sampling by Variables	456
11-4.3	The Lot-Plot Method	456
11-4.4	Narrow-Limit Gaging	457
11-5	EXERCISES	458
<b>12</b>	<b>Other Acceptance-Sampling Procedures</b>	<b>461</b>
12-1	CHAIN SAMPLING	461
12-2	CONTINUOUS SAMPLING	463
12-2.1	CSP-1	464

12-2.2 CSP-2, CSP-3, and Multilevel Plans	468
12-2.3 MIL STD 1235B	470
12-3 SKIP-LOT SAMPLING PLANS	473
12-4 CONSIDERATION OF INSPECTION ERROR	477
12-5 ECONOMIC DESIGN OF ACCEPTANCE-SAMPLING PLANS	481
12-6 EXERCISES	485

**BIBLIOGRAPHY 489****APPENDIX 497**

<b>I Cumulative Poisson Distribution</b>	<b>498</b>
<b>II Cumulative Standard Normal Distribution</b>	<b>501</b>
<b>III Percentage Points of the <math>\chi^2</math> Distribution</b>	<b>503</b>
<b>IV Percentage Points of the <math>t</math> Distribution</b>	<b>504</b>
<b>V Percentage Points of the <math>F</math> Distribution</b>	<b>505</b>
<b>VI Factors for Constructing Variables Control Charts</b>	<b>510</b>
<b>VII Factors for Two-Sided Normal Tolerance Limits</b>	<b>511</b>
<b>VIII Factors for One-Sided Normal Tolerance Limits</b>	<b>512</b>
<b>IX Random Numbers</b>	<b>513</b>
<b>Index</b>	<b>515</b>