

# CONTENTS

## PREFACE

1. INTRODUCTION .....	1
2. THE PROCESS MODEL AND LOSS FUNCTION .....	5
2.1 The Process Model .....	5
2.2 The Control Scheme .....	8
2.3 The Average Run Length .....	15
2.4 The Objective Function .....	16
2.5 Economic Consequences of a Control Chart .....	19
2.6 The Renewal Cycle .....	21
2.7 The Loss Function .....	26
2.8 Loss per Unit Produced Versus Loss per Unit of Time .....	31
3. THE SAMPLING INTERVAL .....	33
3.1 The $h^*$ -Algorithm .....	34
4. CONTROL CHARTS FOR VARIABLES .....	41
4.1 The Sampling Plan .....	41
4.2 $\bar{X}$ -Control Charts .....	46
4.3 The $\bar{X}$ -Algorithm .....	50
5. CONTROL CHARTS FOR ATTRIBUTES .....	68
5.1 C-Control Charts .....	68
5.2 The C-Algorithm .....	75
5.3 P-Control Charts .....	103
5.4 The P-Algorithm .....	104
6. STATISTICAL PROPERTIES OF ECONOMICALLY DESIGNED CONTROL CHARTS .....	110
7. EXTENSIONS .....	118

7.1	$\bar{X}$ -Control Charts for Aging Processes .....	119
7.2	The Repair-Algorithm .....	133
7.3	Control Charts with Warning Limits .....	137
8.	THE NO-SAMPLING ALTERNATIVE .....	143
9.	CONCLUSIONS .....	152
	BIBLIOGRAPHY .....	154
	LIST OF SYMBOLS .....	165
	INDEX .....	170