

INTRODUCTION	ix
METRICATION	xi
1. BASIC PRINCIPLES: LINEAR MEASUREMENTS	1
Co-ordinates – Five basic methods – Triangulation and traversing – Chains and chaining – Offsets; locating objects – Sloping ground – Other modes of linear measurement – Signals	
2. CHAIN SURVEYING	19
Equipment – Field book – Principles of chain surveying – Fieldwork – Boundary lines – Traversing with the chain – Sources of error in chaining	
3. PLOTTING PLANS AND MAPS	28
Construction and use of scales – Special scales – Plotting and finishing maps – Conventional signs – Constructing angles; use of protractor and trigonometrical tables – Enlarging maps and plans – Ordnance Survey maps	
4. FIELD GEOMETRY	59
Reciprocal ranging – Perpendiculars and parallels – Checking angles with the tape – Obstructions to measurement and alignment – Four classes of obstacles	
5. LEVELLING	72
Classification of methods; historical note – Bubble tubes and equivalent plumb line – Telescope – Dumpy and other levels – Levelling staves – Levelling practice – Two systems of booking levels – Curvature and refraction – Levelling difficulties	
6. ANGULAR LEVELLING	96
Methods – The clinometer and Abney level – Observing heights – Barometry – Aneroid barometer	
7. THE COMPASS AND BOX SEXTANT	104
Historical note – The prismatic compass – Bearings and azimuths – Magnetic declination – Local attraction – Fixed and free needle – Traversing with the compass – Graphical adjustment of traverse surveys – Compass resection – Box sextant	
8. PLANE TABLING	126
The plane table and its accessories – Primary methods – Orientation and setting – Resection; the three-point problem – Field work	

9. CONTOURING	136
Nature and uses of contours – Horizontal and vertical control – Direct and indirect methods of contour location – Combinations of methods – Interpolation	
10. AREAS AND VOLUMES	148
Areas of simple plane figures – Areas of irregular plane figures – Methods – Give and take lines – Trapezoidal and Simpson's rules – Computing scale – Volumes of simple regular solids – Cross sections – Trapezoidal and prismoidal rules – Earthwork volumes – Use of truncated prisms and contours – Longitudinal and cross sections; gradients	
11. THEODOLITE SURVEYING	170
Historical note – The theodolite – Circles and verniers – Measurement of angles – Theodolite surveys – Reducing bearings – Latitudes and departures – Adjustment of traverse surveys – Miscellaneous problems	
APPENDIX A	184
Metric equipment – B.S.I. recommendations	
APPENDIX B	187
Plane trigonometry	
TRIGONOMETRICAL TABLE	189
INDEX	190

Figs. 3.10–3.14 are reproduced from the Ordnance Survey Conventional Signs with the sanction of the Controller of H.M. Stationery Office, Crown Copyright reserved.