

Contents

Foreword	vii
Acknowledgements	x
Abbreviations	xi
1 The Evidence	1
Introduction	1
Written and visual sources	1
Metallographic and surface examination	2
Experimental archaeology	3
Conclusions	4
2 Iron Production	5
Introduction	5
Sources of iron in the Roman Empire	5
Moving the ore	10
Charcoal production	11
Ore preparation	12
Bloomery iron production	13
Bloomsmithing (primary smithing)	17
Clean iron	18
Conclusions	22
3 Blacksmithing Techniques and Production Methods	25
Introduction	25
Blacksmithing	25
Welding	27
Heat treatment	27
Advantages of hot and cold working	31
Work hardening	32
Forming sheet metal hemispheres	32
Producing holes in sheet metal	36
Materials testing in antiquity	38
Recycling metal	39
Manufacture	40
Economics	43
Conclusions	46
4 The Production of Sheet Metal	49
Methods of sheet iron production	49
Conclusions	56

5	Iron and Steel	58
	Introduction	58
	Methods of making steel	59
	Hardening and tempering	62
	Conclusions	64
6	Surface Treatment of Roman Armour	65
	Introduction	65
	Rust prevention	65
	The surface appearance of Roman armour	68
	Polishing	69
	Coatings	71
	A comparison of different surface treatments	76
	Preventing rusting during storage	77
	Conclusions	77
7	Helmets (<i>galea</i> or <i>cassis</i>)	79
	Introduction	79
	Parts of the helmet	80
	Methods of manufacture	82
	Conclusions	92
8	Scale Armour (<i>lorica squamata</i>)	95
	Body armour	95
	<i>Lorica squamata</i>	95
	Typology of <i>lorica squamata</i>	96
	The nature of scale armour	97
	Field repairs	100
	Case study: The Carlisle shoulder piece	101
	Metallography	101
	Wire to join scales	102
	Replication of scale armour	104
	The future of scale armour	108
	Conclusions	108
9	Ring Mail (<i>lorica hamata</i>)	111
	Introduction	111
	Wire production	112
	Wire drawing	114
	Type of metals used for wire	116
	Experimental method for producing a draw plate	118
	Wire drawing	121
	Ring types	123
	Non-ferrous rings	130
	Riveted rings	132
	Conclusions	132

10 Segmented Body Armour (<i>lorica segmentata</i>)	135
Introduction	135
Conclusions	137
11 Leg and Arm Armour	139
Arm armour	139
Greaves (<i>Ocrea</i>)	141
Method of manufacture	143
Conclusion	144
12 The Shield and Boss (<i>umbo</i>)	146
Introduction	146
Shield edging (guttering)	148
The construction typology of shield bosses	148
Double-skinned ferrous shield bosses	149
Laminated shield bosses (welded)	153
Other materials	156
Conclusions	157
13 Conclusions	159
Appendix 1: The Survival of Ancient Machines	163
Appendix 2: One-sided Carburization	165
Glossary	167
Latin terms	170
Bibliography	172
Plates	between pp. 116-117