

CONTENTS

PART 1 INTRODUCTION	1
1 HISTORY AND EVOLUTION OF QUALITY CONTROL	3
1-1 Earliest Developments	4
1-2 Developments in the World War II Era	6
1-3 Modern Developments	8
1-4 Training for Quality	11
1-5 References	12
2 QUALITY AND QUALITY SYSTEMS	14
2-1 Quality and Productivity	15
2-2 Quality Control	30
2-3 Quality Systems	35
2-4 References	62
2-5 Problems	66
3 REVIEW OF FUNDAMENTAL STATISTICAL CONCEPTS	68
3-1 Probability	68
3-2 Frequency Distributions	72
3-3 Measurements of Central Tendency	74
3-4 Measures of Dispersion	78
3-5 Probability Distributions	81
3-6 Statistical Inference	96
	ix

3-7	Quality Control as an Area of Statistics	104
3-8	References	105
3-9	Problems	105

PART 2 STATISTICAL PROCESS CONTROL **113**

4	INTRODUCTION TO CONTROL CHARTS	115
4-1	Variation and the Control Chart	116
4-2	An Attribute Control Chart	121
4-3	Detection of Changes	129
4-4	References	132
4-5	Problems	133
5	ADDITIONAL CONTROL CHART PRINCIPLES	134
5-1	Behavior of Variables Data	134
5-2	Normal Distribution	136
5-3	Control Charts for Averages and Ranges	142
5-4	General Principles of Control Charts	156
5-5	References	160
5-6	Problems	160
6	CONTROL CHARTS FOR ATTRIBUTES	162
6-1	Charts for Number of Pieces Nonconforming	163
6-2	Charts for Percent Nonconforming	168
6-3	Charts for Number of Nonconformities	176
6-4	OC Curves for Attributes Control Charts	180
6-5	References	183
6-6	Problems	183
7	CONTROL CHARTS FOR VARIABLES	190
7-1	Individuals (x) Chart	190
7-2	Rational Subgroups—Design of Data Collection	195
7-3	Range (R) Chart	197
7-4	Standard Deviation Chart	200
7-5	Average (\bar{x}) Chart	205
7-6	Median (\tilde{x}) Chart	211
7-7	Midrange (M) Chart	214
7-8	Other Variables Control Charts	216
7-9	Evaluation of Average Control Charts	217
7-10	Other Evaluations	220

7-11 Economic Design and Evaluation of Control Charts	221
7-12 Conclusions	223
7-13 References	223
7-14 Problems	225
8 SPECIAL CONTROL CHARTS	233
8-1 Cumulative Sum Control Charts	233
8-2 The Exponentially Weighted Moving Average Control Chart	253
8-3 Modified or Reject Control Limits for \bar{x} Charts	256
8-4 Acceptance Control Charts	266
8-5 References	279
8-6 Problems	280

PART 3 METHODS FOR QUALITY IMPROVEMENT **285**

9 GRAPHICAL METHODS FOR QUALITY	287
9-1 History of Graphical Methods	287
9-2 The Magnificent Seven	290
9-3 The Second Seven	325
9-4 Special Graphics	343
9-5 Other Graphics and Advanced Methods	347
9-6 References	348
9-7 Problems	351
10 PROCESS CONTROL TECHNIQUES	354
10-1 Quality Improvement	355
10-2 Control of Quality	385
10-3 Conclusions	400
10-4 References	401
10-5 Problems	402
11 SPECIFICATION LIMITS, TOLERANCES, AND RELATED TECHNIQUES	408
11-1 Specification Limits and Tolerances	408
11-2 Relationship to Processes and Control Charts	409
11-3 CUSUM Charts and Specification Limits	419
11-4 Some Miscellaneous Procedures	421
11-5 Statistical Addition of Tolerances	423
11-6 References	431
11-7 Problems	431

PART 4 ACCEPTANCE SAMPLING**435**

12 SINGLE AND DOUBLE ATTRIBUTE SAMPLING	437
12-1 Sampling Risks	438
12-2 Sampling Variations	439
12-3 Types of Sampling Plans	441
12-4 Single Sampling	444
12-5 Double Sampling Plans	460
12-6 References	467
12-7 Problems	467
13 SEQUENTIAL AND MULTIPLE ATTRIBUTE SAMPLING PLANS	469
13-1 Item-by-Item Sequential Sampling Plans	470
13-2 Group Sequential Plans	480
13-3 Derivation of Matched Plans	481
13-4 References	485
13-5 Problems	486
14 ATTRIBUTE SAMPLING TABLES	487
14-1 ANSI/ASQC Z1.4-1981	489
14-2 The Dodge-Romig System	501
14-3 An <i>LQL</i> Indexed System	508
14-4 Other Attribute Acceptance Sampling Plans	514
14-5 References	516
14-6 Problems	517
15 SPECIAL ATTRIBUTE SAMPLING PROCEDURES	518
15-1 Continuous Sampling Plans—CSP	518
15-2 Skip-Lot Sampling Plans—SkSP	531
15-3 Chain Sampling Plans—ChSP	536
15-4 References	540
15-5 Problems	542
16 ACCEPTANCE SAMPLING BY VARIABLES	545
16-1 Estimating Fraction Nonconforming with the Normal Distributions	546
16-2 Estimating Fraction Nonconforming when the Standard Deviation Is Known	549
16-3 Acceptance Sampling by Variables Using ANSI/ASQC Z1.9-1980 (MIL-STD-414)	552
16-4 The Graphical Method—ISO 3951	571
16-5 Testing Normality	575
16-6 Other Procedures	575
16-7 References	575
16-8 Problems	576

PART 5 METHODS FOR DESIGN QUALITY 579

17 INDUSTRIAL EXPERIMENTATION	581
17-1 Onetime Experiments	582
17-2 Evolutionary Operations	593
17-3 Analysis of Means (ANOM)	603
17-4 Summary	616
17-5 References	616
17-6 Problems	618
18 RELIABILITY	620
18-1 Basic Concepts of Reliability	621
18-2 Distributions Useful in Reliability	624
18-3 Reliability Predictions	629
18-4 Reliability Estimation	635
18-5 Accelerated Life Testing	647
18-6 References	650
18-7 Problems	652

APPENDIX: TABLES 655

A Areas Under the Normal Curve	656
B Percentage Points of the Chi Square (χ^2) Distribution	658
C Percentage Points of the t Distribution	659
D Percentage Points of the F Distribution	660
E Cumulative Binomial Distribution	665
F Summation of Terms of the Poisson Distribution	667
G Control Chart Factors for Central Tendency	672
H Control Chart Factors for Dispersion	673
I One-sided Statistical Tolerance Interval, μ, σ unknown	676
J Two-sided Statistical Tolerance Interval, μ, σ unknown	677
K Exact Critical Values for the Analysis of Means	678
L Factors for Acceptance Control Charts	680

INDEX 681
