

# Contents

<b>Chapter One – Introduction</b>	<b>1</b>
<b>Chapter Two – Barriers to automation</b>	<b>7</b>
Advanced manufacturing systems	8
Automatic assembly	9
Programmable controllers	10
Data processing	11
Microcomputers	11
The electronic office	12
Material handling	12
Problems in implementing computer aided engineering	13
DCF and profit centres	17
Specialisation of suppliers	20
<b>Chapter Three – The need for training</b>	<b>27</b>
Employment growth and new product markets	29
Skills needed for rationalisation	30
Strategy and skills	31
Changes in production processes	36
Changes in materials	38
Recruitment and training implications	40
<b>Chapter Four – CAD/CAM</b>	<b>45</b>
Management benefits	47
Why British engineering firms adopted CAD	47
CAD/CAM	50
The development of CAD use in the mid-1980s	51
Implications	53

<b>Chapter Five – Computerised production and inventory control systems</b>	<b>55</b>
Firm and plant goals	57
CPICS success and failure	59
Implications of CPICS for employment	61
CPICS and management	62
CPICS and training	64
<b>Chapter Six – The maintenance skills gap</b>	<b>69</b>
Maintenance skill needs in the 1960s and 1970s	70
Maintenance skill needs in the 1980s	73
Problems in implementing appropriate maintenance training schemes	76
Outside maintenance services	79
Computer maintenance	82
<b>Chapter Seven – The Japanese influence</b>	<b>87</b>
Some reasons for Japanese firms' competitiveness	88
The Japanese approach to volume production	91
British working practices	93
Japanese-owned firms in the UK	94
Industrial relations	95
Changing work practices in the British motor industry	96
What are the implications?	98
<b>Chapter Eight – Towards the automatic factory?</b>	<b>101</b>
The development of automation	102
Managerial perspectives	103
Deskilling – labour process analysis	106
The need for skills	109
An attempt at evaluation	114
<b>Chapter Nine – Some conclusions and recommendations</b>	<b>117</b>