

2671-079 8

TABLET MACHINE INSTRUMENTATION IN PHARMACEUTICS: Principles and Practice

PETER RIDGWAY WATT, MSc, CChem, FRSC, CPhys, FInstP
Instrument Services Co-ordinator
Beecham Pharmaceuticals Research Division



ELLIS HORWOOD LIMITED
Publishers · Chichester

Halsted Press: a division of
JOHN WILEY & SONS
New York · Chichester · Brisbane · Toronto

Table of contents

Foreword	15
Preface	17
Part I Principles	19
The need for instrumentation	20
The instrumented tablet press	22
The simulator	23
Variable factors for measurement	23
Section A Measurement of force	27
1 Strain gauges: electrical resistance strain gauges	29
1.1 Characteristics of metal foil strain gauges	30
1.1.1 Gauge construction	30
1.1.2 Gauge backing	32
1.1.3 Gauge configurations	33
1.1.4 Electrical characteristics	33
1.1.5 Temperature variation of gauge factor	33
1.1.6 Non-linearity of gauge resistance with strain level	35
1.1.7 Temperature coefficient of gauge expansion	35
1.1.8 Gauge compensation	36
1.1.9 Dimensions of foil strain gauges	38
1.1.10 Measuring range	38
1.1.11 Gauge life	38
1.1.12 Gauge resistance	40
1.1.13 Gauge selection	40
1.2 Semiconductor strain gauge	40
1.2.1 Gauge backing	42
1.2.2 Gauge life	42

2	Siting the strain gauges	
2.1	Stress analysis	.43
2.1.1	Analysis through modelling	.43
2.1.2	Direct methods of stress analysis	.51
3	Strain gauge installation	
3.1	Surface preparation	.69
3.1.1	Cleaning	.69
3.1.2	Porosity	.70
3.1.3	Surface finish	.71
3.1.4	Further cleaning	.72
3.1.5	Marking the gauge site	.72
3.1.6	Surface conditioning	.72
3.2	Adhesive bonding	.73
3.2.1	Cyanoacrylates	.73
3.2.2	Epoxy resins	.73
3.2.3	Choice of adhesive	.74
3.2.4	Gauge positioning	.74
3.2.5	Applying the adhesive	.76
3.2.6	Curing the adhesive	.77
3.2.7	Bonding semiconductor gauges	.77
3.3	Making electrical connexions	.79
3.3.1	Soldering	.81
3.3.2	Securing the connecting wires	.85
3.4	Gauge protection	.85
3.5	Strain gauge installation tools and equipment	.86
4	The Wheatstone bridge circuit	.96
4.1	Gauge resistance	.97
4.2	Bridge configurations	.98
4.3	Lead resistance	.99
4.4	Zero drift	.99
4.5	Gauge factor variation	101
4.6	Apparent strain	104
4.7	Non-linearity	104
4.8	Effect of surface curvature	106
4.9	Bridge completion resistors	106
4.10	Bridge excitation levels	107
5	Miscellaneous methods	
5.1	Encapsulated gauges	108
5.2	Weldable gauges	108
5.3	Vibrating element gauges: the 'S-sensor'	109
5.4	Capacitance gauges	111
5.5	Magnetostrictive gauges	111
5.6	Load cells — general	112
5.6.1	Piezoresistive cells	112

5.6.2	Piezoelectric cells	112
5.6.3	Magnetoelastic cells	118
5.6.4	The LVDT load cell	118
5.6.5	Advantages of load cells	118
5.6.6	Disadvantages of load cells.	119
5.6.7	Resolution	121
5.7	Miscellaneous	122
5.7.1	The fibre optic strain gauge	122
5.7.2	Laser speckle strain gauging	123
5.7.3	Prescale film	124

Section B Measurement of displacement

6 Displacement transducers with analogue output

6.1	Linear variable-differential transformer	130
6.1.1	Zero setting	132
6.1.2	Thermal effects	132
6.1.3	Gauging transducers	132
6.1.4	Dimensions	133
6.1.5	Excitation	134
6.1.6	Demodulator	134
6.2	Linear inductive displacement transducer	134
6.3	Variable turns-ratio transformer	135
6.4	Linear variable capacitor.	135
6.5	Linear magnetoresistive transducer	137
6.6	The Hall effect transducer	137
6.7	Linear variable resistor	138
6.7.1	Thermal effects	139
6.7.2	Electrical noise	139
6.7.3	Measuring range	139
6.7.4	Operating speed	139
6.7.5	Frictional forces.	139
6.7.6	Track wear	141
6.8	Strain gauge conversion transducer	141
6.9	Remote inductive transducer	141
6.10	Remote capacitive transducer.	143
6.11	The magnetostrictive transducer	144
6.12	Magnetic sensor	144
6.13	The ultrasonic transducer	145
6.14	The fibre optic transducer	146
6.15	Optical wedge.	148
6.16	Optical potentiometer	148

7 Displacement transducers with digital output

7.1	Optical grating transducer	152
7.2	The linear diode array	155
7.3	Inductive element transducers	156

7.4	Optical interferometers	156
8	Dynamic measuring devices	
8.1	The accelerometer	159
8.1.1	Construction	159
8.1.2	Characteristics	160
8.1.3	Signal processing	161
8.2	Velocity transducers	161
8.2.1	Optical	161
8.2.2	Inductive	163
8.2.3	Capacitive	164
8.3	Laser Doppler-shift measurement	164
9	Miscellaneous methods	
9.1	Laser speckle photography	166
9.2	Flash photography	167
9.2.1	Black-and-white	167
9.2.2	Three-colour	168
10	Choice of displacement measurement system	170
Section C	Measurement of temperature	173
11	Temperature measurements	175
11.1	Platinum resistance thermometer	176
11.1.1	Fundamental interval	176
11.1.2	Physical forms	176
11.1.3	External circuitry	177
11.1.4	Linearisation	178
11.1.5	Connecting leads	178
11.1.6	Signal presentation	178
11.1.7	Performance	178
11.1.8	Self-heating effects	180
11.2	Nickel resistance thermometers	180
11.3	Thermocouple systems	181
11.3.1	Advantages of the thermocouple	181
11.3.2	Disadvantages of the thermocouple	181
11.3.3	The measuring junction	181
11.3.4	Reference junction	182
11.3.5	Connecting leads	182
11.3.6	Compensating cables	183
11.3.7	Choice of thermocouple type	183
11.3.8	Annealing	183
11.3.9	Signal measurement	183
11.3.10	Resolution, accuracy, stability	184
11.4	The thermistor	184
11.4.1	Thermistor construction	184
11.4.2	Circuitry	185

11.4.3	Performance	185
11.5	Semiconductor sensors	185
11.5.1	Passive integrated sensors	186
11.6	Integrated circuits	186
11.7	Infra-red thermometry	186
11.7.1	Field of view	188
11.7.2	Performance	189
11.7.3	Resolution	189
11.7.4	Circuitry	189
11.7.5	Infra-red scanning devices	189
11.8	Fibre optics	192
11.8.1	The 'Fluoroptic' TM thermometer	192
11.8.2	Performance	193
11.8.3	Interferometric sensing	193
11.9	The quartz crystal thermometer	193
11.10	Thermally sensitive paints	194
11.10.1	Limitations	194
11.10.2	Temperature-sensitive labels	195
11.11	Liquid crystals	196
11.11.1	Recording liquid crystal colours	197
11.12	Expansion of fluids	197
11.12.1	Dial thermometers	199
11.13	Expansion of solids	199
11.14	Choice of temperature measurement system	200
11.14.1	The die	200
11.14.2	Other components	201
11.14.3	Tablets	201
Section D Data handling: methods and equipment		203
12	Data handling	
12.1	Introduction	205
12.1.1	Electrical noise	205
12.1.2	Mains filters	206
12.1.3	Transient suppressors	207
12.1.4	Power supplies	208
12.1.5	Excitation level	208
12.2	Dealing with rotary machines	210
12.2.1	Radio telemetry	210
12.2.2	Slip-ring gear	214
12.2.3	Optical linkage	215
12.2.4	Biotelemetry transmitters	219
12.3	Signal amplification	219
12.3.1	Variable voltage	220
12.3.2	Variable current	220
12.3.3	Current loop or FM?	220
12.4	Signal display	221

- 12.4.1 Oscilloscope 221
- 12.4.2 The ultraviolet recorder 224
- 12.5 Signal conversion: A to D 226
- 12.6 Interfacing to the microcomputer. 227
 - 12.6.1 Commercial data-acquisition packages. 229
- 12.7 Microprocessor bus systems 231
 - 12.7.1 'Smart Cable'TM 231
 - 12.7.2 Screened bus cable 233

- Part II Practice 235**

- 13 Measurement of punch forces**
- 13.1 Requirements of accuracy 237
- 13.2 The single-punch machine 238
 - 13.2.1 Upper punch force 238
 - 13.2.2 Lower punch force 250
- 13.3 Rotary tablet machines 257
 - 13.3.1 The machine frame 257
 - 13.3.2 The roll-pin 262
 - 13.3.3 The pressure roll. 267
 - 13.3.4 The punch. 269
 - 13.3.5 Electrical connexions. 271
 - 13.3.6 Precompression force measurement 273
 - 13.3.7 Ejection force 274
 - 13.3.8 Punch pull-up force 282

- 14 Die wall stress**
- 14.1 Nelson's three-punch die 288
- 14.2 Windheuser's segmented die. 289
 - 14.2.1 Calibration 289
- 14.3 Ridgway's photoelastic die 290
- 14.4 Further studies with segmented dies 290
- 14.5 Problems with the segmented die. 291
- 14.6 Other die constructions 295
- 14.7 Current practice. 295

- 15 Displacement measurements**
- 15.1 Single-punch tablet machines 299
 - 15.1.1 Correction for applied force 299
 - 15.1.2 Choice of scale length 300
 - 15.1.3 Problems with short-scale transducers 300
 - 15.1.4 The LVDT with large radial clearance 300
 - 15.1.5 Requirements of accuracy 301
 - 15.1.6 Machine distortion errors 301
 - 15.1.7 Using balanced transducers 302
 - 15.1.8 Strain in the punches 304
 - 15.1.9 Other displacement transducers 304

15.2	Rotary tablet machines	305
15.2.1	Measurement errors in the rotary press	305
15.2.2	Retaining balance in the turret	306
16	Temperature measurements	
16.1	Importance of temperature measurement	311
16.2	Use of thermocouples	312
16.3	Thermochromic compounds	312
16.4	Calorimetry	313
16.5	Liquid crystals	313
16.6	Infra-red thermography	314
16.7	Energy computations	315
16.8	Multiple compressions	316
17	Calibration of transducer systems	
17.1	Fundamental standards	318
17.2	Fundamental units	319
17.2.1	Mass	319
17.2.2	Length	319
17.2.3	Time	319
17.2.4	Temperature	320
17.3	Derived units	320
17.3.1	Force	320
17.3.2	Work	320
17.3.3	Pressure	320
17.4	Practical standards	320
17.5	The calibration chain	321
17.5.1	Force	321
17.5.2	Displacement	325
17.5.3	Temperature	332
17.6	Calibration problems	332
18	Tablet weight	
18.1	General considerations	335
18.2	Standards for tablet weight uniformity	335
18.2.1	The British Pharmacopoeia 1980	335
18.2.2	The United States Pharmacopoeia: USP XXI (1985)	336
18.3	Tablet weight variations in commercial practice	337
18.4	Monte Carlo simulation	337
18.5	Effects of processing	338
18.6	Causes of weight variation	338
18.6.1	Powder flow	339
18.6.2	Separation of particle sizes	343
18.6.3	Effect of machine operating speed	343
18.6.4	Using one station of tooling	345
18.6.5	Machine effects	345

18.6.6	The relation between punch force and tablet weight	350
18.6.7	Tablet weight control systems	350
19	Post-compressional measurements	
19.1	Post-compressional relaxation	357
19.1.1	Stages of compaction	357
19.1.2	Stress relaxation	358
19.1.3	Effect of punch velocity	359
19.1.4	Multiple compression	359
19.1.5	Strain recovery	360
19.1.6	Measurements	361
19.2	Surface area	365
19.3	Acoustic emission	366
19.4	Capping	367
19.5	Acoustic emission and stress release	369
19.6	Moisture measurement in compacts	370
19.7	Electrical measurements	370
19.8	External appearance	371
19.9	Other physical properties	371
19.9.1	Tablet hardness	371
19.9.2	The Monsanto (or Stokes) tester	373
19.9.3	The Strong-Cobb	374
19.9.4	The Pfizer tester	374
19.9.5	The Erweka	375
19.9.6	Schleuniger (or Heberlein)	375
19.9.7	Erweka Electronic	377
19.9.8	Pharma Test	378
19.9.9	Microspan Contestar	378
19.10	Diametral compression in tablet hardness measurement	379
19.10.1	The effect of loading rate on apparent tablet hardness	381
19.11	Comparison of different hardness testers	382
19.12	Testing by flexure	383
19.12.1	Three-point bending	383
19.12.2	Four-point bending	385
19.13	Young's Modulus determination by acoustic measurement	386
19.14	Surface hardness	387
19.15	Direct tensile strength measurement	388
19.16	Brittle fracture index	388
19.17	Friability	388
19.18	Disintegration	390
19.19	Dissolution	390
20	Interpretation of data	
20.1	What is the value of instrumentation?	397
20.2	Compaction force limits	399
20.3	Compaction profiles	402
20.4	Work of compaction	405

20.5	Stress relaxation and viscoelasticity	408
20.6	The Heckel equation	411
20.7	Compactibility	413
20.8	Material variations	416
20.8.1	Particle size	416
20.8.2	Particle shape and crystal form.	418
20.8.3	Method of preparation	419
20.9	Evaluation of lubricants.	421
20.10	General	422
Conclusion		429
Suppliers of materials and services		435
Index		442