## Werner Schweika

## Disordered Alloys

Diffuse Scattering and Monte Carlo Simulations

With 48 Figures



## Contents

1. Introduction				1	
2.	Diffuse Scattering of Alloys				
	2.1		luction	5	
	2.2		dered Solid Alloys	8	
	2.3	Short-	Range Order	11	
	2.4	Lattic	e Displacements	14	
	2.5	Data	Analysis	22	
	2.6	Exper	imental Considerations	26	
3.	Mo	nte Ca	arlo Simulations of Alloys	31	
	3.1	Ising I	Models	31	
	3.2	Metro	polis Monte Carlo Method	35	
	3.3	Rever	se Monte Carlo Method	39	
	3.4	Invers	e Monte Carlo Method	41	
	3.5	Comn	nents on the Uniqueness of the Models and Methods	43	
4.	Applications				
	4.1	Cluste	ering Alloys	51	
		4.1.1	Solubility of Co in Cu	54	
		4.1.2	Decomposition in the Cu-Ni Alloy System	55	
	4.2	Order	ing Alloys	58	
		4.2.1	Chemical Order in Ferromagnetic Fe–Al Alloys	58	
		4.2.2	Short-Range Order and Interactions in the Ni–Cr System	64	
		4.2.3	The Temperature Dependence of Short-Range Order		
			in Cu–Zn	70	
	4.3	Inters	titial Alloys	74	
		4.3.1	The Defect Structure of Ferrous Oxide $Fe_{1-x}O$	74	
		4.3.2	Short-Range Order and Interactions in the Metal Hy-		
			dride $VD_x$	83	
	4.4	Surfac	ce-Induced Ordering and Disordering	90	
		4.4.1	Surface-Induced Disorder	92	
		4.4.2	Surface-Induced Order due to Reduced Frustrations	96	
		4.4.3	Surface-Induced Order due to Effective Surface Fields .	98	

X	Contents	
5.	Summary and Conclusions	05
Rei	erences	11
Ind	ex	21