

Pramod K. Rastogi (Ed.)

Photomechanics

With 314 Figures



Springer

Contents

Optics for Engineers

Daniel Malacara-Hernández	1
1. Introduction	1
2. Geometrical Optics Principles	1
2.1. Fermat's Principle and the Law of Refraction	1
2.2. First-Order Optics	3
2.3. Aberrations	7
3. Wave-Optics Fundamentals	12
3.1. Young's Double Slit	12
3.2. Michelson Interferometer	13
3.3. Coherence and Light Sources	14
4. Main Interferometers Used in Optical Engineering	15
4.1. Fizeau Interferometer and Newtons Rings	16
4.2. Twyman-Green Interferometer	19
4.3. Ronchi and Lateral-Shear Interferometers	22
4.4. Talbot Interferometer and Moiré Deflectometry	26
4.5. Foucault Test and Schlieren Techniques	27
4.6. Two-Wavelength Interferometry	28
4.7. Holographic Principles	29
5. Summary	31
References	31

Introduction to Engineering Mechanics

Anand Asundi	33
1. Introduction	33
2. Basic Concepts	34
2.1. Stress	34
2.2. Stress Transformation	35
2.3. Stress Transformation Using Mohr's Circle	36
2.4. Displacement and Strain	37
2.5. Strain Transformation	39
2.6. Stress-Strain Relations	40
2.7. Boundary Conditions	41
3. Theory of Elasticity Approach	42
3.1. Plane Stress Formulation	44
3.2. Plane Strain Formulation	45

4. Strength of Materials Approach 46

5. Examples 47

 5.1. Axial Loading 47

 5.2. Bending of Beams 49

 5.3. Combined Bending and Axial Load 52

6. Conclusion 53

Further Reading 54

Fringe Analysis

Yves Surrel 55

1. Introduction 55

2. Phase Evaluation 57

 2.1. Local and Global Strategies 57

 2.2. Local Phase detection 58

 2.3. Global Phase Detection 77

 2.4. Residual Phase Errors 81

 2.5. Effect of Additive Noise 84

3. Phase Unwrapping 86

 3.1. Spatial Approach 87

 3.2. Temporal Approach 89

4. Conclusion 94

References 99

Principles of Holographic Interferometry and Speckle Metrology

Pramod K. Rastogi 103

1. Holographic Interferometry 103

 1.1. Types of Holographic Interferometry 104

 1.2. Thermoplastic Camera 107

 1.3. Mapping of the Resolved Part of Displacement 109

 1.4. Determination of the Wavefront Phase

 Using Phase-shifting Interferometry 110

 1.5. Out-of-plane Displacement Measurement 111

 1.6. In-plane Displacement Measurement 112

 1.7. Holographic Shearing Interferometry 115

 1.8. Comparative Holographic Interferometry 117

 1.9. Vibration Analysis 119

2. Speckle Metrology 124

 2.1. Focused Speckle Photography 125

 2.2. Defocused Speckle Photography 128

 2.3. Speckle Shearing Photography 129

 2.4. Speckle Interferometry 131

 2.5. Speckle Shearing Interferometry 140

3. Conclusions145
 References145

**Moiré Methods for Engineering and Science –
 Moiré Interferometry and Shadow Moiré**

Daniel Post, Bongtae Han, and Peter G. Ifju151

1. Introduction 151
 2. Moiré Interferometry 152
 2.1. Basic Concepts 152
 2.2. Equipment 156
 2.3. Specimen Gratings 157
 2.4. Bithermal Loading (Isothermal Loading) 158
 2.5. Fringe Counting 158
 2.6. Strain Analysis 160
 2.7. Carrier Fringes 160
 2.8. Out-of-Plane Deformation 162
 3. Advanced Techniques in Moiré Interferometry 164
 3.1. Microscopic Moiré Interferometry 164
 3.2. Curved Surfaces 166
 3.3. Replication of Deformed Gratings 170
 4. Diverse Applications of Moiré Interferometry 171
 4.1. Thermal Deformations of Microelectronics Devices 171
 4.2. Textile Composites 173
 4.3. Fracture Mechanics 176
 4.4. Micromechanics: Grain Deformations 177
 5. Shadow Moiré 180
 5.1. Basic Concepts 180
 5.2. Additional Considerations 183
 6. Increased Sensitivity, Shadow Moiré 184
 6.1. Phase Stepping (or Quasi-heterodyne) Method 184
 6.2. Optical/Digital Fringe Multiplication (O/DFM) 185
 7. Applications of Shadow Moiré 185
 7.1. Post-buckling Behavior of a Composite Column 185
 7.2. Pre-buckling Behavior of an Aluminum Channel 189
 7.3. Warpage of Electronic Devices 191
 References194

Digital Photoelasticity

Terry Y. Chen197

1. Basic Principles of Photoelasticity 197
 1.1. Light and Complex Notation 197
 1.2. Polarization of Light 198
 1.3. Retardation 200
 1.4. Optical Media 200
 1.5. The Stress-Optic Law 202

1.6. Plane Polariscope	204
1.7. Circular Polariscope	207
2. Computer Evaluation of Photoelastic Fringe Patterns	210
2.1. Digital Image Processing	211
2.2. Extraction of Fringe Point	213
2.3. Fringe Multiplication	213
2.4. Determination of the Isochromatic Fringe Order	215
2.5. Determination of Principal Stress Direction	222
3. Applications of Evaluated Data	226
3.1. Stress Analysis	226
3.2. Examples	227
4. System and Error Assessment	227
5. Conclusions	230
References	230

Optical Fiber Strain Sensing in Engineering Mechanics

James S. Sirkis	233
1. Intrinsic Fabry-Perot Sensor	234
1.1. Optical Arrangement	234
1.2. Response to Strain and Temperature	236
1.3. Sensor Multiplexing	239
2. Extrinsic Fabry-Perot Strain Sensor	239
2.1. Optical Arrangement	241
2.2. Response to Strain and Temperature	242
2.3. Self-temperature Compensation	243
2.4. EFP Sensor Variants	244
2.5. Sensor Multiplexing	246
3. Bragg Grating Strain Sensor	246
3.1. Bragg Grating Fabrication	247
3.2. Strain and Temperature Response	250
3.3. Effects of Gradients	250
3.4. Bragg Grating Reliability	251
3.5. Sensor Multiplexing	251
4. Fiber-Optic Coatings and Cables	253
5. Commercial Packaging	256
6. Sensor Bonding Techniques	257
7. Demodulation	258
7.1. Serrodyne Fringe Counting (IFP Sensors)	259
7.2. White Light Cross-Correlator (EFP Sensors)	260
7.3. Scanning Fabry-Perot Filter (Bragg Grating Sensors)	262
7.4. Spectral Interrogation (EFP Sensors)	263
7.5. Other Demodulators	266
8. Sensor Comparison	266
References	269

Long-Gage Fiber-Optic Sensors for Structural Monitoring	
Daniele Inaudi	273
1. Introduction: Monitoring versus Measuring Structures	273
2. Long-Gage versus Short-Gage Sensors	274
3. Interferometric Sensors	275
3.1. Optical Arrangements	276
3.2. Strain and Temperature Sensitivity	276
3.3. Demodulation Techniques	277
3.4. Sensor Packaging	280
3.5. Application Example: Monitoring the Versoix Bridge	283
4. Intensity-Based Sensors	284
5. Brillouin-Scattering Sensors	286
5.1. Principles	286
5.2. Measurement Techniques	287
5.3. Sensor Packaging	289
5.4. Application Example: Temperature Monitoring of the Luzzzone Dam	290
6. Outlook	291
7. Conclusions	291
References	292
 Techniques for Non-Birefringent Objects:	
Coherent Shearing Interferometry and Caustics	
Sridhar Krishnaswamy	295
1. Introduction	295
2. Elasto-Optic Relations	297
2.1. Optical Phase Shift due to Transmission through an Optically Isotropic Linear Elastic Medium	297
2.2. Optical Phase-Shift due to Reflection from a Polished Surface	298
3. Shearing Interferometry	299
3.1. A Dual-Grating Shearing Interferometer – The Coherent Gradient Sensor (CGS)	300
3.2. A Polarization-Based Shearing Interferometer: Compact Polariscope / Shearing Interferometer (PSI)	304
4. Optical Caustics	309
5. Applications	311
5.1. Compressive Line Load on the Edge of a Plate	312
5.2. Fracture Mechanics	315
6. Conclusion	319
References	319

**Advances in Two-Dimensional
and Three-Dimensional Computer Vision**

Michael A. Sutton, Stephen R. McNeill, Jeffrey D. Helm,
and Yuh J. Chao 323

1. Introduction 323

2. Theory and Numerical Implementation 326

 2.1. Two-Dimensional Video Image Correlation 326

 2.2. Three-Dimensional Video Image Correlation 334

3. Applications 343

 3.1. Two-Dimensional Video Image Correlation 343

 3.2. Three-Dimensional Video Image Correlation 354

4. Discussion 366

5. Summary 367

References 368

**Laser Doppler and Pulsed Laser Velocimetry
in Fluid Mechanics**

Jeremy M. Coupland 373

1. Introduction 373

 1.1. The Scattering and Dynamic Properties of Seeding Particles . 375

2. Laser Doppler Velocimetry (LDV) 376

 2.1. Fundamentals of LDV 376

 2.2. Fourier Optics Model of LDV 381

 2.3. The Doppler Signal and Signal Processing 386

 2.4. LDV Measurements in Practice 389

3. Planar Doppler Velocimetry (PDV) 391

4. Pulsed Laser Velocimetry 395

 4.1. Particle Image Velocimetry (PIV) 395

 4.2. Removal of Directional Ambiguity 399

 4.3. PIV Measurements in Practice 400

 4.4. Three-Dimensional PIV 402

 4.5. Holographic Particle Image Velocimetry (HPIV) 402

5. Conclusions, Discussion and Future Development 408

References 410

**Surface Characterization and Roughness Measurement
in Engineering**

David J. Whitehouse 413

1. General 413

 1.1. Historical 413

 1.2. Nature and Importance of Surfaces 414

 1.3. Trends 416

2. Instrumentation 419

 2.1. General Points 419

2.2. The Stylus	422
2.3. Basic Instrument	425
2.4. The Stylus Method (Mechanical)	427
2.5. The Optical Methods	428
2.6. Other Conventional Methods	433
2.7. Non-conventional Methods	433
3. Pre-Processing and Filtering	433
3.1. Levelling	433
3.2. Curve Fitting for Form	433
3.3. Filtering for Waviness	434
4. Parameters	439
4.1. General	439
4.2. Height Parameters (see [36] for example)	440
4.3. Peak Parameters	441
4.4. Spacing Parameters	442
4.5. Peak Parameters (Statistical)	443
4.6. Hybrid Parameters	445
4.7. Effects of Filtering on Parameter Values	445
5. Random Process Analysis in Surface Metrology	446
5.1. General	446
5.2. Height Information	446
5.3. Spacing Information	447
6. Areal (or Three-Dimensional) Parameters	453
6.1. General	453
6.2. Comments on Areal Measurement	454
7. Conclusions	458
References	459
Index	463