

Particle Size Measurement

Volume 2

Surface area and pore size determination

Fifth edition

TERENCE ALLEN

*Formerly Senior Consultant
E.I. DuPont de Nemours and Company
Wilmington, Delaware, USA*



CHAPMAN & HALL

London · Weinheim · New York · Tokyo · Melbourne · Madras

Contents

Acknowledgments	xi
Preface to fifth edition	xiii
Preface to first edition	xv
Editor's foreword	xvii
1. Permeametry and gas diffusion	1
1.1 Flow of a viscous fluid through a packed bed of powder	1
1.2 The aspect factor k	4
1.3 Other flow equations	6
1.4 Experimental applications	11
1.5 Bed preparation	12
1.6 Constant flow rate permeameters	12
1.6.1 The Lea and Nurse permeameter	12
1.6.2 The Fisher sub-sieve sizer	13
1.7 Constant volume permeameters	16
1.7.1 The Blaine apparatus	16
1.7.2 The Griffin Surface Area of Powder Apparatus	18
1.7.3 Reynolds and Branson autopermeameter	18
1.7.4 Pechukas and Gage permeameter	18
1.8 Types of flow	19
1.9 Transitional region between viscous and molecular flow	20
1.10 Calculation of permeability surface	21
1.11 An experimental approach to the two-term permeametry equation	23
1.12 Diffusional flow for surface area measurement	24
1.13 The relationship between diffusion constant and specific surface	26
1.14 Non-steady state diffusional flow	27
1.15 Steady state diffusional flow	29
1.16 The liquid phase permeameter	32
1.17 Application to hindered settling	32
1.18 Turbo Powdersizer Model TPO-400 In-Line Grain Analyzer	33
1.19 Permoporometry	33
1.19.1 Theory	33

2	Surface area determination by gas adsorption	39
2.1	Introduction	39
2.2	Langmuir theory	40
2.3	Equation of state	41
2.4	Comparison between Langmuir and BET methods	41
2.4.1	BET theory	41
2.4.2	Langmuir–BET theory	42
2.4.3	Langmuir–BET–Harkins–Jura theory	43
2.4.4	Langmuir–BET–Harkins–Jura–Hüttig theory	43
2.4.5	Langmuir–BET–Harkins–Jura–Hüttig–Frenkel–Halsey–Hill theory	43
2.4.6	Langmuir–BET–Harkins–Jura–Hüttig–Frenkel–Halsey–Hill–V–t curve theory	43
2.5	Polymer	43
2.6	Equations	43
2.6.1	Dubinin–Auskashov equation	60
2.6.2	Dubinen–Kaganer equation	60
2.7	Jovanovic equations	61
2.8	Hüttig equation	62
2.9	Harkins and Jura relative method	62
2.10	Comparison between BET and HJr methods	64
2.11	Frenkel–Halsey–Hill equation	64
2.12	V–t curve	65
2.13	Kiselev's equation	66
2.14	Experimental techniques	68
2.14.1	Introduction	68
2.15	Volumetric methods	68
2.15.1	Volumetric methods for high surface areas	68
2.15.2	Volumetric methods for low surface areas	70
2.16	Gravimetric methods	71
2.16.1	Single spring balances	72
2.16.2	Multiple spring balances	72
2.16.3	Beam balances	73
2.17	Flow, thermoconductivity methods	74
2.18.	Sample preparation	78
2.18.1	Degassing	78
2.18.2	Pressure	78
2.18.3	Temperature and time	79
2.18.4	Adsorbate.	79
2.18.5	Interlaboratory tests	81
2.19	Standard volumetric gas adsorption apparatus	81
2.19.1	Worked example using BS 4359 standard apparatus	83
2.20	Haynes apparatus	86
2.21	Commercial equipment	86

2.21.1	Static volumetric apparatus	86
2.21.2	Continuous flow gas chromatographic methods	92
2.21.3	Gravimetric methods	96
3	Determination of pore size distribution by gas adsorption	104
3.1	Introduction	104
3.2	The Kelvin equation	105
3.3	The hysteresis loop	108
3.4	Theoretical evaluation of hysteresis loops	111
3.4.1	Cylindrical pore model	111
3.4.2	Ink-bottle pore model	112
3.4.3	Parallel plate model	113
3.5	Classification of pores	113
3.6	Relationship between the thickness of the adsorbed layer and the relative pressure	114
3.7	Non-linear $V-t$ curves	119
3.8	The α_s method	120
3.9	The n_S-n_R method	121
3.10	Relationship between gas volume and condensed liquid volume for nitrogen	121
3.11	Pore size determination	122
3.11.1	Modelless method	122
3.11.2	Cylindrical core model	127
3.11.3	Cylindrical pore model	127
3.11.4	Parallel plate model	131
3.12	Network theory	136
3.13	Analysis of micropores; the MP method	138
3.14	Density functional theory	143
3.15	Benzene desorption	143
3.16	Other adsorbates	144
4	Pore size determination by mercury porosimetry	149
4.1	Introduction	149
4.2	Relationship between pore radii and intrusion pressure	150
4.3	Equipment fundamentals	151
4.4	Incremental mode	153
4.5	Continuous mode	154
4.6	Discussion	155
4.7	Limitations of mercury porosimetry	157
4.8	Effect of interconnecting pores	159
4.9	Hysteresis	159
4.10	Contact angle for mercury	161
4.10.1	Effect of contact angle	162
4.11	Surface tension of mercury	162
4.12	Corrections for compressibility	163
4.13	Structural damage	165

4.14	Delayed intrusion	165
4.15	Theory for volume distribution determination	166
4.16	Theory for surface distribution determination	167
4.16.1	Cylindrical pore model	167
4.16.2	Modelless method	167
4.17	Theory for length distribution determination	168
4.18	Illustrative examples	169
4.18.1	Narrow size range	169
4.18.2	Wide size range	169
4.19	Commercial equipment	175
4.19.1	Incremental mode	175
4.19.2	Incremental and continuous mode	175
4.19.3	Continuous mode	176
4.20	Anglometers	177
4.21	Assessment of mercury porosimetry	179
4.21.1	Effect of experimental errors	179
4.22	Mercury porosimetry report	180
4.22.1	Data	181
4.23	Liquid porosimetry	182
4.24	Applications	187
5	Other methods for determining surface area	191
5.1	Introduction	191
5.2	Determination of specific surface from size distribution data	192
5.2.1	Number distribution	192
5.2.2	Surface distribution	193
5.2.3	Volume (mass) distribution	193
5.3	Turbidity methods of surface area determination	195
5.4	Adsorption from solution	196
5.4.1	Molecular orientation at the solid–liquid interface	197
5.4.2	Polarity of organic liquids and adsorbents	198
5.4.3	Drying of organic liquids and adsorbents	200
5.5	Theory for adsorption from solution	200
5.6	Methods for determining the amount of solute adsorbed	201
5.6.1	Langmuir trough	202
5.6.2	Gravimetric methods	202
5.6.3	Volumetric method	202
5.6.4	Rayleigh interferometer	203
5.6.5	Precolumn method	203
5.7	Experimental procedures for adsorption from solution	203
5.7.1	Non-electrolytes	203
5.7.2	Fatty acids	203
5.7.3	Polymers	204
5.8	Adsorption of dyes	204
5.9	Adsorption of electrolytes	206

5.10	Deposition of silver	206
5.11	Adsorption of <i>p</i> -nitrophenol	206
5.12	Chemisorption	207
	5.12.1 Hydrogen	207
	5.12.2 Oxygen	207
	5.12.3 Carbon monoxide	208
5.13	Other systems	208
5.14	Theory for heat of adsorption from a liquid phase	209
	5.14.1 Surface free energy of a fluid	209
	5.14.2 Surface entropy and energy	210
	5.14.3 Heat of immersion	210
5.15	Static calorimetry	211
5.16	Flow microcalorimetry	213
	5.16.1 Experimental procedures – liquids	213
	5.16.2 Calibration	215
	5.16.3 Precolumn method	215
	5.16.4 Experimental procedure – gases	216
	5.16.5 Applications to surface area determination	217
5.17	Density methods	217
	Appendix: Names and addresses of manufacturers and suppliers	224
	Author index	239
	Subject index	248