

Design of Brushless Permanent-Magnet Motors

J.R. Hendershot Jr.

General Manager
Magna Physics Tridelta
Hillsboro, OHIO 45133

TJE Miller

Lucas Professor in Power Electronics
Director, SPEED Consortium
University of Glasgow, UK

MAGNA PHYSICS PUBLISHING
AND
CLarendon Press • oxford
1994

Contents

1.	GENERAL INTRODUCTION	
<i>J.R. Hendershot Jr.</i>		
1.1	Definitions and types of brushless motor	1-1
1.2	Commutation	1-5
1.3	Performance characteristics	1-12
1.4	Shaft position sensing	1-19
2.	MOTOR AND CONTROLLER TYPES	
<i>J.R. Hendershot Jr. and TJE Miller</i>		
2.1	Introduction	2-1
2.2	Interior-rotor motors	2-2
2.3	Exterior-rotor motors	2-8
2.4	Pancake or disc-type brushless motors	2-10
2.5	Slotless motors	2-12
2.6	Controllers—basic principles	2-14
2.7	The single phaseleg—the basic power electronic switch . . .	2-15
2.8	Power semiconductor devices	2-18
2.9	Voltage PWM and current regulation	2-21
2.10	Full-bridge circuits for 1- and 2-phase drives	2-23
2.11	Three-phase full-bridge circuit	2-27
2.12	Three-phase squarewave control strategies	2-31
2.13	Maximum AC sinewave voltage	2-38
2.14	Provision of DC supply voltage	2-39
2.15	Controller architecture	2-39
	<i>2.15.1 Cost issues</i>	2-39
	<i>2.15.2 Squarewave drives</i>	2-40
	<i>2.15.3 Sinewave drives</i>	2-46
	<i>2.15.3 Unipolar drive</i>	2-47
2.16	Commutation test circuit	2-47
3.	BASIC DESIGN CHOICES	
<i>J.R. Hendershot Jr.</i>		
3.1	Introduction	3-1
3.2	Interior rotor, exterior rotor, or axial gap configuration? .	3-3
3.3	Number of phases	3-3
3.4	Number of stator slots and poles	3-4
3.5	Caution with the basic laws of electromagnetism	3-14

CONTENTS

3.6	Simplified motor design	3-18
3.6.1	<i>Simple design formulas for the EMF and torque constants</i>	3-18
3.6.2	<i>Simple calculation of the flux</i>	3-20
3.6.3	<i>Basic sizing rules</i>	3-23
3.7	Lamination and stator stack design	3-27
3.8	Winding arrangements	3-34
3.8.1	<i>Coil span</i>	3-34
3.8.2	<i>Coils per pole</i>	3-35
3.8.3	<i>Winding configurations—fractional and integral slot</i>	3-38
3.8.4	<i>Wire size calculations</i>	3-68
3.8.5	<i>Basic winding calculations</i>	
3.9	Examples of motor construction	3-69

4. MAGNETIC DESIGN

TJE Miller

4.1	Introduction	4-1
4.2	Permanent magnets and magnetic circuits	4-3
4.3	Approximate calculation of the flux	4-10
4.4	Nonlinear calculation of the magnetic circuit	4-16
4.5	Armature reaction and demagnetization	4-18
4.6	Calculation of rotor leakage permeance	4-23
4.7	Cogging	4-26
4.9	Retaining can losses	4-28

5. ELECTRICAL DESIGN

TJE Miller

5.1	Introduction	5-1
5.2	Basic windings	5-1
5.2.1	<i>Squarewave motor</i>	5-1
5.2.2	<i>Effect of additional coils</i>	5-6
5.2.3	<i>Lap windings and concentric windings</i>	5-9
5.2.4	<i>Multiple-pole machines</i>	5-11
5.2.5	<i>Consequent-pole windings and magnets</i>	5-12
5.2.6	<i>Computer-aided design of windings</i>	5-13
5.3	Wye and delta connections	5-14
5.3.1	<i>Wye connection, with 120° trapezoidal phase EMF</i>	5-14
5.3.2	<i>Delta connection</i>	5-21
5.3.3	<i>Flux/pole and magnet utilization</i>	5-31

CONTENTS

5.4	Unipolar 3-phase connection	5-32
5.5	Two-phase and single-phase connections	5-32
5.6	The EMF constant k_E	5-35
5.7	The torque constant k_T	5-36
	<i>5.7.1 Basis of torque production — coenergy</i>	5-36
	<i>5.7.2 Torque linearity</i>	5-38
	<i>5.7.3 Demagnetization</i>	5-38
5.8	Calculating the number of turns	5-38
5.9	Winding inductances and armature reaction	5-39
	<i>5.9.1 Importance of inductance</i>	5-39
	<i>5.9.2 Inductance components</i>	5-42
	<i>5.9.3 Airgap self-inductance of single coil</i>	5-44
	<i>5.9.4 Airgap mutual inductance between two coils</i>	5-46
	<i>5.9.5 Examples of inductance calculations</i>	5-48
	<i>5.9.6 General case of airgap inductance</i>	5-51
	<i>5.9.7 Slot-leakage inductance : self and mutual</i>	5-55
	<i>5.9.8 End-winding inductance</i>	5-59
5.10	Slotless windings	5-61
	<i>5.10.1 General</i>	5-61
	<i>5.10.2 Design theory for slotless windings</i>	5-63

6. SINEWAVE MOTORS

TJE Miller

6.1	Introduction	6-1
	<i>6.1.1 The ideal sinewave motor</i>	6-1
	<i>6.1.2 Practical motors designed to approximate the sinewave motor</i>	6-2
6.2	Properties of sine-distributed windings	6-4
	<i>6.2.1 Conductor and ampere-conductor distributions</i>	6-4
	<i>6.2.2 Airgap flux produced by sine-distributed winding</i>	6-4
	<i>6.2.3 Self flux-linkage and inductance of sine-distributed winding</i>	6-6
	<i>6.2.4 Mutual inductance between sine-distributed windings</i>	6-8
	<i>6.2.5 Generated EMF</i>	6-9
	<i>6.2.6 Torque</i>	6-10
	<i>6.2.7 Rotating flux and ampere-conductors</i>	6-10
	<i>6.2.8 Vector control or "field-oriented" control</i>	6-11
	<i>6.2.9 Synchronous reactance</i>	6-12
6.3	Real windings	6-13
	<i>6.3.1 Full-pitch coil</i>	6-13
	<i>6.3.2 Short-pitch coil</i>	6-14

CONTENTS

6.3.3	<i>Distribution or spread</i>	6-17
6.3.4	<i>General case</i>	6-19
6.3.5	<i>Skew</i>	6-21
6.3.6	<i>Design formulas for practical windings</i>	6-21
6.4	Salient-pole motors	6-23
6.4.1	<i>Calculation of X_d</i>	6-23
6.4.2	<i>Calculation of X_q</i>	6-31
6.4.3	<i>Demagnetizing effect of d-axis flux due to I_d</i>	6-33
6.4.4	<i>Cross-magnetizing effect of q-axis flux due to I_q</i>	6-33
6.4.5	<i>Significance of rotor leakage</i>	6-33
6.5	Phasor diagram	6-35
6.5.1	<i>Non-salient-pole machines</i>	6-35
6.5.2	<i>Salient-pole machines</i>	6-36
6.5.3	<i>Operation as a generator</i>	6-39
6.6	Circle diagram and speed/torque characteristic	6-42
6.6.1	<i>Non-salient-pole motors with $X_d = X_q$</i>	6-42
6.6.2	<i>Salient-pole motors with $X_d \neq X_q$</i>	6-47
7.	K_T AND K_E	
<i>TJE Miller</i>		
7.1	Introduction	7-1
7.2	Squarewave and sinewave motors	7-2
7.3	Definition and measurement of k_T and k_E	7-3
7.3.1	<i>DC commutator motors</i>	7-3
7.3.2	<i>Three-phase squarewave brushless DC motors</i>	7-4
7.3.3	<i>Two-phase squarewave brushless DC motors</i>	7-7
7.3.4	<i>Two-phase sinewave brushless DC motors</i>	7-7
7.3.5	<i>Three-phase sinewave brushless DC motors</i>	7-8
7.3.6	<i>Summary</i>	7-10
7.4	Calculation of k_T and k_E	7-10
7.4.1	<i>Squarewave three-phase brushless DC motors</i>	7-11
7.4.2	<i>Two-phase sinewave brushless DC motors</i>	7-13
7.4.3	<i>Three-phase sinewave brushless DC motors</i>	7-15
7.5	Example calculation	7-16
8.	THE BACK-EMF WAVEFORM	
<i>TJE Miller and R. Rabinovici</i>		
8.1	Introduction	8-1
8.2	The <i>BLV</i> method	8-4

CONTENTS

8.3	Airgap flux-density distribution	8-5
8.4	Skew	8-7
8.5	Slotting	8-9
8.6	Calculating back-EMF from tooth flux	8-11
	<i>8.6.1 Single-tooth flux and EMF</i>	8-11
	<i>8.6.2 Accumulation of tooth flux</i>	8-13
	<i>8.6.3 Direct construction of tooth-EMF waveform</i>	8-14
8.7	Construction of the phase EMF from the e_T waveform	8-17
8.8	Development of yoke waveform from ϕ_T waveform	8-18
8.9	Cogging torque	8-19
9.	CORE LOSSES	
	<i>TJE Miller and R. Rabinovici</i>	
9.1	Introduction	9-1
9.2	Nonsinusoidal Steinmetz equation	9-3
9.3	Core-loss formulas	9-3
9.4	Waveform method	9-5
9.5	Augmentation of tooth weight	9-6
9.6	Comparison with test data	9-8
10.	ELECTRONIC COMMUTATION OF SQUAREWAVE MOTORS	
	<i>TJE Miller</i>	
10.1	Introduction	10-1
10.2	Basic principles	10-2
10.3	Circuit equations - wye	10-7
	<i>10.3.1 Commutation</i>	10-7
	<i>10.3.2 Period A and period B</i>	10-9
	<i>10.3.3 Chopping (regulation)</i>	10-10
	<i>10.3.4 State-space averaged voltages</i>	10-10
	<i>10.3.5 Euler form of voltage equations</i>	10-11
	<i>10.3.6 Initial conditions</i>	10-13
10.4	Circuit equations - delta	10-14
	<i>10.4.1 Commutation</i>	10-14
	<i>10.4.2 Period A and period B</i>	10-17
	<i>10.4.3 Chopping (regulation)</i>	10-18
	<i>10.4.4 State-space averaged voltages</i>	10-18
	<i>10.4.5 Euler form of voltage equations</i>	10-19
	<i>10.4.6 Initial conditions</i>	10-20

CONTENTS

10.5	Unipolar half-bridge controller	10-23
	10.5.1 <i>Commutation</i>	10-23
	10.5.2 <i>Period A and period B</i>	10-24
	10.5.3 <i>Chopping (regulation)</i>	10-24
	10.5.4 <i>State-space averaged values</i>	10-25
	10.5.6 <i>Initial conditions and final DC values</i>	10-26
10.6	Over-running	10-27
10.7	Practical examples and comparison with test data	10-28
	10.7.1 <i>Comparison of measured and computed waveforms</i>	10-28
	10.7.2 <i>Accurate calculation of no-load speed</i>	10-30
11.	PERFORMANCE EVALUATION BY TEST	
	<i>J.R. Hendershot Jr.</i>	
11.1	Introduction	11-1
11.2	Testing of PM brushless motors	11-1
	11.2.1 <i>Back-EMF testing</i>	11-2
	11.2.2 <i>Resistance and inductance</i>	11-4
	11.2.3 <i>Speed/torque curve and load tests</i>	11-6
	11.2.4 <i>Thermal resistance</i>	11-7
	11.2.5 <i>Torque linearity</i>	11-8
	11.2.6 <i>Torque ripple</i>	11-10
11.3	Magnetization testing	11-11
11.4	Precision dynamometer	11-12
12.	COMPUTER-AIDED DESIGN	
	<i>TJE Miller, D.A. Stanon and R.P. Deodhar</i>	
12.1	The modern design environment	12-1
12.2	Basic sizing guidelines	12-2
12.3	Computer-aided design with <i>PC-BDC</i>	12-6
12.4	Finite-element analysis	12-13
	12.4.1 <i>Introduction</i>	12-13
	12.4.2 <i>Pre-processing</i>	12-15
	12.4.3 <i>Field solution</i>	12-18
	12.4.4 <i>Post-processing</i>	12-19
12.5	Example : armature reaction in brushless DC motor	12-20
	12.5.1 <i>Open-circuit flux distribution</i>	12-21
	12.5.2 <i>Armature reaction field alone</i>	12-22
	12.5.3 <i>Cross-magnetization</i>	12-25
	12.5.4 <i>Demagnetization</i>	12-25

CONTENTS

13. EXAMPLES CALCULATED BY HAND

J.R. Hendershot Jr.

13.1	Introduction	13-1
13.2	Interior-rotor motor designed from AC induction motor .	13-2
13.3	Exterior-rotor disc drive motor design	13-16
13.4	Summary	13-26

14. CONTROL SYSTEMS PERFORMANCE

G. Gray

14.1	Introduction	14-1
14.2	Basic modelling tools for linear control systems	14-1
	<i>14.2.1 Laplace transforms</i>	14-1
	<i>14.2.2 Transfer functions</i>	14-5
	<i>14.2.3 Example of a DC or brushless DC motor</i>	14-5
14.3	Modelling drive components	14-7
	<i>14.3.1 Brushless PM motor model including inductance</i>	14-7
	<i>14.3.2 Mechanical and electrical time constants</i>	14-8
	<i>14.3.3 Transducers</i>	14-10
	<i>14.3.4 Load effects</i>	14-10
14.4	Control systems	14-10
	<i>14.4.1 Feedback and closed-loop control</i>	14-10
	<i>14.4.2 Speed controls and servo systems</i>	14-12
	<i>14.4.3 Speed control</i>	14-13
	<i>14.4.4 Position control</i>	14-13
	<i>14.4.5 Torque control</i>	14-14
	<i>14.4.6 Incremental motion control systems</i>	14-14
14.5	Characteristics of closed-loop control systems	14-15
	<i>14.5.1 Frequency response</i>	14-15
	<i>14.5.2 Bandwidth</i>	14-18
	<i>14.5.3 Step response</i>	14-18
	<i>14.5.4 Stability; gain and phase margins</i>	14-20
	<i>14.5.5 Steady-state error</i>	14-21
	<i>14.5.6 Integral gain compensation</i>	14-22
	<i>14.5.7 Root locus</i>	14-22
	<i>14.5.8 Second-order systems: critical damping</i>	14-24
14.6	Control systems—design	14-25
	<i>14.6.1 Lead/lag compensation</i>	14-26
	<i>14.6.2 Pole placement</i>	14-28

CONTENTS

14.6.3	<i>Robustness</i>	14-30
14.7	PID Controllers	14-31
14.7.1	<i>Design of a PID controller</i>	14-31
14.7.2	<i>Tuning a PID controller</i>	14-32
14.7.3	<i>Auto-tuning</i>	14-33
14.8	Digital control	14-34
14.8.1	<i>Discrete system theory</i>	14-34
14.8.2	<i>Z-transforms</i>	14-36
14.8.3	<i>Z transforms and difference equations</i>	14-38
14.8.4	<i>Stability of discrete systems</i>	14-38
14.8.5	<i>Digital control system design</i>	14-38
14.8.6	<i>Deadbeat controller</i>	14-39
14.8.7	<i>Digital PID</i>	14-39
14.8.8	<i>PID control example</i>	14-41
14.9	Advanced control techniques	14-43
14.9.1	<i>Adaptive control</i>	14-43
14.9.2	<i>Optimal control</i>	14-46
14.9.3	<i>Observers</i>	14-46
15.	COOLING	
	<i>TJE Miller</i>	
15.1	Introduction	15-1
15.2	Heat removal	15-3
15.2.1	<i>Conduction</i>	15-3
15.2.2	<i>Contact resistance</i>	15-4
15.2.3	<i>Radiation</i>	15-6
15.2.4	<i>Convection</i>	15-6
15.2.5	<i>Natural convection</i>	15-7
15.2.6	<i>Forced convection</i>	15-7
15.2.7	<i>Some rules of thumb for "calibration"</i>	15-8
15.3	Internal temperature distribution	15-9
15.3.1	<i>The diffusion equation</i>	15-9
15.3.2	<i>Thermal equivalent circuit</i>	15-10
15.3.3	<i>Current Density</i>	15-12
15.4	Intermittent operation	15-14
15.4.1	<i>Duty-cycle</i>	15-14
15.4.2	<i>Temperature rise during ON-time</i>	15-15
15.4.3	<i>Temperature fall during OFF-time</i>	15-17
15.4.4	<i>Steady-state</i>	15-18
15.4.5	<i>Maximum overload factor</i>	15-18

CONTENTS

15.4.6 Maximum overload for a single pulse	15-19
15.4.7 Required cool-down period	15-19
15.4.8 Maximum on-time for a given overload factor	15-19
15.4.9 Maximum duration of single pulse	15-20
15.4.10 Graphical transient heating curves	15-20
15.5 Thermal modelling by computer	15-22
15.5.1 Computer model of thermal equivalent circuit	15-22
15.5.2 Determination of equivalent-circuit parameters by test . . .	15-23
16. MAGNETIC MATERIALS	
D.A. Staton	
16.1 Introduction	16-1
16.2 Permanent magnets	16-1
16.2.1 The hysteresis loop and demagnetization characteristic . . .	16-1
16.2.2 Permanent magnet materials	16-4
16.2.3 Temperature effects	16-8
16.2.4 Magnet energy product	16-9
16.2.5 Magnetization	16-10
16.2.6 Mechanical properties and handling	16-10
16.2.7 The latest trends in magnet technology	16-13
16.3 Soft magnetic iron	16-13
16.3.1 The DC magnetization curve	16-15
16.3.2 Core losses	16-16
16.3.3 Calculation of coefficients for use in core-loss formulas .	16-17
16.3.4 Work hardening	16-18
16.3.5 Special steels	16-19
16.4 Measurement of material characteristics	16-19
16.5 Copper wire	16-20

INDEX

Corrigendum:

Contents

Not included: Chapters 17 – 18
