

Contents

CHAPTER 1	QUALITY IMPROVEMENT IN THE MODERN BUSINESS ENVIRONMENT	1
1-1	The Meaning of Quality and Quality Improvement	2
1-1.1	Dimensions of Quality	2
1-1.2	Quality Engineering Terminology	6
1-2	A Brief History of Quality Methodology	8
1-3	Statistical Methods for Quality Improvement	12
1-4	Total Quality Management	17
1-4.1	Quality Philosophy	17
1-4.2	The Link Between Quality and Productivity	21
1-4.3	Quality Costs	22
1-4.4	Legal Aspects of Quality	28
1-4.5	Implementing Quality Improvement	30
PART I	STATISTICAL METHODS USEFUL IN QUALITY IMPROVEMENT	33
CHAPTER 2	MODELING PROCESS QUALITY	34
2-1	Describing Variation	35
2-1.1	The Stem and Leaf Plot	35
2-1.2	The Frequency Distribution and Histogram	38
2-1.3	Numerical Summary of Data	40
2-1.4	The Box Plot	43
2-1.5	Sample Computer Output	44
2-1.6	Probability Distributions	46
2-2	Important Discrete Distributions	51
2-2.1	The Hypergeometric Distribution	51
2-2.2	The Binomial Distribution	52
2-2.3	The Poisson Distribution	55
2-2.4	The Pascal and Related Distributions	56

2-3	Important Continuous Distributions	57
2-3.1	The Normal Distribution	57
2-3.2	The Exponential Distribution	62
2-3.3	The Gamma Distribution	65
2-3.4	The Weibull Distribution	67
2-4	Some Useful Approximations	69
2-4.1	The Binomial Approximation to the Hypergeometric	69
2-4.2	The Poisson Approximation to the Binomial	69
2-4.3	The Normal Approximation to the Binomial	70
2-4.4	Comments on Approximations	70
2-5	Exercises	71

CHAPTER 3 INFERENCES ABOUT PROCESS QUALITY 77

3-1	Statistics and Sampling Distributions	78
3-1.1	Sampling from a Normal Distribution	79
3-1.2	Sampling from a Bernoulli Distribution	83
3-1.3	Sampling from a Poisson Distribution	84
3-2	Estimation of Process Parameters	85
3-2.1	Point Estimation	85
3-2.2	Interval Estimation	86
3-3	Hypothesis Testing on Process Parameters	96
3-3.1	Tests on Means, Variance Known	97
3-3.2	The Use of <i>P</i> -Values in Hypothesis Testing	100
3-3.3	Tests on Means of Normal Distributions, Variance Unknown	101
3-3.4	Tests on Variances of Normal Distributions	107
3-3.5	Tests on Binomial Parameters	109
3-3.6	Tests on Poisson Parameters	110
3-3.7	Probability Plotting	113
3-3.8	The Probability of Type II Error	116
3-4	Exercises	119

PART II STATISTICAL PROCESS CONTROL 127

CHAPTER 4 METHODS AND PHILOSOPHY OF STATISTICAL PROCESS CONTROL 129

4-1	Introduction	130
4-2	Chance and Assignable Causes of Quality Variation	130
4-3	Statistical Basis of the Control Chart	132
4-3.1	Basic Principles	132
4-3.2	Choice of Control Limits	138
4-3.3	Sample Size and Sampling Frequency	140

4-3.4	Rational Subgroups	143
4-3.5	Analysis of Patterns on Control Charts	146
4-3.6	Discussion of Sensitizing Rules for Control Charts	149
4-4	The Rest of the “Magnificent Seven”	150
4-5	Implementing SPC	158
4-6	An Application of SPC	159
4-7	Nonmanufacturing Applications of Statistical Process Control	167
4-8	Exercises	174

CHAPTER 5 CONTROL CHARTS FOR VARIABLES 179

5-1	Introduction	180
5-2	Control Charts for \bar{x} and R	181
5-2.1	Statistical Basis of the Charts	181
5-2.2	Development and Use of \bar{x} and R Charts	186
5-2.3	Charts Based on Standard Values	201
5-2.4	Interpretation of \bar{x} and R Charts	202
5-2.5	The Effect of Nonnormality on \bar{x} and R Charts	205
5-2.6	The Operating-Characteristic Function	206
5-2.7	The Average Run Length for the \bar{x} Chart	209
25-3	Control Charts for \bar{x} and S	211
5-3.1	Construction and Operation of \bar{x} and S Charts	212
5-3.2	The \bar{x} and S Control Charts with Variable Sample Size	217
5-3.3	The S Control Chart	221
5-4	Control Charts for Individual Measurements	221
5-5	Summary of Procedures for \bar{x} , R , and S Charts	229
5-6	Applications of Variables Control Charts	230
5-7	Exercises	235

CHAPTER 6 CONTROL CHARTS FOR ATTRIBUTES 250

6-1	Introduction	251
6-2	The Control Chart for Fraction Nonconforming	251
6-2.1	Development and Operation of the Control Chart	253
6-2.2	Variable Sample Size	265
6-2.3	Nonmanufacturing Applications	270
6-2.4	The Operating-Characteristic Function and Average Run Length Calculations	271
6-3	Control Charts for Nonconformities (Defects)	275
6-3.1	Procedures with Constant Sample Size	275
6-3.2	Procedures with Variable Sample Size	285

6-3.3	Demerit Systems	287
6-3.4	The Operating-Characteristic Function	289
6-3.5	Dealing with Low Defect Levels	290
6-3.6	Nonmanufacturing Applications	294
6-4	Choice Between Attributes and Variables Control Charts	294
6-5	Guidelines for Implementing Control Charts	299
6-6	Exercises	304

CHAPTER 7 CUMULATIVE SUM AND EXPONENTIALLY WEIGHTED MOVING AVERAGE CONTROL CHARTS 313

7-1	The Cumulative-Sum Control Chart	314
7-1.1	Basic Principles: The Cusum Control Chart for Monitoring the Process Mean	314
7-1.2	The Tabular or Algorithmic Cusum for Monitoring the Process Mean	317
7-1.3	Recommendations for Cusum Design	322
7-1.4	The Standardized Cusum	324
7-1.5	Rational Subgroups	325
7-1.6	Improving Cusum Responsiveness for Large Shifts	325
7-1.7	The Fast Initial Response or Headstart Feature	325
7-1.8	One-Sided Cusums	327
7-1.9	A Cusum for Monitoring Process Variability	328
7-1.10	Cusums for Other Sample Statistics	329
7-1.11	The V-Mask Procedure	329
7-2	The Exponentially Weighted Moving-Average Control Chart	332
7-2.1	The Exponentially weighted Moving-Average Control Chart for Monitoring the Process Mean	333
7-2.2	Design of an EWMA Control Chart	337
7-2.3	Rational Subgroups	339
7-2.4	Extensions of the EWMA	339
7-3	The Moving Average Control Chart	341
7-4	Exercises	344

CHAPTER 8 OTHER STATISTICAL PROCESS CONTROL TECHNIQUES 348

8-1	Statistical Process Control for Short Production Runs	349
8-1.1	\bar{x} and R Charts for Short Production Runs	349
8-1.2	Attribute Control Charts for Short Production Runs	352
8-1.3	Other Methods	353
8-2	Modified and Acceptance Control Charts	354
8-2.1	Modified Control Limits for the \bar{x} Chart	354
8-2.2	Acceptance Control Charts	357

8-3	Group Control Charts for Multiple-Stream Processes	358
8-4	Multivariate Quality Control	360
8-4.1	Monitoring of Means	362
8-4.2	Monitoring Process Variability	372
8-5	SPC with Correlated Data	374
8-6	Interfacing Statistical Process Control and Engineering Process Control	386
8-6.1	Process Monitoring and Process Regulation	386
8-6.2	Combining SPC and EPC	395
8-7	Economic Design of Control Charts	399
8-7.1	Designing a Control Chart	399
8-7.2	Process Characteristics	399
8-7.3	Cost Parameters	400
8-7.4	Early Work and Semi-Economic Design	402
8-7.5	An Economic Model of the \bar{x} Control Chart	403
8-7.6	Other Work	412
8-8	Overview of Other Procedures	413
8-8.1	Tool Wear	413
8-8.2	Control Charts Based on Other Sample Statistics	414
8-8.3	Adaptive Schemes	415
8-8.4	Selecting the Optimum Target Value for a Process	417
8-8.5	Fill Control	419
8-8.6	Precontrol	419
8-9	Exercises	421

CHAPTER 9 PROCESS CAPABILITY ANALYSIS 430

9-1	Introduction	431
9-2	Process-Capability Analysis Using a Histogram or a Probability Plot	433
9-2.1	Using the Histogram	433
9-2.2	Probability Plotting	434
9-3	Process Capability Ratios	438
9-3.1	Use and Interpretation of PCR	438
9-3.2	Process-Capability Ratio for an Off-Center Process	442
9-3.3	Normality and the Process Capability Ratio	444
9-3.4	More About Process Centering	444
9-3.5	Confidence Intervals and Tests on Process Capability Ratios	447
9-4	Process-Capability Analysis Using a Control Chart	451
9-5	Process-Capability Analysis Using Designed Experiments	453
9-6	Gage and Measurement System Capability Studies	455

9-7	Setting Specification Limits on Discrete Components	461
9-7.1	Linear Combinations	461
9-7.2	Nonlinear Combinations	465
9-8	Estimating the Natural Tolerance Limits of a Process	467
9-8.1	Tolerance Limits Based on the Normal Distribution	468
9-8.2	Nonparametric Tolerance Limits	469
9-9	Exercises	470

PART III	PROCESS DESIGN AND IMPROVEMENT WITH DESIGNED EXPERIMENTS	475
-----------------	---	------------

CHAPTER 10	THE FUNDAMENTALS OF EXPERIMENTAL DESIGN	477
-------------------	--	------------

10-1	What is Experimental Design?	478
10-2	Examples of Designed Experiments in Quality and Process Improvement	479
10-3	Experiments with One Factor	483
10-3.1	An Example	483
10-3.2	The Analysis of Variance	485
10-3.3	Residual Analysis	490
10-3.4	Comparison of Individual Means	491
10-3.5	Using the Computer	494
10-3.6	A Components-of-Variance Model	496
10-4	Blocking and Nuisance Factors	499
10-4.1	The Randomized Block Design	499
10-4.2	Residual Analysis	504
10-5	Guidelines for Designing Experiments	506
10-6	Exercises	508

CHAPTER 11	FACTORIAL AND FRACTIONAL FACTORIAL EXPERIMENTS FOR PROCESS DESIGN AND IMPROVEMENT	512
-------------------	--	------------

11-1	Factorial Experiments	513
11-1.1	An Example	517
11-1.2	Statistical Analysis	517
11-1.3	Residual Analysis	523
11-2	The 2^k Factorial Design	525
11-2.1	The 2^2 Design	525
11-2.2	The 2^k Design for $k \geq 3$ Factors	532
11-2.3	A Single Replicate of the 2^k Design	545
11-2.4	Addition of Center Points to the 2^k Design	549
11-2.5	Blocking and Confounding in the 2^k Design	553

11-3	Fractional Replication of the 2^k Design	555
11-3.1	The One-Half Fraction of the 2^k	555
11-3.2	Smaller Fractions: The 2^{k-p} Fractional Factorial Design	562
11-4	Exercises	569
CHAPTER 12	PROCESS OPTIMIZATION WITH DESIGNED EXPERIMENTS	572
12-1	Response Surface Methods and Designs	573
12-1.1	The Method of Steepest Ascent	575
12-1.2	Analysis of a Second-Order Response Surface	578
12-2	Evolutionary Operation	583
12-3	Taguchi's Contributions to Quality Engineering	589
12-3.1	The Taguchi Philosophy	590
12-3.2	The Taguchi Approach to Parameter Design	591
12-3.3	Improved Robust Parameter Design	600
12-4	Exercises	681
PART IV	ACCEPTANCE SAMPLING	605
CHAPTER 13	LOT-BY-LOT ACCEPTANCE SAMPLING BY ATTRIBUTES	606
13-1	The Acceptance Sampling Problem	607
13-1.1	Advantages and Disadvantages of Sampling	608
13-1.2	Types of Sampling Plans	609
13-1.3	Lot Formation	610
13-1.4	Random Sampling	610
13-1.5	Guidelines for Using Acceptance Sampling	611
13-2	Single-Sampling Plans for Attributes	613
13-2.1	Definition of a Single-Sampling Plan	613
13-2.2	The OC Curve	613
13-2.3	Designing a Single-Sampling Plan with a Specified OC Curve	619
13-2.4	Rectifying Inspection	621
13-3	Double, Multiple, and Sequential Sampling	625
13-3.1	Double-Sampling Plans	625
13-3.2	Multiple-Sampling Plans	632
13-3.3	Sequential-Sampling Plans	632
13-4	Military Standard 105E (ANSI/ASQC Z1.4, ISO 2859)	636
13-4.1	Description of the Standard	636

13-4.2	Procedure	638
13-4.3	Discussion	643
13-5	The Dodge-Romig Sampling Plans	645
13-5.1	AOQL Plans	646
13-5.2	LTPD Plans	648
13-5.3	Estimation of Process Average	649
13-6	Exercises	649

CHAPTER 14 OTHER ACCEPTANCE SAMPLING TECHNIQUES 652

14-1	Acceptance Sampling by Variables	653
14-1.1	Advantages and Disadvantages of Variables Sampling	653
14-1.2	Types of Sampling Plans Available	654
14-1.3	Caution in the Use of Variables Sampling	655
14-2	Designing a Variables Sampling Plan with a Specified OC Curve	656
14-3	MIL STD 414 (ANSI/ASQC Z1.9)	659
14-3.1	General Description of the Standard	659
14-3.2	Use of the Tables	660
14-3.3	Discussion of MIL STD 414 and ANSI/ASQC Z1.9	663
14-4	Other Variables Sampling Procedures	664
14-4.1	Sampling by Variables to Give Assurance Regarding the Lot or Process Mean	664
14-4.2	Sequential Sampling by Variables	665
14-5	Chain Sampling	665
14-6	Continuous Sampling	667
14-6.1	CSP-I	668
14-6.2	Other Continuous Sampling Plans	670
14-7	Skip-Lot Sampling Plans	671
14-8	Exercises	675

APPENDIX A-1

I	Cumulative Poisson Distribution	A-3
II	Cumulative Standard Normal Distribution	A-6
III	Percentage Points of the χ^2 Distribution	A-8
IV	Percentage Points of the t Distribution	A-9
V	Percentage Points of the F Distribution	A-10

VI	Factors for Constructing Variables Control Charts	A-15
VII	Factors for Two-Sided Normal Tolerance Limits	A-16
VIII	Factors for One-Sided Normal Tolerance Limits	A-17
IX	Random Numbers	A-18

BIBLIOGRAPHY	B-1
---------------------	------------

ANSWERS TO SELECTED EXERCISES	ANS-1
--------------------------------------	--------------

INDEX	I-1
--------------	------------