

# Contents

<b>1. Introduction</b> .....	1
<b>2. Basics of MBE Growth</b> .....	3
2.1 MBE Apparatus .....	3
2.2 Understanding of MBE Growth Processes .....	5
2.3 Solid–Vapor Equilibrium for Binary Compounds .....	8
2.4 Liquid–Solid–Vapor Equilibrium for Binary Compounds .....	15
2.5 Particular III–V Materials .....	16
2.5.1 AlAs .....	16
2.5.2 InAs .....	17
2.5.3 InP .....	18
2.5.4 GaP .....	19
2.6 Solid–Vapor Equilibrium for Ternary Compounds .....	20
2.7 Liquid–Solid–Vapor Equilibrium for Ternary Compounds: Surface Segregation of More Volatile Elements .....	22
<b>3. Doping and Impurity Segregation Effects in MBE</b> .....	33
3.1 Point-Defect Equilibria in MBE .....	33
3.2 Impurity Incorporation in MBE .....	36
3.2.1 General Consideration .....	36
3.2.2 Manganese Doping of GaAs .....	37
3.2.3 GaAs Doping with Zn, Cd, Pb, Mg .....	39
3.2.4 GaAs Doping with S, Se, Te .....	40
3.2.5 GaAs Doping with Amphoteric Impurities: Ge, Si, Sn ..	41
3.3 Impurity Segregation in MBE .....	43
3.4 Interplay Between Impurity Segregation and Diffusion in MBE .....	47
<b>4. Influence of Strain in the Epitaxial Film on Surface-Phase Equilibria</b> .....	59
4.1 MBE Growth of Lattice-Mismatched Binary Compound .....	59
4.2 Growth of Lattice-Matched Solid Solution Formed From Lattice-Mismatched Binaries .....	66

VIII Contents

<b>5. II–VI Materials</b> .....	71
<b>6. Conclusion</b> .....	75
<b>Index</b> .....	83