

Contents

	Page
Preface	vii
1 Introduction	1
1.1 Object of the book	
1.2 Nature of statistical methods	
1.3 Use of computers in statistics	
1.4 This book, and others	
2 Frequency Distributions	9
2.1 Histograms and probability density	
2.2 Measures of central tendency and spread	
2.3 Form of distribution	
2.4 The Normal distribution	
2.5 Population and sample	
2.6 Samples and sampling fluctuations	
3 Averages and Measures of Dispersion	30
3.1 Introduction: Condensation of data	
3.2 Measures of location	
3.3 Measures of dispersion	
3.4 Measures of skewness and kurtosis	
3.5 Outliers	
3.6 Standard error of mean and standard deviation	
3.7 Standard error of a function of several variables	
App. 3A Unbiased estimate of Population variance	
4 Statistical Inference	58
4.1 Introduction to confidence limits	
4.2 Confidence limits for mean values	
4.3 Confidence limits for standard deviations	
4.4 The effect of non-Normality	
4.5 Tests of significance	
4.6 Significance of means	
4.7 Distribution-free tests	
4.8 The F -test	
4.9 Statistical decisions	

- App. 4A Confidence limits for a standard deviation: data not assumed Normal
- App. 4B The likelihood function
- App. 4C Utility functions

- 5 Statistical Tests: Choosing the Number of Observations** 94
- 5.1 Introduction: Prior distributions and costs
 - 5.2 Prior distribution and costs known
 - 5.3 Prior distribution unknown
 - 5.4 Prior distribution and costs unknown
 - 5.5 Comparison of two means
 - 5.6 Standard deviation not precisely known
 - 5.7 Number of observations in comparing standard deviations
 - 5.8 Sequential testing
- 6 Analysis of Variance** 121
- 6.1 Introduction: Additive property of variances
 - 6.2 Types of classification and nature of variation
 - 6.3 Hierarchic classification with two sources of variation
 - 6.4 Example: Variation of dyestuff yields
 - 6.5 Hierarchic classification with three sources of variation
 - 6.6 Cross-classifications
 - 6.7 Comparison of means
 - 6.8 Further aspects of the Analysis of Variance
 - App. 6A Combination of results from several samples
 - App. 6B Analysis of hierarchic data
 - App. 6C Confidence limits for the components of variance
 - App. 6D Comparison of the efficiencies of certain hierarchic designs
 - App. 6E Comparison of several variance estimates
 - App. 6F Analysis of two-way cross-classification without repeats
 - App. 6G Estimation of a missing value in a two-way cross-classification without repeats
- 7 Linear Relationships between Two Variables** 178
- 7.1 Introduction: Functional relationship and regression
 - 7.2 Linear regression
 - 7.3 Conditions for valid estimation of the regression equations
 - 7.4 Regression through the origin
 - 7.5 Weighted linear regression
 - 7.6 Linear functional relationships
 - 7.7 Comparison of several regression lines
 - 7.8 Correlation
 - App. 7A Fieller's Theorem
- 8 Multiple and Curvilinear Regression** 237
- 8.1 Introduction
 - 8.2 Multiple linear regression
 - 8.3 Generalization of the method of least squares
 - 8.4 Selection of the best subset of variables
 - 8.5 Further aspects of model building
 - 8.6 Curvilinear regression
 - 8.7 Multiple quadratic regression
 - 8.8 Interpretation and presentation of a multiple regression analysis
 - 8.9 Miscellaneous topics: Plant records, functional relationships and nonlinear estimation

9	Frequency Data and Contingency Tables	304
	9.1 Binomial distribution	
	9.2 Poisson distribution	
	9.3 Negative binomial distribution	
	9.4 Chi-squared distribution	
	9.5 Analysis of single classification data	
	9.6 Contingency tables	
	9.7 General considerations on frequency data	
10	Control Charts	336
	10.1 Introduction: Application in quality control	
	10.2 General purpose of control charts	
	10.3 Analysis of data by Shewhart control charts	
	10.4 Control charts for process control	
	10.5 Rate of detection of changes in average level	
	10.6 Cumulative sum charts	
	10.7 Decision making with a V-mask	
	10.8 Choice of charting method	
	10.9 Further applications of control charts: Defect charts and double cusum charts	
	App. 10A Use of Shewhart control charts	
11	Sampling and Specifications	373
	11.1 Introduction: Reasons for sampling	
	11.2 Random sampling and systematic sampling	
	11.3 Sampling of attributes	
	11.4 Process control of attributes	
	11.5 Sampling of variables	
	11.6 Process control of variables	
	App. 11A Process control by decision limit schemes	
12	Simulation	409
	12.1 Introduction: A blending problem	
	12.2 Types of simulation	
	12.3 Building a simulation model	
	12.4 Simulation experiments	
	12.5 The use of computers for simulation	
	12.6 Applications	
	Statistical and Mathematical Symbols	423
	Tables and Charts of Statistical Functions	431
	Index	473