

CONTENTS

Introduction..... v

<u>TABLE</u>	<u>Page number</u>	
	<u>Table</u>	<u>Description</u>
NORMAL DISTRIBUTION		
1	Inverse of the Standardized Normal Distribution..... 3 2
STUDENT'S t-DISTRIBUTION		
2	Critical Values for Student's t.. 4 2
3	Sample Size for a Test of the Mean of a Normal Variable	7 6
4	Sample Size for Comparing the Means of Two Normal Variables.... 9 6
CHI SQUARE DISTRIBUTION		
5	Critical Values of the Chi Square Distribution..... 12 11
F-DISTRIBUTION		
6	Critical Values of the F-Distribution..... 14 11
7	Sample Size: One-way Analysis of Variance..... 21 20
NORMAL TOLERANCE LIMITS		
8	One-sided Tolerance Limits..... 25 24
9	Two-sided Tolerance Limits..... 27 26
10	Factors for Tolerance Limits Controlling Both Tails of a Normal Distribution..... 29 28
STATISTICS INVOLVING THE RANGE OF NORMAL VARIABLES		
11	Critical Values of the Sample Range from a Normal Distribution 31 30
12	Mean, Variance, and Standard Deviation of the Range, Control Chart Factors..... 33 32
13	Critical Values for Testing the Deviation of the Sample Mean from a Preassigned Value Using the Sample Range..... 35 34

TABLE	Page number	
	Table	Description
14	Critical Values for Testing the Significance of the Difference Between Means of Two Samples of Equal Size Using the Sample Ranges.....	37 36
15	Critical Values of the Studentized Range from a Normal Distribution.....	38 36
16	Chi-approximation to the Mean Range.....	41 40
QUALITY CONTROL TABLES		
17	Factors for Control Charts.....	43 42
18	Characteristics for Sequential Tests of a Binomial Proportion..	45 44
19	Critical Values for Testing an Extreme Value.....	46 44
20	MIL-STD 105D or ABC Plan: Single Sampling.....	50 48
21	Binomial Acceptance Plans with Fixed α and β	55 54
POISSON DISTRIBUTION		
22	The Cumulative Poisson Distribution.....	56 54
23	Confidence Limits on a Poisson Parameter.....	58 54
BINOMIAL DISTRIBUTION		
24	The Cumulative Binomial Distribution.....	61 60
25	Confidence Limits on a Binomial Parameter.....	71 70
NONPARAMETRIC TOLERANCE LIMITS		
26	Sample Sizes for One-sided Nonparametric Tolerance Limits..	81 80
27	Sample Sizes for Two-sided Nonparametric Tolerance Limits..	83 82
SOME NONPARAMETRIC TESTS		
28	Critical Values of the Mann-Whitney Two-sample Statistic....	84 82

<u>TABLE</u>	<u>Page number</u>	
	<u>Table</u>	<u>Discription</u>
29	Critical Values of the Sign Test and Distribution-free Confidence Limits on the Median.....	89 88
30	Sample Size for the Sign Test....	91 90
31	Critical Values for the Number of Runs Test.....	93 92
32	Distribution of the Magnitude of Quadrant Sums.....	97 96
RANK CORRELATION		
33	Critical Values for Kendall's Rank Correlation Coefficient.....	99 98
34	Critical Values for Spearman's Rank Correlation Coefficient.....	100 98
NONPARAMETRIC ONE-WAY ANALYSIS OF VARIANCE		
35	Critical Values for the Kruskal- Wallis Statistic.....	104 101
36	Critical Values for Jonckheere's Statistic.....	106 102
37	Multiple Comparisons Based on Kruskal-Wallis Rank Sums.....	109 102
38	Critical Values of the Maximum Rank Sum.....	110 103
NONPARAMETRIC TWO-WAY ANALYSIS OF VARIANCE		
39	Critical Values for Friedman's Chi Square Statistic.....	113 111
40	Critical Values for Page's L Statistic.....	117 112
41	Multiple Comparisons Based on Friedman Rank Sums.....	118 112
KOLMOGOROV-SMIRNOV TESTS		
42	Critical Values for the One- sample Kolmogorov-Smirnov Statistic.....	122 120
43	Critical Values for the One- sided Two-sample Kolmogorov- Smirnov Statistic.....	123 121

TABLE	Page number	
	Table	Description
44	Critical Values for the Two-sided Two-sample Kolmogorov-Smirnov Statistic.....	126 121
45	Limiting Critical Values of the Kolmogorov-Smirnov Statistics...	129 121
TESTS FROM THE HYPERGEOMETRIC DISTRIBUTION		
46	Critical Values for Fisher's Exact Test for Two by Two Tables.....	132 130
47	Sample Size to Compare Two Proportions.....	147 146
48	Critical Values for a Nonparametric Test of Location.....	149 148
49	Critical Values for a Nonparametric Test of Dispersion.....	152 151
PRODUCT MOMENT CORRELATIONS		
50	Critical Values for the Product Moment Correlation Coefficient ($\rho = 0$).....	155 154
51	Critical Values for the Multiple Correlation Coefficient.....	157 156
RANDOM NUMBERS		
52	Random Numbers.....	158 156
References.....		163