

The Role of Statistics in Engineering 1

- 1-1 The Engineering Method and Statistical Thinking 1
- 1-2 Collecting Engineering Data 10
- 1-3 Mechanistic and Empirical Models 12
- 1-4 Designing Experimental Investigations 16
- 1-5 Observing Processes over Time 19

Data Summary and Presentation 24

- 2-1 The Importance of Data Summary
and Display 24
- 2-2 The Stem-and-Leaf Diagram 25
- 2-3 The Frequency Distribution and
Histogram 30
- 2-4 The Box Plot 35
- 2-5 Time Sequence Plots 37

Random Variables and Probability Distributions 46

- 3-1 Introduction 47
- 3-2 Random Variables 49
- 3-3 Probability 51
- 3-4 Probability Density Function, Mean, and Variance of a Continuous Random Variable 56
 - 3-4.1 Probability Density Function 56
 - 3-4.2 Mean and Variance of a Continuous Random Variable 59
- 3-5 Normal Distribution 63
- 3-6 Probability Plots 75
- 3-7 Probability Mass Function, Mean, and Variance of a Discrete Random Variable 79
 - 3-7.1 Probability Mass Function 80
 - 3-7.2 Mean and Variance of a Discrete Random Variable 81
- 3-8 Binomial Distribution 84
- 3-9 Poisson Process 92
 - 3-9.1 Poisson Distribution 92
 - 3-9.2 Exponential Distribution 99
- 3-10 Normal Approximation to the Binomial and Poisson Distributions 105
- 3-11 Correlation and Independence 109
 - 3-11.1 Correlation 109
 - 3-11.2 Independence 113
- 3-12 Random Samples, Statistics, and the Central Limit Theorem 115

Decision Making for a Single Sample 131

- 4-1 Statistical Inference 132
- 4-2 Point Estimation 133
- 4-3 Hypothesis Testing 140

- 4-3.1 Statistical Hypotheses 140
- 4-3.2 Testing Statistical Hypotheses 142
- 4-3.3 One-Sided and Two-Sided Hypotheses 150
- 4-3.4 General Procedure for Hypothesis Testing 152
- 4-4 Inference on the Mean of a Population, Variance Known 154
 - 4-4.1 Hypothesis Testing on the Mean 154
 - 4-4.2 *P*-Values in Hypothesis Testing 157
 - 4-4.3 Type II Error and Choice of Sample Size 158
 - 4-4.4 Large-Sample Test 161
 - 4-4.5 Some Practical Comments on Hypothesis Testing 161
 - 4-4.6 Confidence Interval on the Mean 163
 - 4-4.7 General Method for Deriving a Confidence Interval 169
- 4-5 Inference on the Mean of a Population, Variance Unknown 171
 - 4-5.1 Hypothesis Testing on the Mean 172
 - 4-5.2 *P*-Value for a *t*-Test 176
 - 4-5.3 Computer Solution 177
 - 4-5.4 Choice of Sample Size 178
 - 4-5.5 Confidence Interval on the Mean 180
- 4-6 Inference on the Variance of a Normal Population 183
 - 4-6.1 Hypothesis Testing on the Variance of a Normal Population 183
 - 4-6.2 Confidence Interval on the Variance of a Normal Population 187
- 4-7 Inference on a Population Proportion 189
 - 4-7.1 Hypothesis Testing on a Binomial Proportion 190
 - 4-7.2 Type II Error and Choice of Sample Size 191

- 4-7.3 Confidence Interval on a Binomial Proportion 193
- 4-8 Summary Table of Inference Procedures for a Single Sample 198
- 4-9 Testing for Goodness of Fit 198

Decision Making for Two Samples 210

- 5-1 Introduction 211
- 5-2 Inference for a Difference in Means, Variances Known 211
 - 5-2.1 Hypothesis Tests for a Difference in Means, Variances Known 212
 - 5-2.2 Choice of Sample Size 214
 - 5-2.3 Identifying Cause and Effect 215
 - 5-2.4 Confidence Interval on a Difference in Means, Variances Known 216
- 5-3 Inference for the Difference in Means of Two Normal Distributions, Variances Unknown 221
 - 5-3.1 Hypotheses Tests for the Difference in Means 221
 - 5-3.2 Choice of Sample Size 227
 - 5-3.3 Confidence Interval on the Difference in Means 228
 - 5-3.4 Computer Solution 230
- 5-4 The Paired t -Test 235
- 5-5 Inferences on the Variances of Two Normal Populations 243
 - 5-5.1 Tests of Hypotheses on the Ratio of Two Variances 243
 - 5-5.2 Confidence Interval on the Ratio of Two Variances 247
- 5-6 Inference on Two Population Proportions 250
 - 5-6.1 Large-Sample Test for $H_0: p_1 = p_2$ 250

- 5-6.2 The β -Error and Choice of Sample Size 252
- 5-6.3 A Confidence Interval for $p_1 - p_2$ 254
- 5-7 Summary Table for Inference Procedures for Two Samples 256
- 5-8 What If We Have More Than Two Means? 256
 - 5-8.1 An Example 257
 - 5-8.2 The Analysis of Variance 258

Building Empirical Models 275

- 6-1 Introduction to Empirical Models 275
- 6-2 Least Squares Estimation of the Parameters 283
 - 6-2.1 Simple Linear Regression 283
 - 6-2.2 Multiple Linear Regression 287
- 6-3 Properties of the Least Squares Estimators and Estimation of σ^2 297
- 6-4 Hypothesis Testing in Linear Regression 301
 - 6-4.1 Test for Significance of Regression 301
 - 6-4.2 Tests on Individual Regression Coefficients 304
- 6-5 Confidence Intervals in Linear Regression 308
 - 6-5.1 Confidence Intervals on Individual Regression Coefficients 308
 - 6-5.2 Confidence Interval on the Mean Response 309
- 6-6 Prediction of New Observations 313
- 6-7 Assessing the Adequacy of the Regression Model 317
 - 6-7.1 Residual Analysis 317
 - 6-7.2 The Coefficient of Multiple Determination 322
 - 6-7.3 Influential Observations 324

Design of Engineering Experiments 333

- 7-1 The Strategy of Experimentation 333
- 7-2 Some Applications of Experimental Design Techniques 335
- 7-3 Factorial Experiments 339
- 7-4 2^k Factorial Design 344
 - 7-4.1 2^2 Design 344
 - 7-4.2 Analysis 347
 - 7-4.3 Residual Analysis and Model Checking 351
- 7-5 2^k Design for $k \geq 3$ Factors 356
- 7-6 Single Replicate of a 2^k Design 364
- 7-7 Addition of Center Points to a 2^k Design 369
- 7-8 Fractional Replication of a 2^k Design 375
 - 7-8.1 One-Half Fraction of a 2^k Design 376
 - 7-8.2 Smaller Fractions: 2^{k-p} Fractional Factorial Design 383
- 7-9 Response Surface Methods and Designs 395
 - 7-9.1 Method of Steepest Ascent 397
 - 7-9.2 Analysis of a Second-Order Response Surface 400
- 7-10 Factorial Experiments with More Than Two Levels 410

Statistical Quality Control 426

- 8-1 Quality Improvement and Statistics 426
- 8-2 Statistical Quality Control 428
- 8-3 Statistical Process Control 428
- 8-4 Introduction to Control Charts 429
 - 8-4.1 Basic Principles 429
 - 8-4.2 Design of a Control Chart 433
 - 8-4.3 Rational Subgroups 435
 - 8-4.4 Analysis of Patterns on Control Charts 436
- 8-5 \bar{X} and R control Charts 439
- 8-6 Control Charts for Individual Measurements 447
- 8-7 Process Capability 453
- 8-8 Attribute Control Charts 459
 - 8-8.1 P Chart (Control Chart for Proportions) 459
 - 8-8.2 U Chart (Control Chart for Defects per Unit) 462
- 8-9 Control Chart Performance 465

Appendices 473

- A. Statistical Tables and Charts A-1
- B. Bibliography B-1
- C. Answers to Selected Problems C-1

Index I-1