

CONTENTS

CHAPTER 1 INTRODUCTION	1
I. Trace Analysis	1
A. Role of Contamination	1
B. Scope	2
C. Control of Parameters	3
D. Existing Needs	5
1. Purity Determinations	5
2. Characterization of Natural Systems	7
E. Challenges	9
References	10
CHAPTER 2 BASIC ASPECTS OF QUANTITATIVE ULTRATRACE ANALYSIS	12
I. Literature on Ultratrace Analysis	14
II. The Blank	15
III. Accuracy and Precision	18
IV. Standards	20
A. Synthetic	20
1. Solids	21
2. Liquids	21
B. High Purity Standards (Major element or compound standards)	22
C. Standards for Trace Analysis	24
V. Stability of Dilute Solutions	27
A. Methods of Storage	27
B. Adsorption Losses	28
VI. Measuring Small Volumes of Solutions	33
A. Volumetric Flasks	33
B. Pipets	33
C. Burets	40
D. Calibration	40
VII. Summary	42
References	42

CHAPTER 3 THE LABORATORY	46
I. Airborne Contamination	46
A. Analysis of Particles	46
B. Classification of Clean Environments by Particle Counting	47
C. Removal of Particles	47
D. Effects on Analytical Results	49
II. Clean Analytical Laboratories	50
A. Upgrading the Conventional Laboratory	50
1. <i>Phase I</i>	50
2. <i>Phase II</i>	51
B. Positive Pressure Non-Laminar-Flow Laboratories	54
C. Other Facilities and Considerations	59
D. Electrostatics	62
E. Humidity	63
F. The Analyst	63
G. Garments	64
H. Laundry	65
I. Safety	65
References	67
CHAPTER 4 MATERIALS FOR CONTAINERS AND APPARATUS	69
I. Storage of Chemicals	69
A. Containers	69
B. Conditions	70
1. <i>The Laboratory</i>	70
2. <i>Commercial Production</i>	71
II. Leaching	71
III. Selection of Materials	75
A. Polymers	77
1. <i>Polyfluorocarbons</i>	77
2. <i>Polyethylene</i>	80
3. <i>Polypropylene</i>	82
4. <i>Silicones</i>	82
5. <i>Polymethyl Methacrylate</i>	83
6. <i>Polyvinyl Chloride</i>	83

B. Ceramics	84
1. <i>Vitreous Silica</i>	84
2. <i>Borosilicate Glass</i>	86
3. <i>Porcelain</i>	88
4. <i>Pyroceram</i>	88
5. <i>Graphite</i>	89
6. <i>Other Materials</i>	89
C. Metals	90
1. <i>Platinum</i>	90
2. <i>Aluminum</i>	91
3. <i>Stainless Steel</i>	91
IV. Cleaning Procedures	92
References	95
CHAPTER 5 PURIFICATION OF REAGENTS	98
I. Methods of Purification	99
A. Distillation	102
1. <i>Acids</i>	102
a. <i>Subboiling Distillation</i>	102
b. <i>Isopiestic Distillation</i>	104
c. <i>Gaseous Saturation of High Purity Water</i>	105
2. <i>Bases</i>	106
3. <i>Solvents</i>	106
4. <i>Water</i>	107
B. Chromatography	108
1. <i>Liquid Chromatography</i>	108
a. <i>Ion Exchange</i>	108
(1) <i>Preparation and Purification of an Ion-Exchange Column</i>	111
(2) <i>Water Purification</i>	113
(3) <i>Hydrochloric Acid and Sodium Hydroxide</i>	119
b. <i>Adsorptive Filtration</i>	120
c. <i>High Performance Liquid Chromatography</i>	121
2. <i>Gas-Liquid Chromatography</i>	122
C. Fractional Solidification	122
1. <i>Progressive Freezing</i>	123
2. <i>Zone Melting</i>	123
3. <i>Column Crystallization</i>	124
D. Crystallization	125

E.	Extraction and Complexation	125
	1. <i>Dithiocarbamates</i>	126
	2. <i>8-Quinolinol</i>	126
	3. <i>Dithizone</i>	127
	4. <i>Acetylacetone</i>	128
	5. <i>PAN</i>	129
	6. <i>EDTA</i>	129
F.	Electrolysis	131
G.	Filtration, a Prepurification Tool	133
	1. <i>Purification of Fluxes</i>	133
	2. <i>Purification of Calcium Nitrate</i>	134
H.	Precipitation	134
	1. <i>Prepurification of Calcium Nitrate</i>	134
	2. <i>Ultrapurification of Calcium Nitrate</i>	134
I.	Sublimation	135
II.	Gases	137
	A. Industrial Production and Purification	137
	B. Laboratory Methods of Purification	141
	References	145

CHAPTER 6 CONTAMINATION CONTROL DURING ROUTINE ANALYTICAL OPERATIONS		151
I.	Sampling	151
	A. Solutions and Liquids	151
	B. Powders and Solids	152
II.	Heating and Drying	155
	A. Gas Burners and Hot Plates	155
	B. Furnaces	155
	C. Microwave Heating	156
	D. Air Drying and Infrared Heating	157
III.	Fusion	157
	A. Conventional Methods	157
	B. Levitation Melting	161
IV.	Ashing	164
	A. Wet and Dry Ashing	164
	B. Low Temperature Ashing	164
V.	Decomposition and Dissolution	165
	A. Acid Digestion	165
	B. Acid Pressure Bombs	165
	C. Gas Phase Reactions	166

VI. Concentration of Trace Elements	173
A. Electrolysis	173
B. Nonelectrolytic Deposition	175
C. Evaporation	176
D. Freeze-Drying	178
E. Ion-Exchange and Chelating Resins	180
VII. Stirring	184
VIII. Filtration	185
References	189

CHAPTER 7 SELECTED METHODS FOR DETERMINING ULTRATRACE ELEMENTS IN REAGENTS AND MATERIALS

193

I. Neutron Activation Analysis (NAA)	193
A. General	193
1. <i>Advantages</i>	193
2. <i>Limitations</i>	195
3. <i>Sample Preparation</i>	196
a. <i>Contamination Problems</i>	196
b. <i>Liquids</i>	197
c. <i>Powdered Samples</i>	197
d. <i>Sample Recovery</i>	198
e. <i>Evaluation of Procedures</i>	198
f. <i>Volatilization Losses</i>	199
B. Principle of Measurement	201
C. Standards	202
1. <i>General</i>	202
2. <i>Solids</i>	203
3. <i>Solutions</i>	203
4. <i>Errors Due to Standard</i>	203
D. Accuracy and Precision	207
E. Interferences	209
F. Analysis of High Purity Materials	211
II. Radioisotope Dilution (RID)	215
A. Introduction	215
B. Quantitative Principles	215
C. Substoichiometric Radioisotope Dilution (SRID)	217
D. SRID Versus NAA	218
E. General Procedure	219
F. Applications	220

III. Stable Isotope Dilution (SID)	220
A. General	220
B. Basis for Quantitative Analysis	220
C. Experimental Procedure	221
1. <i>Calibration of Isotope Solutions</i>	223
2. <i>Recent Innovations</i>	223
3. <i>Interferences</i>	224
D. Analysis of Ultrapure Reagents	224
IV. X-Ray Fluorescence Spectroscopy	225
A. Introduction	225
B. Separations in X-Ray Analysis	226
C. Microanalysis	229
D. Analysis of Particulates	230
V. Spark Source Mass Spectrometry	234
A. Introduction	234
B. Preparation of Samples	234
VI. Emission Spectroscopy (ES)	236
A. General	236
B. Sensitivity	236
C. Contamination Problems	237
VII. Atomic Absorption (AAS) and Atomic Fluorescence Spectroscopy (AFS)	239
VIII. Summary	241
References	242
APPENDIX	247
I. Abbreviations, Definitions, and Symbols	247
II. Storage Conditions for Minimum Loss of Trace Elements	248
III. Suppliers of Specialty Products for the Analytical Laboratory	249
A. Laminar-Flow Hoods	249
B. Vitreous Silica	249
C. Glass	249
D. Plastics	249
E. High Purity Chemicals and Metals	250
F. Ion-Exchange Resins	251
G. Filters	252
H. Lyophilizers	252
INDEX	253