## Contents

1.	Introduction
	Suggested Reading, 6
2.	Phenomenological Treatment of Viscoelasticity
	A. Elastic Modulus, 7
	B. Transient Experiments, 19
	C. Dynamic Experiments, 23
	D. Boltzmann Superposition Principle, 27
	E. Relationship Between the Creep Compliance and the Stress
	Relaxation Modulus, 32
	F. Relationship Between Static and Dynamic Properties, 33
	Appendix 1. Connecting Creep Compliance and Stress Relaxation
	Modulus Using Laplace Transforms, 35
	Appendix 2. Borel's Theorem, 38
	Appendix 3. Geometries for the Measurement of Viscoelastic
	Functions, 38
	1. Axial Geometries, 38
	2. Rotational Geometries, 42
	Problems, 46
	References, 50
	Actionomy, 50
3.	Viscoelastic Models

## xviii CONTENTS

5.

Mechanical Elements, 51  1. Maxwell Model, 53  2. Voigt Model, 59  3. Generalized Maxwell Model, 61  4. Voigt-Kelvin Model, 64  Distributions of Relaxation and Retardation Times, 66  Molecular Theories, 69  Application of Flexible-Chain Models to Solutions, 78  The Zimm Modification, 79  Extension to Bulk Polymer, 82  Reptation, 93  sendix: Manipulation of the Rouse Matrix, 97  olems, 102  erences, 105			
ne-Temperature Correspondence	107		
Four Regions of Viscoelastic Behavior, 107 Time-Temperature Superposition, 114 Master Curves, 117 The WLF Equation, 119 Molecular Interpretation of Viscoelastic Response, 124 blems, 125 erences, 128			
Transitions and Relaxation in Polymers 129			
Phenomenology of the Glass Transition, 129 Theories of the Glass Transition, 132 1. Free-Volume Theory, 133 2. Thermodynamic Theory, 137 3. Kinetic Theories, 141 Structural Parameters Affecting the Glass Transition, 145 Relaxations in the Glassy State, 151 Relaxation Processes in Networks, 154 1. Physical Relaxation, 154 2. Chemical Processes, 156 blems, 159 Gerences, 163			
	1. Maxwell Model, 53 2. Voigt Model, 59 3. Generalized Maxwell Model, 61 4. Voigt-Kelvin Model, 64 Distributions of Relaxation and Retardation Times, 66 Molecular Theories, 69 Application of Flexible-Chain Models to Solutions, 78 The Zimm Modification, 79 Extension to Bulk Polymer, 82 Reptation, 93 endix: Manipulation of the Rouse Matrix, 97 lems, 102 rences, 105 e-Temperature Correspondence Four Regions of Viscoelastic Behavior, 107 Time-Temperature Superposition, 114 Master Curves, 117 The WLF Equation, 119 Molecular Interpretation of Viscoelastic Response, 124 lems, 125 rences, 128 nsitions and Relaxation in Polymers  Phenomenology of the Glass Transition, 129 Theories of the Glass Transition, 132 1. Free-Volume Theory, 133 2. Thermodynamic Theory, 137 3. Kinetic Theories, 141 Structural Parameters Affecting the Glass Transition, 145 Relaxations in the Glassy State, 151 Relaxation Processes in Networks, 154 1. Physical Relaxation, 154 2. Chemical Processes, 156 olems, 159		

308

6.	Elasticity of Rubbery Networks	165
7.	<ul> <li>A. Thermodynamic Treatment, 166</li> <li>B. Statistical Treatment, 172 <ol> <li>Derivation, 172</li> <li>Energy Contribution, 183</li> </ol> </li> <li>C. Phenomenological Treatment, 187</li> <li>D. Factors Affecting Rubber Elasticity, 190 <ol> <li>Effect of Degree of Crosslinking, 190</li> <li>Effect of Swelling, 192</li> <li>Effect of Fillers, 195</li> <li>Effect of Strain-Induced Crystallization, 198</li> </ol> </li> <li>Appendix 1. Statistics of a Polymer Chain, 199 Appendix 2. Equation of State for a Polymer Chain, 206 Problems, 208 References, 211 </li> <li>Dielectric and NMR Methods</li> <li>A. Dielectric Methods, 213 <ol> <li>Phenomenology, 214</li> <li>Molecular Interpretation of Dielectric Constant, 220</li> <li>Interfacial Polarization, 227</li> <li>Application to Polymers, 229</li> <li>Experimental Methods, 231</li> <li>Application of Dielectric Relaxation to Polymethyl Methacrylate, 235</li> <li>Comparisons Between Mechanical and Dielectric Relaxation for Polymers, 236</li> <li>Nuclear Magnetic Resonance Methods, 237</li> <li>Problems, 243</li> <li>References, 244</li> </ol> </li> </ul>	213
An	swers to Problems	247
Lis	t of Major Symbols	293
Lis	t of Files on CD	301
Au	thor Index	305

**Subject Index**