

Contents

Chapter 1. Excitation and Nature of X-Rays and X-Ray Spectra

1.1. History	1
1.2. Definition	4
1.3. Properties	5
1.4. Units of Measurement	6
1.5. X-Ray Tubes	8
1.5.1. Conventional High-Power X-Ray Spectrometer Tubes	8
1.5.2. Other X-Ray Tubes	11
1.6. The Primary X-Ray Generator	12
1.6.1. Alternating Current	12
1.6.2. Transformers, Rectifiers, Filters	13
1.6.3. X-Ray Tube Power Supply	16
1.6.3.1. AC-Line Input	16
1.6.3.2. High-Potential Power Supply	16
1.6.3.3. X-Ray Tube Filament Supply	18
1.6.3.4. Operation	18
1.6.3.5. Stabilization	21
1.6.3.6. Safety and Protective Devices	22
1.7. The Continuous Spectrum	23
1.8. The Characteristic Line Spectrum	26
1.8.1. Atomic Structure	26
1.8.2. Origin and Nature	34
1.8.3. Notation	38
1.8.4. Wavelength and Photon Energy	39
1.8.5. Intensity	43
1.8.6. Electron (Primary) Excitation	46
1.8.7. X-Ray (Secondary, "Fluorescence") Excitation	48
1.8.7.1. Principles	48
1.8.7.2. Relationship of Absorption Edges and Spectral-Line Series	50
1.8.7.3. Excitation with Polychromatic X-Rays	51
1.8.7.4. Comparison of Primary and Secondary Excitation	53
1.8.8. Other Excitation Modes	55
Suggested Reading	58

Chapter 2. Properties of X-Rays

2.1. X-Ray Absorption	59
2.1.1. Mass-Absorption Coefficients	59
2.1.2. X-Ray Absorption Phenomena	61
2.1.3. Absorption Edges	62
2.1.4. X-Ray Cross Section	65
2.1.5. Comparison of X-Ray and Optical Absorption	65
2.1.6. Significance of X-Ray Absorption	67
2.1.7. The Inverse-Square Law	67
2.2. X-Ray Scatter	68
2.3. X-Ray Diffraction by Crystals	71
2.3.1. The Bragg Law	71
2.3.2. Miller Indexes (<i>hkl</i>)	74
2.4. Auger Effect; Fluorescent Yield	78
Suggested Reading	81

Chapter 3. X-Ray Emission Spectrometric Analysis: General Introduction

3.1. Nomenclature	83
3.2. Introduction	84
3.3. Wavelength-Dispersive X-Ray Spectrometry	87
3.3.1. Principle	87
3.3.2. Basic Instrument and Method	87
3.3.3. Manual, Semiautomatic, and Automatic Spectrometers	91
3.3.3.1. Introduction	91
3.3.3.2. Sequential Automatic Spectrometers	93
3.3.3.3. Simultaneous Automatic Spectrometers.	97
3.3.3.4. Special Spectrometers	99
3.4. Energy-Dispersive X-Ray Spectrometry	101
3.4.1. Principle	101
3.4.2. Basic Instrument and Method	101
3.5. Appraisal of X-Ray Spectrometric Analysis	103
3.5.1. Scope	103
3.5.2. Advantages	104
3.5.3. Disadvantages and Limitations	110
3.5.4. Wavelength and Energy Dispersion Compared	113
3.6. Personnel Safety	115
Suggested Reading	119

Chapter 4. Excitation; Wavelength Dispersion

4.1. Excitation	121
4.1.1. Electron Excitation	121
4.1.2. Ion Excitation	122
4.1.3. Radioisotope Excitation	122

4.1.4.	X-Ray Tube Excitation (X-Ray “Fluorescence”)	126
4.1.4.1.	General	126
4.1.4.2.	Theory—Excitation Equations	128
4.1.4.3.	Practice—Operating Conditions	132
4.2.	Wavelength Dispersion	137
4.2.1.	Radiation Path	138
4.2.2.	Collimators	138
4.2.3.	Analyzer Crystals	140
4.2.3.1.	Introduction	140
4.2.3.2.	Features	140
4.2.3.3.	Other Wavelength-Dispersion Devices	149
4.2.3.4.	Curved-Crystal Spectrometers	152
4.2.4.	Spectrogoniometer Alignment	155
	Suggested Reading	157

Chapter 5. Detection and Readout; X-Ray Intensity Measurement

5.1.	X-Ray Detection	159
5.1.1.	Principles	159
5.1.2.	Pulse-Height Distributions	162
5.1.3.	Gas-Filled Detectors	164
5.1.3.1.	Structure	164
5.1.3.2.	Types of Gas-Filled Detectors; Gas Amplification	166
5.1.3.3.	Phenomena in the Detector Gas Volume	169
5.1.3.4.	Detector Output; Escape Peaks	172
5.1.4.	Scintillation Counters	173
5.1.5.	Lithium-Drifted Silicon Detectors	176
5.1.6.	Detector Characteristics	178
5.1.6.1.	Quantum Efficiency	179
5.1.6.2.	Plateau	179
5.1.6.3.	Dead Time	181
5.1.6.4.	Resolution	184
5.1.6.5.	Comparison of Detectors	187
5.2.	Readout Components	189
5.2.1.	Introduction	189
5.2.2.	Preamplifier and Amplifier	192
5.2.3.	Pulse-Height Selector	192
5.2.3.1.	Instrument and Principle	193
5.2.3.2.	Pulse-Height Distributions	194
5.2.3.3.	Pulse-Height Distribution Curves	197
5.2.3.4.	Pulse-Height Selector Settings	201
5.2.3.5.	Applications and Limitations	207
5.2.3.6.	Automatic Pulse-Height Selection	209
5.2.3.7.	Pulse-Height Selection Problems	212
5.2.4.	Ratemeter–Recorder	217
5.2.5.	Scaler–Timer	218
5.2.6.	Computer	220

5.3.	X-Ray Intensity Measurement	221
5.3.1.	Measurement Techniques	221
5.3.2.	Background	223
5.3.2.1.	Nature	223
5.3.2.2.	Measurement	224
5.3.2.3.	Reduction	226
	Suggested Reading	228

Chapter 6. Energy-Dispersive X-Ray Spectrometry

6.1.	Energy-Dispersive X-Ray Spectrometry	231
6.1.1.	Introduction	231
6.1.2.	Multichannel Pulse-Height Analyzer	232
6.1.3.	Instrument Functions	235
6.1.3.1.	General	235
6.1.3.2.	Spectrum Display and Labeling	237
6.1.3.3.	Spectrum Processing	242
6.1.3.4.	Quantitative Analysis.	245
6.2.	Nondispersive X-Ray Spectrometry	246
6.3.	Energy-Dispersive X-Ray Diffractometry-Spectrometry	248
	Suggested Reading	253

Chapter 7. Qualitative and Semiquantitative Analysis

7.1.	Qualitative Analysis	255
7.1.1.	Recording the Spectrum	256
7.1.2.	Identification of Peaks	261
7.1.2.1.	X-Ray Spectrometer Tables	261
7.1.2.2.	Identification of Peaks	269
7.2.	Semiquantitative Analysis	273
7.2.1.	General	273
7.2.2.	Comparison Analysis	275
	Suggested Reading	277

Chapter 8. Problems and Performance Criteria

8.1.	Sources of Error	279
8.2.	Matrix Effects	281
8.2.1.	Introduction	281
8.2.2.	Absorption-Enhancement Effects	282
8.2.2.1.	General	282
8.2.2.2.	Nonspecific Absorption Effects	284
8.2.2.3.	Specific Absorption-Enhancement Effects	287
8.2.2.4.	Secondary Absorption-Enhancement Effects	291
8.2.2.5.	Unusual Absorption-Enhancement Effects	292
8.2.3.	Surface-Texture, Particle-Size, and Heterogeneity Effects	294
8.3.	Spectral Interference	298

8.4. Precision	299
8.4.1. Definitions	299
8.4.2. Elementary Statistics	301
8.4.3. Counting Error	305
8.4.4. Counting Strategy and Figure of Merit	310
8.4.5. Analytical Precision	313
8.5. Sensitivity	316
8.6. Resolution	322
Suggested Reading	325

Chapter 9. Quantitative Analysis

9.1. Introduction	327
9.2. Calibration-Standard Methods	331
9.2.1. General Method	331
9.2.2. Special Calibration Methods	334
9.3. Internal-Standardization Methods	338
9.3.1. Internal-Standard Method	338
9.3.2. Other Standardization Methods	343
9.4. Standardization with Scattered X-Rays	344
9.5. Matrix-Dilution Methods	348
9.6. Thin-Film Methods	351
9.7. Standard Addition and Dilution Methods	353
9.8. Miscellaneous Experimental Correction Methods	355
9.9. Mathematical Correction Methods	357
9.9.1. Geometric Methods	358
9.9.2. Empirical-Correction Methods	360
9.9.3. Absorption-Correction Methods	366
9.9.4. Influence-Coefficient Methods	368
9.9.5. Variable-Takeoff-Angle Method	373
9.9.6. Fundamental-Parameters Method	376
9.9.7. Multiple-Regression Method	380
9.10. Films and Platings	381
9.11. Trace and Micro Analysis	386
Suggested Reading	389

Chapter 10. Specimen Preparation and Presentation

10.1. Introduction	393
10.2. Specimen Forms	396
10.3. Standards	397
10.3.1. Permanence	397
10.3.2. Sources	398
10.4. Solids	401
10.4.1. Scope, Advantages, Limitations	401
10.4.2. Presentation	402
10.4.3. Preparation	403

10.5. Powders and Briquets	405
10.5.1. Scope, Advantages, Limitations	405
10.5.2. Preparation	407
10.5.3. Precautions	409
10.6. Fusion Products	411
10.7. Liquids	413
10.7.1. Scope, Advantages, Limitations	413
10.7.2. Liquid-Specimen Cells	415
10.8. Supported Specimens	419
10.8.1. General Techniques	419
10.8.2. Ion-Exchange Techniques	423
10.9. Special Specimen Forms	426
10.9.1. Selected-Area Analysis	426
10.9.2. Radioactive Specimens	434
10.9.3. Dynamic Systems	435
10.9.4. Gases and Vapors	435
Suggested Reading	436
Chapter 11. Electron-Probe Microanalysis	
11.1. Introduction	439
11.2. Instrumentation	440
11.3. Interaction of the Electron Beam and Specimen	444
11.4. Modes of Readout and Display	446
11.4.1. Cathode-Ray Tube Displays	446
11.4.1.1. The Cathode-Ray Tube	448
11.4.1.2. Line and Raster Scanning	450
11.4.1.3. Deflection Modulation Displays	451
11.4.1.4. Intensity Modulation Displays	453
11.4.2. Measurement at a Point	453
11.4.3. Measurement along a Line	454
11.4.4. Measurement over a Raster	456
11.4.5. Color Displays	461
11.5. Specimen Considerations	462
11.6. Quantitative Analysis	464
11.7. Performance	468
11.8. Applications	469
11.9. Comparison with X-Ray Fluorescence Spectrometry	470
Suggested Reading	473
Index	475