

Contents

| | |
|---|-----------|
| Preface | v |
| 1. Principles and Techniques | 1 |
| 1.1. Design: Basic Principles and Techniques | 1 |
| 1.1.1. The Art of Experimentation | 1 |
| 1.1.2. Replication | 2 |
| 1.1.3. Blocking | 3 |
| 1.1.4. Randomization | 3 |
| 1.2. Analysis: Basic Principles and Techniques | 5 |
| 2. Planning Experiments | 7 |
| 2.1. Introduction | 7 |
| 2.2. A Checklist for Planning Experiments | 7 |
| 2.3. A Real Experiment—Cotton-Spinning Experiment | 14 |
| 2.4. Some Standard Experimental Designs | 17 |
| 2.4.1. Completely Randomized Designs | 18 |
| 2.4.2. Block Designs | 18 |
| 2.4.3. Designs with Two or More Blocking Factors | 19 |
| 2.4.4. Split-Plot Designs | 21 |
| 2.5. More Real Experiments | 22 |
| 2.5.1. Soap Experiment | 22 |
| 2.5.2. Battery Experiment | 26 |
| 2.5.3. Cake-Baking Experiment | 29 |
| Exercises | 31 |
| 3. Designs with One Source of Variation | 33 |
| 3.1. Introduction | 33 |
| 3.2. Randomization | 34 |
| 3.3. Model for a Completely Randomized Design | 35 |
| 3.4. Estimation of Parameters | 37 |

| | | |
|--------|--|----|
| 3.4.1. | Estimable Functions of Parameters | 37 |
| 3.4.2. | Notation | 37 |
| 3.4.3. | Obtaining Least Squares Estimates | 38 |
| 3.4.4. | Properties of Least Squares Estimators | 40 |
| 3.4.5. | Estimation of σ^2 | 42 |
| 3.4.6. | Confidence Bound for σ^2 | 43 |
| 3.5. | One-Way Analysis of Variance | 44 |
| 3.5.1. | Testing Equality of Treatment Effects | 44 |
| 3.5.2. | Use of p -Values | 48 |
| 3.6. | Sample Sizes | 49 |
| 3.6.1. | Expected Mean Squares for Treatments | 50 |
| 3.6.2. | Sample Sizes Using Power of a Test | 51 |
| 3.7. | A Real Experiment—Soap Experiment, Continued | 53 |
| 3.7.1. | Checklist, Continued | 53 |
| 3.7.2. | Data Collection and Analysis | 54 |
| 3.7.3. | Discussion by the Experimenter | 56 |
| 3.7.4. | Further Observations by the Experimenter | 56 |
| 3.8. | Using SAS Software | 57 |
| 3.8.1. | Randomization | 57 |
| 3.8.2. | Analysis of Variance | 58 |
| | Exercises | 61 |

4. Inferences for Contrasts and Treatment Means 67

| | | |
|--------|--|----|
| 4.1. | Introduction | 67 |
| 4.2. | Contrasts | 68 |
| 4.2.1. | Pairwise Comparisons | 69 |
| 4.2.2. | Treatment Versus Control | 70 |
| 4.2.3. | Difference of Averages | 70 |
| 4.2.4. | Trends | 71 |
| 4.3. | Individual Contrasts and Treatment Means | 73 |
| 4.3.1. | Confidence Interval for a Single Contrast | 73 |
| 4.3.2. | Confidence Interval for a Single Treatment Mean | 75 |
| 4.3.3. | Hypothesis Test for a Single Contrast or Treatment Mean | 75 |
| 4.4. | Methods of Multiple Comparisons | 78 |
| 4.4.1. | Multiple Confidence Intervals | 78 |
| 4.4.2. | Bonferroni Method for Preplanned Comparisons | 80 |
| 4.4.3. | Scheffé Method of Multiple Comparisons | 83 |
| 4.4.4. | Tukey Method for All Pairwise Comparisons | 85 |
| 4.4.5. | Dunnnett Method for Treatment-Versus-Control Comparisons | 87 |
| 4.4.6. | Hsu Method for Multiple Comparisons with the Best Treatment | 89 |
| 4.4.7. | Combination of Methods | 91 |
| 4.4.8. | Methods Not Controlling Experimentwise Error Rate | 92 |

| | | |
|-----------|---|------------|
| 4.5. | Sample Sizes | 92 |
| 4.6. | Using SAS Software | 94 |
| 4.6.1. | Inferences on Individual Contrasts | 94 |
| 4.6.2. | Multiple Comparisons | 96 |
| | Exercises | 97 |
| 5. | Checking Model Assumptions | 103 |
| 5.1. | Introduction | 103 |
| 5.2. | Strategy for Checking Model Assumptions | 104 |
| 5.2.1. | Residuals | 104 |
| 5.2.2. | Residual Plots | 105 |
| 5.3. | Checking the Fit of the Model | 107 |
| 5.4. | Checking for Outliers | 107 |
| 5.5. | Checking Independence of the Error Terms | 109 |
| 5.6. | Checking the Equal Variance Assumption | 111 |
| 5.6.1. | Detection of Unequal Variances | 112 |
| 5.6.2. | Data Transformations to Equalize Variances | 113 |
| 5.6.3. | Analysis with Unequal Error Variances | 116 |
| 5.7. | Checking the Normality Assumption | 119 |
| 5.8. | Using SAS Software | 122 |
| 5.8.1. | Using SAS to Generate Residual Plots | 122 |
| 5.8.2. | Transforming the Data | 126 |
| | Exercises | 127 |
| 6. | Experiments with Two Crossed Treatment Factors | 135 |
| 6.1. | Introduction | 135 |
| 6.2. | Models and Factorial Effects | 136 |
| 6.2.1. | The Meaning of Interaction | 136 |
| 6.2.2. | Models for Two Treatment Factors | 138 |
| 6.2.3. | Checking the Assumptions on the Model | 140 |
| 6.3. | Contrasts | 141 |
| 6.3.1. | Contrasts for Main Effects and Interactions | 141 |
| 6.3.2. | Writing Contrasts as Coefficient Lists | 143 |
| 6.4. | Analysis of the Two-Way Complete Model | 145 |
| 6.4.1. | Least Squares Estimators for the Two-Way Complete Model | 146 |
| 6.4.2. | Estimation of σ^2 for the Two-Way Complete Model | 147 |
| 6.4.3. | Multiple Comparisons for the Complete Model | 149 |
| 6.4.4. | Analysis of Variance for the Complete Model | 152 |
| 6.5. | Analysis of the Two-Way Main-Effects Model | 158 |
| 6.5.1. | Least Squares Estimators for the Main-Effects Model | 158 |
| 6.5.2. | Estimation of σ^2 in the Main-Effects Model | 162 |
| 6.5.3. | Multiple Comparisons for the Main-Effects Model | 163 |
| 6.5.4. | Unequal Variances | 165 |

| | | |
|-----------|---|------------|
| 6.5.5. | Analysis of Variance for Equal Sample Sizes | 165 |
| 6.5.6. | Model Building | 168 |
| 6.6. | Calculating Sample Sizes | 168 |
| 6.7. | Small Experiments | 169 |
| 6.7.1. | One Observation per Cell | 169 |
| 6.7.2. | Analysis Based on Orthogonal Contrasts | 169 |
| 6.7.3. | Tukey's Test for Additivity | 172 |
| 6.7.4. | A Real Experiment—Air Velocity Experiment | 173 |
| 6.8. | Using SAS Software | 175 |
| 6.8.1. | Contrasts and Multiple Comparisons | 177 |
| 6.8.2. | Plots | 181 |
| 6.8.3. | One Observation per Cell | 182 |
| | Exercises | 183 |
| 7. | Several Crossed Treatment Factors | 193 |
| 7.1. | Introduction | 193 |
| 7.2. | Models and Factorial Effects | 194 |
| 7.2.1. | Models | 194 |
| 7.2.2. | The Meaning of Interaction | 195 |
| 7.2.3. | Separability of Factorial Effects | 197 |
| 7.2.4. | Estimation of Factorial Contrasts | 199 |
| 7.3. | Analysis—Equal Sample Sizes | 201 |
| 7.4. | A Real Experiment—Popcorn—Microwave Experiment | 205 |
| 7.5. | One Observation per Cell | 211 |
| 7.5.1. | Analysis Assuming That Certain Interaction Effects Are Negligible | 211 |
| 7.5.2. | Analysis Using Normal Probability Plot of Effect Estimates | 213 |
| 7.5.3. | Analysis Using Confidence Intervals | 215 |
| 7.6. | Design for the Control of Noise Variability | 217 |
| 7.6.1. | Analysis of Design-by-Noise Interactions | 218 |
| 7.6.2. | Analyzing the Effects of Design Factors on Variability | 221 |
| 7.7. | Using SAS Software | 223 |
| 7.7.1. | Normal Probability Plots of Contrast Estimates | 224 |
| 7.7.2. | Voss—Wang Confidence Interval Method | 224 |
| 7.7.3. | Identification of Robust Factor Settings | 226 |
| 7.7.4. | Experiments with Empty Cells | 227 |
| | Exercises | 231 |
| 8. | Polynomial Regression | 243 |
| 8.1. | Introduction | 243 |
| 8.2. | Models | 244 |
| 8.3. | Least Squares Estimation (Optional) | 248 |
| 8.3.1. | Normal Equations | 248 |

| | | |
|------------|---|------------|
| 8.3.2. | Least Squares Estimates for Simple Linear Regression | 248 |
| 8.4. | Test for Lack of Fit | 249 |
| 8.5. | Analysis of the Simple Linear Regression Model | 251 |
| 8.6. | Analysis of Polynomial Regression Models | 255 |
| 8.6.1. | Analysis of Variance | 255 |
| 8.6.2. | Confidence Intervals | 257 |
| 8.7. | Orthogonal Polynomials and Trend Contrasts (Optional) | 258 |
| 8.7.1. | Simple Linear Regression | 258 |
| 8.7.2. | Quadratic Regression | 260 |
| 8.7.3. | Comments | 261 |
| 8.8. | A Real Experiment—Bean-Soaking Experiment | 262 |
| 8.8.1. | Checklist | 262 |
| 8.8.2. | One-Way Analysis of Variance and Multiple Comparisons | 264 |
| 8.8.3. | Regression Analysis | 267 |
| 8.9. | Using SAS Software | 268 |
| | Exercises | 273 |
| 9. | Analysis of Covariance | 277 |
| 9.1. | Introduction | 277 |
| 9.2. | Models | 278 |
| 9.2.1. | Checking Model Assumptions and Equality of Slopes | 279 |
| 9.2.2. | Model Extensions | 279 |
| 9.3. | Least Squares Estimates | 280 |
| 9.3.1. | Normal Equations (Optional) | 280 |
| 9.3.2. | Least Squares Estimates and Adjusted Treatment Means | 281 |
| 9.4. | Analysis of Covariance | 282 |
| 9.5. | Treatment Contrasts and Confidence Intervals | 286 |
| 9.5.1. | Individual Confidence Intervals | 286 |
| 9.5.2. | Multiple Comparisons | 287 |
| 9.6. | Using SAS Software | 288 |
| | Exercises | 292 |
| 10. | Complete Block Designs | 295 |
| 10.1. | Introduction | 295 |
| 10.2. | Blocks, Noise Factors or Covariates? | 296 |
| 10.3. | Design Issues | 297 |
| 10.3.1. | Block Sizes | 297 |
| 10.3.2. | Complete Block Design Definitions | 298 |
| 10.3.3. | The Randomized Complete Block Design | 299 |
| 10.3.4. | The General Complete Block Design | 300 |
| 10.3.5. | How Many Observations? | 301 |
| 10.4. | Analysis of Randomized Complete Block Designs | 301 |
| 10.4.1. | Model and Analysis of Variance | 301 |

| | |
|---|-----|
| 10.4.2. Multiple Comparisons | 305 |
| 10.5. A Real Experiment—Cotton-Spinning Experiment | 306 |
| 10.5.1. Design Details | 306 |
| 10.5.2. Sample-Size Calculation | 307 |
| 10.5.3. Analysis of the Cotton-Spinning Experiment | 307 |
| 10.6. Analysis of General Complete Block Designs | 309 |
| 10.6.1. Model and Analysis of Variance | 309 |
| 10.6.2. Multiple Comparisons for the General Complete Block Design | 312 |
| 10.6.3. Sample-Size Calculations | 315 |
| 10.7. Checking Model Assumptions | 316 |
| 10.8. Factorial Experiments | 317 |
| 10.9. Using SAS Software | 320 |
| Exercises | 324 |

11. Incomplete Block Designs 339

| | |
|---|-----|
| 11.1. Introduction | 339 |
| 11.2. Design Issues | 340 |
| 11.2.1. Block Sizes | 340 |
| 11.2.2. Design Plans and Randomization | 340 |
| 11.2.3. Estimation of Contrasts (Optional) | 342 |
| 11.2.4. Balanced Incomplete Block Designs | 343 |
| 11.2.5. Group Divisible Designs | 345 |
| 11.2.6. Cyclic Designs | 346 |
| 11.3. Analysis of General Incomplete Block Designs | 348 |
| 11.3.1. Contrast Estimators and Multiple Comparisons | 348 |
| 11.3.2. Least Squares Estimation (Optional) | 351 |
| 11.4. Analysis of Balanced Incomplete Block Designs | 354 |
| 11.4.1. Multiple Comparisons and Analysis of Variance | 354 |
| 11.4.2. A Real Experiment—Detergent Experiment | 355 |
| 11.5. Analysis of Group Divisible Designs | 360 |
| 11.5.1. Multiple Comparisons and Analysis of Variance | 360 |
| 11.6. Analysis of Cyclic Designs | 362 |
| 11.7. A Real Experiment—Plasma Experiment | 362 |
| 11.8. Sample Sizes | 368 |
| 11.9. Factorial Experiments | 369 |
| 11.9.1. Factorial Structure | 369 |
| 11.10. Using SAS Software | 372 |
| 11.10.1. Analysis of Variance and Estimation of Contrasts | 372 |
| 11.10.2. Plots | 377 |
| Exercises | 378 |

| | |
|---|------------|
| 12. Designs with Two Blocking Factors | 387 |
| 12.1. Introduction | 387 |
| 12.2. Design Issues | 388 |
| 12.2.1. Selection and Randomization of Row–Column Designs | 388 |
| 12.2.2. Latin Square Designs | 389 |
| 12.2.3. Youden Designs | 391 |
| 12.2.4. Cyclic and Other Row–Column Designs | 392 |
| 12.3. Model for a Row–Column Design | 394 |
| 12.4. Analysis of Row–Column Designs (Optional) | 395 |
| 12.4.1. Least Squares Estimation (Optional) | 395 |
| 12.4.2. Solution for Complete Column Blocks (Optional) | 397 |
| 12.4.3. Formula for ssE (Optional) | 398 |
| 12.4.4. Analysis of Variance for a Row–Column Design (Optional) | 399 |
| 12.4.5. Confidence Intervals and Multiple Comparisons | 401 |
| 12.5. Analysis of Latin Square Designs | 401 |
| 12.5.1. Analysis of Variance for Latin Square Designs | 401 |
| 12.5.2. Confidence Intervals for Latin Square Designs | 403 |
| 12.5.3. How Many Observations? | 405 |
| 12.6. Analysis of Youden Designs | 406 |
| 12.6.1. Analysis of Variance for Youden Designs | 406 |
| 12.6.2. Confidence Intervals for Youden Designs | 407 |
| 12.6.3. How Many Observations? | 407 |
| 12.7. Analysis of Cyclic and Other Row–Column Designs | 408 |
| 12.8. Checking the Assumptions on the Model | 409 |
| 12.9. Factorial Experiments in Row–Column Designs | 410 |
| 12.10. Using SAS Software | 410 |
| 12.10.1. Factorial Model | 413 |
| 12.10.2. Plots | 415 |
| Exercises | 415 |
| 13. Confounded Two-Level Factorial Experiments | 421 |
| 13.1. Introduction | 421 |
| 13.2. Single replicate factorial experiments | 422 |
| 13.2.1. Coding and notation | 422 |
| 13.2.2. Confounding | 422 |
| 13.2.3. Analysis | 423 |
| 13.3. Confounding Using Contrasts | 424 |
| 13.3.1. Contrasts | 424 |
| 13.3.2. Experiments in Two Blocks | 425 |
| 13.3.3. Experiments in Four Blocks | 430 |
| 13.3.4. Experiments in Eight Blocks | 432 |
| 13.3.5. Experiments in More Than Eight Blocks | 433 |

| | |
|---|------------|
| 13.4. Confounding Using Equations | 433 |
| 13.4.1. Experiments in Two Blocks | 433 |
| 13.4.2. Experiments in More Than Two Blocks | 435 |
| 13.5. A Real Experiment—Mangold Experiment | 437 |
| 13.6. Plans for Confounded 2^p Experiments | 441 |
| 13.7. Multireplicate Designs | 441 |
| 13.8. Complete Confounding: Repeated Single-Replicate Designs | 442 |
| 13.8.1. A Real Experiment—Decontamination Experiment | 442 |
| 13.9. Partial Confounding | 446 |
| 13.10. Comparing the Multireplicate Designs | 449 |
| 13.11. Using SAS Software | 452 |
| Exercises | 454 |
| 14. Confounding in General Factorial Experiments | 461 |
| 14.1. Introduction | 461 |
| 14.2. Confounding with Factors at Three Levels | 462 |
| 14.2.1. Contrasts | 462 |
| 14.2.2. Confounding Using Contrasts | 463 |
| 14.2.3. Confounding Using Equations | 464 |
| 14.2.4. A Real Experiment—Dye Experiment | 467 |
| 14.2.5. Plans for Confounded 3^p Experiments | 470 |
| 14.3. Designing Using Pseudofactors | 471 |
| 14.3.1. Confounding in 4^p Experiments | 471 |
| 14.3.2. Confounding in $2^p \times 4^q$ Experiments | 472 |
| 14.4. Designing Confounded Asymmetrical Experiments | 472 |
| 14.5. Using SAS Software | 475 |
| Exercises | 477 |
| 15. Fractional Factorial Experiments | 483 |
| 15.1. Introduction | 483 |
| 15.2. Fractions from Block Designs; Factors with 2 Levels | 484 |
| 15.2.1. Half-Fractions of 2^p Experiments; 2^{p-1} Experiments | 484 |
| 15.2.2. Resolution and Notation | 487 |
| 15.2.3. A Real Experiment—Soup Experiment | 487 |
| 15.2.4. Quarter-Fractions of 2^p Experiments; 2^{p-2} Experiments | 490 |
| 15.2.5. Smaller Fractions of 2^p Experiments | 494 |
| 15.3. Fractions from Block Designs; Factors with 3 Levels | 496 |
| 15.3.1. One-Third Fractions of 3^p Experiments; 3^{p-1} Experiments | 496 |
| 15.3.2. One-Ninth Fractions of 3^p Experiments; 3^{p-2} Experiments | 501 |
| 15.4. Fractions from Block Designs; Other Experiments | 501 |
| 15.4.1. $2^p \times 4^q$ Experiments | 501 |
| 15.4.2. $2^p \times 3^q$ Experiments | 502 |
| 15.5. Blocked Fractional Factorial Experiments | 503 |

| | |
|---|------------|
| 15.6. Fractions from Orthogonal Arrays | 506 |
| 15.6.1. 2^p Orthogonal Arrays | 506 |
| 15.6.2. Saturated Designs | 512 |
| 15.6.3. $2^p \times 4^q$ Orthogonal Arrays | 513 |
| 15.6.4. 3^p Orthogonal Arrays | 514 |
| 15.7. Design for the Control of Noise Variability | 515 |
| 15.7.1. A Real Experiment—Inclinometer Experiment | 516 |
| 15.8. Using SAS Software | 521 |
| 15.8.1. Fractional Factorials | 521 |
| 15.8.2. Design for the Control of Noise Variability | 524 |
| Exercises | 529 |
| 16. Response Surface Methodology | 547 |
| 16.1. Introduction | 547 |
| 16.2. First-Order Designs and Analysis | 549 |
| 16.2.1. Models | 549 |
| 16.2.2. Standard First-Order Designs | 551 |
| 16.2.3. Least Squares Estimation | 552 |
| 16.2.4. Checking Model Assumptions | 553 |
| 16.2.5. Analysis of Variance | 553 |
| 16.2.6. Tests for Lack of Fit | 554 |
| 16.2.7. Path of Steepest Ascent | 559 |
| 16.3. Second-Order Designs and Analysis | 561 |
| 16.3.1. Models and Designs | 561 |
| 16.3.2. Central Composite Designs | 562 |
| 16.3.3. Generic Test for Lack of Fit of the Second-Order Model | 564 |
| 16.3.4. Analysis of Variance for a Second-Order Model | 564 |
| 16.3.5. Canonical Analysis of a Second-Order Model | 566 |
| 16.4. Properties of Second-Order Designs: CCDs | 569 |
| 16.4.1. Rotatability | 569 |
| 16.4.2. Orthogonality | 570 |
| 16.4.3. Orthogonal Blocking | 571 |
| 16.5. A Real Experiment: Flour Production Experiment, Continued | 573 |
| 16.6. Box–Behnken Designs | 576 |
| 16.7. Using SAS Software | 579 |
| 16.7.1. Analysis of a Standard First-Order Design | 579 |
| 16.7.2. Analysis of a Second-Order Design | 582 |
| Exercises | 586 |
| 17. Random Effects and Variance Components | 593 |
| 17.1. Introduction | 593 |
| 17.2. Some Examples | 594 |
| 17.3. One Random Effect | 596 |

| | |
|---|-----|
| 17.3.1. The Random-Effects One-Way Model | 596 |
| 17.3.2. Estimation of σ^2 | 597 |
| 17.3.3. Estimation of σ^2_{τ} | 598 |
| 17.3.4. Testing Equality of Treatment Effects | 601 |
| 17.3.5. Confidence Intervals for Variance Components | 603 |
| 17.4. Sample Sizes for an Experiment with One Random Effect | 607 |
| 17.5. Checking Assumptions on the Model | 610 |
| 17.6. Two or More Random Effects | 610 |
| 17.6.1. Models and Examples | 610 |
| 17.6.2. Checking Model Assumptions | 613 |
| 17.6.3. Estimation of σ^2 | 613 |
| 17.6.4. Estimation of Variance Components | 614 |
| 17.6.5. Confidence Intervals for Variance Components | 616 |
| 17.6.6. Hypothesis Tests for Variance Components | 620 |
| 17.6.7. Sample Sizes | 622 |
| 17.7. Mixed Models | 622 |
| 17.7.1. Expected Mean Squares and Hypothesis Tests | 622 |
| 17.7.2. Confidence Intervals in Mixed Models | 625 |
| 17.8. Rules for Analysis of Random and Mixed Models | 627 |
| 17.8.1. Rules—Equal Sample Sizes | 627 |
| 17.8.2. Controversy (Optional) | 628 |
| 17.9. Block Designs and Random Blocking Factors | 630 |
| 17.10. Using SAS Software | 632 |
| 17.10.1. Checking Assumptions on the Model | 632 |
| 17.10.2. Estimation and Hypothesis Testing | 635 |
| Exercises | 639 |

18. Nested Models 645

| | |
|---|-----|
| 18.1. Introduction | 645 |
| 18.2. Examples and Models | 646 |
| 18.3. Analysis of Nested Fixed Effects | 648 |
| 18.3.1. Least Squares Estimates | 648 |
| 18.3.2. Estimation of σ^2 | 649 |
| 18.3.3. Confidence Intervals | 650 |
| 18.3.4. Hypothesis Testing | 650 |
| 18.4. Analysis of Nested Random Effects | 654 |
| 18.4.1. Expected Mean Squares | 654 |
| 18.4.2. Estimation of Variance Components | 656 |
| 18.4.3. Hypothesis Testing | 657 |
| 18.4.4. Some Examples | 658 |
| 18.5. Using SAS Software | 662 |
| 18.5.1. Voltage Experiment | 662 |
| Exercises | 667 |

| | |
|--|------------|
| 19. Split-Plot Designs | 675 |
| 19.1. Introduction | 675 |
| 19.2. Designs and Models | 676 |
| 19.3. Analysis of a Split-Plot Design with Complete Blocks | 678 |
| 19.3.1. Split-Plot Analysis | 678 |
| 19.3.2. Whole-Plot Analysis | 680 |
| 19.3.3. Contrasts Within and Between Whole Plots | 681 |
| 19.3.4. A Real Experiment—Oats Experiment | 681 |
| 19.4. Split-Split-Plot Designs | 684 |
| 19.5. Split-Plot Confounding | 686 |
| 19.6. Using SAS Software | 687 |
| Exercises | 691 |
| | |
| A. Tables | 695 |
| | |
| Bibliography | 725 |
| | |
| Index of Authors | 731 |
| | |
| Index of Experiments | 733 |
| | |
| Index of Subjects | 735 |