

## Contents

**Preface** *IX*

**Acknowledgments** *XIII*

<b>1</b>	<b>Fundamentals of Crystalline Materials</b>	<b>1</b>
1.1	Crystalline State	1
1.2	Fundamentals of Geometrical Crystallography	12
1.2.1	Crystal Lattices	12
1.2.2	Crystal Axes Systems, Crystal Systems, and Crystal Families	14
1.2.3	Crystal Faces and Zones	15
1.2.4	Indexing in the Hexagonal Crystal Family	24
1.3	Morphological Symmetry of Crystals	25
1.3.1	Crystallographic Point Groups	40
1.3.2	Some Basic Facts of Group Theory	52
1.4	Structural Symmetry	60
1.4.1	Crystal Lattices, Motifs, and Crystal Structures	60
1.4.1.1	Bravais Lattices	61
1.4.1.2	The Reciprocal Lattice	62
1.4.1.3	Lattice Transformations	68
1.4.2	Crystallographic Space Groups	71
1.4.2.1	General Remarks	72
1.4.2.2	The International Tables for Crystallography – The Reference Book for the Representation of Space Group Symmetries	76
1.4.2.3	Mathematical Description of the Space Group Symmetry	93
1.4.3	Generalized Crystallographic Symmetry	101
1.5	Crystal Structures	104
1.5.1	Sphere Packings	108
1.5.2	Selected Examples of Inorganic Structure Types	112
1.5.2.1	Polymorphism and Polytypism	124
1.5.3	Selected Examples of Molecular Crystals	126
1.5.4	Symmetry Relations between Crystal Structures	145

1.6	Crystallographic Databases and Crystallographic Computer Programs 152
	Appendix: Supplementary Material S1 Special Crystal Forms of Cubic Crystal Classes 159
	References 164
<b>2</b>	<b>Basics of Growth Mechanism and Solidification 171</b>
2.1	Nucleation Processes 171
2.1.1	Homogeneous Nucleation 175
2.1.2	Heterogeneous Nucleation 177
2.1.3	Metastable Zone Regime 179
2.1.4	Equilibrium Shape of Crystals 180
2.2	Kinetic Processes and Growth Mechanism 182
2.2.1	Molecular Kinetic Theory of Crystal Growth 183
2.2.2	Interfaces and Roughening of Surfaces 185
2.2.3	Vapor–Liquid–Solid (VLS) Mechanism 189
2.2.4	Crystal Growth from Ambient Phases on Rough Surfaces: Vapor Phase, Solution, and Melt Media 190
2.2.5	Crystal Growth on Flat Surfaces 193
2.3	Phase Diagrams and Principles of Segregation 195
2.3.1	Phase Diagrams with a Continuous Miscibility in the Solid and Liquid Phases 196
2.3.2	Segregation and Segregation Coefficients 201
2.3.3	Constitutional Supercooling and Morphological Stability 212
2.4	Principles of Flow Regimes in Growth Melts 214
2.4.1	Buoyancy Convection 215
2.4.2	Marangoni Convection 216
	References 218
<b>3</b>	<b>Growth Techniques in Correlation with Related Growth Mechanism 221</b>
3.1	Overview on Main Growth Techniques 221
3.2	Principles of Melt Growth Techniques 224
3.2.1	The Czochralski Crystal Growth Process 224
3.2.2	Growth Method after Bridgman 234
3.2.3	The Float Zone Crystal Growth Process 244
3.2.4	Bulk Crystal Growth from Metallic Solutions 253
3.2.4.1	Traveling Solvent Method (TSM) 253
3.2.4.2	Traveling Heater Method (THM) 255
3.2.4.3	The Solute, Synthesis, Diffusion Method (SSD) 259
3.3	Bulk Crystal Growth of II–VI Compounds from the Vapor 260
3.3.1	Crystal Growth of CdTe by a Sublimation Traveling Heater Method, STHM, in Closed Ampoules 262
3.3.2	Crystal Growth of CdTe by the Markov Method in Semiclosed Ampoules 264

3.4	Epitaxial Growth Techniques	267
3.4.1	Liquid Phase Epitaxy (LPE)	270
3.4.2	Vapor Phase Epitaxy (VPE)	279
3.5	Supplementary Material: Principles of Verneuil Technique, Growth from High and Low Temperature, Nonmetallic Solutions	295
3.5.1	Verneuil Technique	295
3.5.2	Growth from High Temperature Solutions (Flux Growth)	295
3.5.3	Growth from Low Temperature Solutions (Aqueous Solutions)	296
	References	298
<b>4</b>	<b>Characterization of Crystals</b>	<b>301</b>
4.1	Crystal Defects	302
4.1.1	Zero-Dimensional Defects	303
4.1.2	One-Dimensional Defects	314
4.1.3	Two-Dimensional Defects (Planar Defects)	326
4.1.3.1	Grain Boundaries	328
4.1.3.2	Stacking Faults	336
4.1.3.3	Antiphase Boundaries	340
4.1.3.4	Twins	342
4.1.3.5	Domain Boundaries	355
4.1.3.6	Crystal Surfaces	363
4.1.4	Three-Dimensional defects	368
4.1.4.1	Inclusions	369
4.1.4.2	Precipitates	370
4.1.4.3	Voids	374
4.2	Crystal Quality	375
4.2.1	Criteria of Crystal Quality	376
4.2.2	Crystal Quality and Application	378
4.3	Selected Methods of Crystal Characterization	382
4.3.1	Etching of Crystals	382
4.3.2	X-Ray Topography	383
4.3.3	Electron Microscopy	385
4.3.3.1	Scanning Electron Microscopy	387
4.3.3.2	Transmission Electron Microscopy	388
4.4	Materials Engineering by Correlation of Crystal Growth and Characterization	392
	<i>Anna Mogilatenko</i>	
4.4.1	Epitaxial Growth of GaN on LiAlO <sub>2</sub> Substrates	393
	References	408
	<b>Index</b>	<b>415</b>