

# Contents

Page

<b>1. Raw materials for electric steelmaking</b> . . . . .	1
1.1 Feedstocks . . . . .	1
1.2 Fluxes . . . . .	3
Fluidizing agents . . . . .	4
Refining agents . . . . .	5
Carburizing agents . . . . .	5
Slag reducing agents . . . . .	6
1.3 Additions . . . . .	6
Deoxidation and alloying agents . . . . .	7
<b>2. Energy</b> . . . . .	14
2.1 Electric energy . . . . .	14
2.2 Water . . . . .	16
2.3 Steam . . . . .	17
2.4 Compressed air . . . . .	17
<b>3. Oxygen</b> . . . . .	18
<b>4. Fuels</b> . . . . .	19
4.1 Gaseous fuels . . . . .	19
4.2 Liquid fuels . . . . .	19
4.3 Solid fuels . . . . .	19
<b>5. Refractories</b> . . . . .	21
5.1 Evaluation of refractory materials . . . . .	21
5.2 Refractories for electric steelmaking . . . . .	22
Dolomite products . . . . .	22
Magnesite products . . . . .	24
Fire clay products . . . . .	25
Silica products . . . . .	26
High – alumina products . . . . .	26
Special refractories . . . . .	27
Insulating materials . . . . .	27
<b>6. Residual materials from steelmaking in electric arc furnaces</b> . . . . .	28
<b>7. Plant and equipment for the production of liquid crude steel by the electric arc furnace process</b> . . . . .	30
7.1 Scrap yard and scrap bay . . . . .	31
7.2 Scrap preheating plants . . . . .	34
7.3 Storage and transport of fluxes, additions, and sponge iron . . . . .	37
Storage and transport of fluxes . . . . .	37
Storage and transport of alloys . . . . .	38
Storage and transport of sponge iron . . . . .	40

7.4	Melting bay . . . . .	41
7.5.	Electric arc furnace plant including auxiliaries and ancillaries . . . . .	42
	Bottom section of furnace . . . . .	44
	Top section or superstructure of furnace . . . . .	45
	Furnace shell . . . . .	49
	Energy supply . . . . .	55
	Graphite electrodes . . . . .	58
	Electrode regulator . . . . .	61
	Electro-magnetic stirrer . . . . .	62
	Oxygen lances . . . . .	64
	Jet burners . . . . .	65
	Furnace control centre . . . . .	66
	Electrode nipple stand . . . . .	67
	Equipment for roof relining . . . . .	69
7.6	High-power electric arc furnaces . . . . .	70
7.7	Rapid melting method and foaming slag practice . . . . .	72
7.8	Dedusting equipment . . . . .	73
7.9	Sludge handling . . . . .	77
7.10	Dust handling . . . . .	78
7.11	Slag handling . . . . .	78
7.12	Means of transport in the meltshop . . . . .	79
<b>8.</b>	<b>Equipment for vacuum treatment of liquid crude steel and other aftertreatment techniques . . . . .</b>	<b>81</b>
8.1	Degassing during tapping . . . . .	82
8.2	Ladle stand degassing . . . . .	82
8.3	Ladle degassing in small batches . . . . .	83
	Vacuum lift process . . . . .	83
	Circulation degassing . . . . .	84
8.4	Stream degassing . . . . .	85
	Ladle-to-ladle degassing . . . . .	85
	Ladle-to-ingot degassing . . . . .	85
8.5	Ladle refining, alloying, and reheating equipment . . . . .	86
	Ladle stirring . . . . .	86
	Degassing, alloying, and reheating equipment . . . . .	87
	Vacuum refining facilities . . . . .	88
8.6	AOD process . . . . .	89
<b>9.</b>	<b>Plant and equipment for steel teeming or casting . . . . .</b>	<b>91</b>
9.1	Casting bay including auxiliaries and ancillaries . . . . .	91
	Equipment for liquid steel transport in the casting bay . . . . .	91
	Casting platforms and casting pits . . . . .	92
	Moulds, stool plates, trumpets, and bottom plates . . . . .	92
	Equipment for mould and ingot transport in the casting bay . . . . .	94
	Equipment for relining and maintenance of ladles . . . . .	94
	Stopper drying furnaces . . . . .	95
	Trumpet drying facilities . . . . .	95
	Equipment for upkeep and maintenance of moulds, bottom plates, trumpets, and stool plates . . . . .	95

9.2	Continuous casting machines . . . . .	96
9.3	Controlled high-pressure pouring plant . . . . .	99
<b>10.</b>	<b>Auxiliaries and ancillaries . . . . .</b>	<b>101</b>
10.1	Brick store . . . . .	101
10.2	Beneficiation plant for residuals . . . . .	101
<b>11.</b>	<b>Monitoring equipment in electric steelmaking . . . . .</b>	<b>102</b>
11.1	Weighing of solids and liquids . . . . .	102
11.2	Temperature measurement . . . . .	103
11.3	Sampling and determination of steel composition . . . . .	105
11.4	Automation of steelmaking in electric arc furnaces . . . . .	107
<b>12.</b>	<b>Physical and chemical process in electric arc furnace steelmaking . . . . .</b>	<b>109</b>
12.1	Generation of electric arc . . . . .	109
12.2	Heat emission and transfer to charge materials, molten steel, and slag in electric arc furnaces . . . . .	109
12.3	Significance of gaseous oxygen to steelmaking in electric arc furnaces . . . . .	110
12.4	Reactions during refining in the oxidizing phase . . . . .	111
12.5	Reducing, refining in the reducing phase, and deoxidizing . . . . .	113
12.6	Build-up and remelting processes . . . . .	115
<b>13.</b>	<b>Physical and chemical processes during solidification of liquid steel in the mould . . . . .</b>	<b>116</b>
13.1	Physical processes during solidification of liquid steel in the mould . . . . .	116
13.2	Chemical processes during solidification of liquid steel in the mould . . . . .	117
<b>14.</b>	<b>Operations in electric steelshops . . . . .</b>	<b>121</b>
14.1	Operations on the scrap yard and in the scrap bay . . . . .	121
14.2	Handling and storage of fluxes and additions . . . . .	122
14.3	Operations in the melting bay . . . . .	122
	Operations during the melting procedure . . . . .	122
	Troubles during melting . . . . .	125
	Upkeep and maintenance of electric arc furnaces . . . . .	126
	Slipping, exchange, and joining of graphite electrodes . . . . .	128
14.3	Refractory lining of electric arc furnaces . . . . .	129
	Hearth lining techniques . . . . .	129
	Side wall relining techniques . . . . .	131
	Roof relining techniques . . . . .	133
14.4	Operations in the teeming bay . . . . .	135
	Relining and maintenance of teeming ladles . . . . .	135
	Ladle closing devices . . . . .	138
	Manufacture of stopper rods . . . . .	138
	Manufacture of slide gates . . . . .	139
	Preparation of teeming ladles for the teeming procedure . . . . .	141
	Teeming ladles with stopper rod system . . . . .	141
	Teeming ladles with slide gate systems . . . . .	142
	Lining for stool plates . . . . .	142

Relining of trumpets . . . . .	143
Upkeep and maintenance of moulds and accessoires . . . . .	144
Positioning of moulds . . . . .	147
Positioning of moulds for top teeming (downhill) . . . . .	147
Positioning of moulds for group teeming (uphill) . . . . .	147
Positioning for forging ingot moulds . . . . .	148
Teeming of a heat into ingots and potential defects arising during that procedure . . . . .	148
Ingot cooling times, stripping, and loading . . . . .	153
Troubles during ingot teeming . . . . .	154
14.5 Casting of a heat in a continuous caster . . . . .	155
Casting of a heat into a strand and potential defects resulting therefrom . . . . .	155
Casting troubles in continuous casting . . . . .	157
14.6 Casting of heats in a controlled high-pressure pouring facility . . . . .	157
<b>15. Steel standards . . . . .</b>	<b>159</b>
<b>16. Protection of labour in electric arc furnace steelshops . . . . .</b>	<b>161</b>
<b>Definitions of technical terms . . . . .</b>	<b>166</b>
<b>References . . . . .</b>	<b>170</b>