

Contents

Preface	xi
Acknowledgements	xiii
Chapter1 Cutting-tool technology	1
1.1 An introduction to cutting-tool technology	1
1.2 The evolution of cutting-tool materials	5
1.3 The classification of carbide inserts	11
1.4 Milling techniques, insert geometry and forces	13
1.5 Turning geometries, forces and insert selection	18
1.6 The principles of chip breaking	26
1.6.1 Swarf problems and remedies	26
1.6.2 The chip thickness	28
1.6.3 Chip curvature	28
1.6.4 The chip-breaker	28
1.6.5 The helical formation of chips	29
1.6.6 Chip-breaker designs	29
1.7 Drilling technology – an introduction	33
1.8 Drill insert design and types of drill	33
1.9 Thread manufacture – an introduction	38
1.10 Threads produced by metal-cutting methods	39
1.10.1 Thread tapping	39
1.10.2 Thread milling	40
1.10.3 Thread turning	42
1.11 Parting-off and grooving	49
1.12 Specialised tooling	52
Chapter2 Modular quick-change cutting-tool systems	57
2.1 Tooling requirements of turning centres	58
2.1.1 Design and development of quick-change tooling	63
2.2 Tooling requirements of machining centres	70
2.3 Tool changing using an automatic tool-changing mechanism and tool-holders	73
2.3.1 Automatic tool-changing mechanisms on turning centres	75
Chapter3 Workpiece and tool-monitoring systems for CNC machine tools	79
3.1 Workpiece-monitoring systems	80
3.1.1 Identification of the workpiece	80
3.1.2 Automatic set-up of the workpiece	82
3.1.3 Gauging of the workpiece	82

3.2	Tool-condition monitoring on turning centres	86
3.2.1	Tool identification	86
3.2.2	Tool-offset measurement	88
3.2.3	Tool-life monitoring	89
3.2.4	Tool-breakage detection	89
3.3	Case studies on tool-condition monitoring on turning and machining centres	92
3.3.1	Tool monitoring using feed-force sensors—strain gauges	92
3.3.2	Monitoring for tool breakage, wear and collisions using piezoelectric sensors	100
3.3.3	Tool-condition monitoring using the acoustic emission principle	106
3.4	Adaptive control on turning and machining centres	107
3.4.1	The benefits to be gained from using adaptive control	108
3.4.2	The design of an adaptive control system	109
3.5	Condition-monitoring systems for stand-alone machines and flexible manufacturing systems	111
Chapter 4 Tool management		115
4.1	Creating a tool-management and documentation database	118
4.1.1	Production requirements	118
4.1.2	Perishable and capital equipment	119
4.1.3	The workforce	120
4.1.1.4	The 'history' of a manufacturing system	120
4.1.5	Designing components for production	122
4.1.6	Further aspects of tool management	122
4.2	Building up the tool file	123
4.3	Methods used in the presetting of tools	126
4.3.1	Presetting tools off the machine tool	126
4.3.2	Presetting tools on the machine tool	128
4.4	The tool store and presetting facility—a typical system	131
4.4.1	Machine-tool spindle cleaning	132
4.5	Tool-recognition systems—using 'intelligent' tooling	134
4.6	Computerised tool management	140
4.6.1	The TOMAS computerised tool-management system	140
4.7	Tool location and inventory rules	143
4.8	The overall benefits of a tool-management system	145
Chapter 5 Cutting and grinding fluids		147
5.1	Why use a cutting fluid?	147
5.2	The 'ideal' cutting fluid	148
5.3	Types of cutting fluid	150
5.3.1	Hand-applied lubricants	150
5.3.2	Flood-applied lubricants	151
5.4	Application methods	154
5.5	Selection	155
5.5.1	The workpiece material	155
5.5.2	The cutting operation	156
5.5.3	The machine tool	156
5.5.4	The condition of the water supply	156
5.6	Problems	157
5.6.1	Bacteria and fungus problems	157
5.6.2	Problems of dilution control	158
5.6.3	Problems of product selection	158
5.7	Care and control	158
5.7.1	Storage	158
5.7.2	Preparation of the emulsion	158

5.7.3	Machine cleaning	161
5.7.4	Maintenance of the fluid during use	161
5.7.5	Disposal	163
5.8	Health and safety	164
5.8.1	Product Health and Safety Information Sheets	164
5.8.2	Formulation of the product	164
5.8.3	Hazard labelling	165
5.8.4	Dilution control	166
5.8.5	Emulsion-condition monitoring	166
5.8.6	Health and Safety Executive publications	166
Chapter 6 The machinability and surface integrity of engineering components		167
6.1	Test methods used for assessing machinability	168
6.1.1	Machining tests	168
6.1.2	Non-machining tests	171
6.2	The mechanics of metal cutting	173
6.3	Chip formation	174
6.3.1	The continuous chip	174
6.3.2	The continuous chip with built-up edge	175
6.3.3	The discontinuous chip	177
6.4	Tool chatter and its effect on chip morphology	177
6.5	Tool wear – a tribological condition	180
6.5.1	The effect of tool temperature on tool wear	181
6.5.2	The mechanisms of wear on the tool	183
6.5.3	Tool life	186
6.6	The use of cutting fluids during machining operations	190
6.6.1	Using a high-velocity coolant system for improved chip control and disposal	192
6.7	The economics of machining	195
6.7.1	Machining costs	195
6.7.2	Machining components economically	196
6.7.3	Maximum-production machining	197
6.7.4	The improved return on the investment	198
6.8	Surface integrity	198
6.8.1	Methods used for assessing surface integrity	199
6.8.2	Surfaces produced by milling	200
6.8.3	Surfaces produced by turning	204
6.8.4	Some aspects of the drilling process	206
6.9	Surface-texture parameters – a means of defining a machined surface	211
6.10	The surface condition after machining	214
6.11	Metrological equipment used for assessing machined surfaces	217
6.11.1	Inexpensive and relatively unsophisticated methods	217
6.11.2	Highly sophisticated instruments	218
6.11.3	The latest technology – almost a complete measuring system	222
6.12	A treated steel with ‘ideal’ machining characteristics	223
6.13	Metal-matrix composites – the challenge for the future	225
Appendix A Turning troubleshooting		227
Turning operations with carbide tooling		227
Threading operations using carbide tooling		229
Parting-off operations		232
Vibrations produced in turning operations		234
Surface-finish problems in turning operations		235
Appendix B Turning data determination		237
The machine power requirement		237

Appendix C Milling troubleshooting	241
Milling operations with carbide tooling	241
Vibrations produced in milling operations	244
Surface-finish problems in milling operations.....	245
Appendix D Milling data determination	247
The machine power requirement	247
The cutting forces in milling	249
Speed conversion chart.....	250
Appendix E Drilling troubleshooting	251
Delta short-hole drilling	251
'U' short-hole drilling	252
Trepanning operations.....	255
Appendix F Cutting speeds using carbide inserts—a basic guide	259
Appendix G Hardness conversion table	263
Appendix H The characterisation of chip forms	265
Appendix I Standards relating to tooling for CNC machining and turning centres	267
Bibliography	269
Company addresses	271
Index.....	275