

Contents

1	Introduction to Additive Manufacturing	1
1.1	What Is Additive Manufacturing?	1
1.2	The Additive Manufacturing Process Chain	4
1.3	Current Usage of Additive Manufacturing	7
1.4	The Advantages of Additive Manufacturing	8
1.4.1	Part Complexity	8
1.4.2	Instant Assemblies	11
1.4.3	Part Consolidation	12
1.4.4	Mass Customization	13
1.4.5	Freedom of Design	13
1.4.6	Light-Weighting	14
1.4.7	On-Demand Manufacturing	16
2	Additive Manufacturing Technologies	19
2.1	Material Extrusion	19
2.2	Material Jetting	23
2.3	Binder Jetting	25
2.4	Sheet Lamination	28
2.5	Vat Photopolymerisation	30
2.6	Powder Bed Fusion	33
2.7	Direct Energy Deposition	35
2.8	Hybrid AM	37
2.9	AM Technology Readiness Level for Part Production	38
3	DfAM Strategic Design Considerations	41
3.1	Introduction to Design for Additive Manufacturing	41
3.2	Using AM to Add Value to Products	43
3.3	General Guidelines for Designing AM Parts	43
3.3.1	The #1 Rule of Design for AM	43
3.3.2	The #2 Rule of Design for AM	44

3.3.3	The #3 Rule of Design for AM	45
3.3.4	The #4 Rule of Design for AM	45
3.3.5	The #5 Rule of Design for AM	45
3.3.6	The #6 Rule of Design for AM	46
3.3.7	The #7 Rule of Design for AM	47
3.4	Design to Avoid Anisotropy	47
3.5	The Economics of Additive Manufacturing	48
3.5.1	Time Factors That Are Not Affected by Design	51
3.6	Design to Minimize Print Time	52
3.7	Design to Minimize Post-processing	56
3.8	Take Advantage of Design Complexity	64
3.9	Function First, Materials Second	66
3.10	Use Topology Optimisation or Lattice Structures	67
4	Computational Tools for Design Analysis and Optimisation of AM Parts	71
4.1	Aims of Using Design Analysis for AM	71
4.2	Special Considerations for Analysis of AM Parts	71
4.2.1	Material Data	71
4.2.2	Surface Finish	72
4.2.3	Geometry	72
4.2.4	Simplifying Geometry	72
4.2.5	Mesh-Based Versus Parametric Models	73
4.2.6	Geometry Distortion	73
4.3	Mesh	73
4.3.1	Parametric Models	73
4.3.2	Mesh-Based Models	74
4.4	Boundary Conditions	74
4.5	Optimisation	74
4.6	Topology Optimisation	74
4.6.1	Objective and Constraints	75
4.6.2	Common Settings	75
4.6.3	Post-processing and Interpreting Results	75
4.7	Parametric or Size Optimisation	76
4.8	Build Process Simulation	76
4.8.1	Layer-by-Layer Simulation	77
4.8.2	Scan Pattern Simulation	77
4.8.3	Limitations	77
5	Guidelines for Part Consolidation	79
5.1	Design for Function	80
5.2	Material Considerations	81
5.3	Number of Fasteners	81
5.4	Use Knowledge from Conventional DFM/DFA	82

5.5	Assembly Considerations	83
5.6	Moving Parts	83
5.7	Common Sense	84
6	Guidelines for AM Tooling Design	85
6.1	Mounting Fixtures and Guides	85
6.2	Conformal Cooling	86
6.3	Coolant Flow Strategies	88
6.4	Coolant Channel Shape	89
6.5	Coolant Channel Spacing	90
6.6	A Hybrid Approach to AM Tooling	90
6.7	Minimise Print Time in Tooling	91
7	Design for Polymer AM	93
7.1	Anisotropy	93
7.2	Wall Thicknesses	94
7.3	Overhangs and Support Material	95
7.4	Holes	96
7.5	Ribs	97
7.6	Avoiding Superfluous Material	98
7.7	Font Sizes and Small Details	100
	7.7.1 Small Details	100
	7.7.2 Font Sizes	100
8	Polymer Design Guidelines	103
8.1	Designing for Material Extrusion	103
	8.1.1 Material Extrusion Accuracy and Tolerances	103
	8.1.2 Layer Thickness	104
	8.1.3 Support Material	104
	8.1.4 Fill Style	105
	8.1.5 Other Considerations	106
	8.1.6 Feature Type: Vertical Wall Thickness	107
	8.1.7 Feature Type: Horizontal Walls	107
	8.1.8 Feature Type: Support Material Overhang Angles	107
	8.1.9 Feature Type: Clearances Between Moving Parts with Soluble Supports	108
	8.1.10 Feature Type: Clearance Between Moving Parts with Break-Away Support Material	108
	8.1.11 Feature Type: Vertical Circular Holes	109
	8.1.12 Feature Type: Circular Pins	109
	8.1.13 Feature Type: Built-in Screw Threads	110
8.2	Designing for Polymer Powder Bed Fusion	110
	8.2.1 Powder Bed Fusion Accuracy and Tolerances	111
	8.2.2 Layer Thickness	111

8.2.3	Avoiding Large Masses of Material	111
8.2.4	Powder Age and Refresh Rate	112
8.2.5	Feature Type: Wall Thickness	112
8.2.6	Feature Type: Clearance Between Moving Parts	113
8.2.7	Feature Type: Circular Profile Through Holes	113
8.2.8	Feature Type: Square Profile Through Holes	114
8.2.9	Feature Type: Circular Pins	114
8.2.10	Feature Type: Hole Proximity to Wall Edge	115
8.3	Designing for Vat Photopolymerisation	115
8.3.1	Resolution	115
8.3.2	Print Orientation	116
8.3.3	Support Material	116
8.3.4	Overhangs	116
8.3.5	Isotropy	117
8.3.6	Hollowing Parts and Resin Removal	117
8.3.7	Details	118
8.3.8	Horizontal Bridges	118
8.3.9	Connections	118
8.3.10	Feature Type: Wall Thickness	118
8.3.11	Feature Type: Circular Holes	119
9	Design for Metal AM	121
9.1	Designing for Metal Powder Bed Fusion	121
9.2	The Basics of Powder Bed Fusion	122
9.3	Metal Powder Production	122
9.4	Powder Morphology (Ideal Powder Shape)	124
9.5	Powder Size Distribution	124
9.6	Other Powder Considerations	125
9.7	Metal AM Material Characteristics	125
9.8	Potential Defects in AM Materials	126
9.9	The Metal AM Process	128
9.9.1	Energy Density	130
9.10	Controlled Chaos	132
9.11	The Reality of Metal AM	132
9.12	Topology Optimisation	133
9.13	Lattice Structures	134
9.13.1	Lattice Structure Strut Diameters	137
9.14	Overhangs and Support Material	138
9.14.1	Printing Parts with Large Horizontal Surfaces	139
9.14.2	Angle for Support Material	141
9.14.3	Unsupported Angles, Overhangs, and Bridges	141
9.15	Residual Stress	143
9.15.1	Designing to Reduce Residual Stress	144
9.15.2	Designing to Minimize Residual Stress Example	145

9.16	Stress Concentrations	149
9.16.1	Designing to Reduce Stress Concentrations	149
9.17	Horizontal Holes.	150
9.18	Setting up a Metal AM Print Job	151
9.18.1	General Part Positioning Guidelines	152
10	Metal AM Guidelines	157
10.1	Design for Laser Powder Bed Fusion	157
10.1.1	Feature Type: Wall Thickness	157
10.1.2	Feature Type: Overhang Angle	158
10.1.3	Feature Type: Clearance Between Moving Parts.	158
10.1.4	Feature Type: Vertical Slots and Circular Holes	159
10.1.5	Feature Type: Vertical Bosses and Circular Pins	159
10.1.6	Feature Type: Built-In External Screw Threads	159
10.2	Design for Electron Beam Melting	160
10.2.1	Post Processing	161
10.2.2	Design Guidelines	162
10.2.3	Feature Type: Wall Thickness	164
10.2.4	Feature Type: Vertical Slots and Circular Holes	164
10.2.5	Feature Type: Clearances to Remove Powder	165
10.2.6	Feature Type: Screw and Threads	165
10.3	Designing for Metal Binder Jetting	166
10.3.1	Shrinkage	166
10.3.2	Part Density	167
10.3.3	The Most Important Design Rule for Metal Binder Jetting	168
10.3.4	Feature Type: Wall Thicknesses	171
10.3.5	Feature Type: Overhang	172
10.3.6	Feature Type: Holes	172
10.3.7	Feature Type: Salt-Shaker Holes	173
11	Other AM Considerations	175
11.1	Designer Machine Operator Cooperation	175
11.2	Health and Safety	176
11.2.1	Material Exposure	176
11.2.2	Gas Monitoring	176
11.2.3	Gas Exhaust.	177
11.2.4	Material Handling	177
11.2.5	Risk of Explosion	177
11.3	AM Part Certification	177
11.3.1	What Needs to Be Certified?.	178
12	Post-processing	181
12.1	Support Material Removal.	182
12.1.1	Polymer.	182
12.1.2	Metal.	187

- 12.2 Polymer Surface Treatments 191
 - 12.2.1 Vapour Smoothing 191
 - 12.2.2 Tumbling 194
 - 12.2.3 Dying 195
 - 12.2.4 Painting 196
 - 12.2.5 Using Textures 196
 - 12.2.6 Sand Blasting 197
 - 12.2.7 Machining 197
 - 12.2.8 Metalizing 198
 - 12.2.9 Wrapping 198
 - 12.2.10 Hydrographics 199
- 12.3 Metal Surface Treatments 199
 - 12.3.1 Shot-Peening 200
 - 12.3.2 Plasma Cleaning and Ion Beam Cleaning 200
 - 12.3.3 Machining and Grinding 201
 - 12.3.4 Abrasive Flow Machining 201
 - 12.3.5 Anodizing 202
 - 12.3.6 Plasma Spraying 202
 - 12.3.7 Plating and PVD 202
 - 12.3.8 Painting 203
- 12.4 Gluing and Welding AM Parts 204
- 12.5 Heat Treatment and Aging 204
 - 12.5.1 Residual Stress Relief 204
 - 12.5.2 Hot Isostatic Pressing (HIP) 205
 - 12.5.3 Case Hardening and Gas Nitride Treatment 206
- 13 The Future of Additive Manufacturing 209**
 - 13.1 Functionally Graded Materials 209
 - 13.2 Bioprinting 210
 - 13.3 Construction Applications 211
 - 13.4 Printed Electronics 212
 - 13.5 Nano Printing 214
 - 13.6 Food Printers 214
- 14 Concluding Remarks 217**
- Glossary of Terms 219**
- References and Further Reading 225**