

Contents

Abstract	viii
Kurzfassung	x
1 Introduction and State of the Art in Geometric Calibration of Machining Centers	1
1.1 Geometric errors of machining centers	2
1.1.1 Location errors	2
1.1.2 Number of axis location errors	4
1.1.3 Component errors	5
1.1.4 Interdependencies of geometric errors	7
1.2 State of the art in geometric machine tool calibration	9
1.2.1 Geometric measurements	9
1.2.2 Kinematic measurements	13
1.2.3 Model-based calibration	14
1.3 Deficiencies of the state of the art	16
2 Error Compensation by Spatial Grid Measurements	19
2.1 The “3D Ball Plate” artefact	20
2.1.1 Work principle and benefits of the artefact	21
2.1.2 Calibration of the artefact	24
2.1.3 Design details of the artefact	27
2.1.4 Uncertainty estimation for the artefact	31

2.2	The 3D probing system for machine tools	34
2.2.1	Work principle of the probing system	35
2.2.2	Probe calibration	35
2.2.3	Uncertainty estimation for the probing system	37
2.3	Characterization of "3D Ball Plate" calibrations	38
2.4	Measurement examples	40
2.4.1	Conventional 3-axes machining center	41
2.4.2	Space Error Compensation for the PKM Hexaglide	46
3	Identification of Error Interdependencies Effects	51
3.1	The 3D probing system for machine tools with rotary axes	52
3.1.1	Calibration and uncertainty estimation	52
3.1.2	Sphere center offset compensation	53
3.2	General kinematic modeling of a machining center	54
3.2.1	Kinematic transformation	54
3.2.2	Error modeling	55
3.3	Parameter uncertainty estimation	55
3.4	Error interdependencies effects on kinematic measurements	58
3.4.1	Error identification	58
3.4.2	Calibration example	58
3.5	Error interdependencies effects on model-based calibrations	61
3.5.1	Possibilities of dealing with geometric machine errors	61
3.5.2	Planning model-based calibration methods	62
3.5.3	Error identification	63
3.5.4	Evaluating the mathematical condition of a model-based calibration	64
3.5.5	Parameter uncertainty estimation of model-based calibration approaches with Monte-Carlo simulations	67
3.5.6	Experimental testing of the calibration quality	68
3.5.7	Calibration example: conventional 5-axes machining center	68

3.5.8 Calibration example: parallel kinematic Hexaglide	79
4 Conclusion and Outlook	102
4.1 Conclusion	102
4.2 Outlook	104
Appendix: Modeling of geometric errors	105
A.1 Modeling of geometric errors 5-axes machining centers	105
A.2 Modeling of geometric errors Hexaglide	109
Bibliography	119